

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-2/16/06	06BR0249-01	Southwest Area (sidewalk bridge level)	2/16/06	0.57	Mercury	EPA 324/1631	BRL	2/20/06	< 26.0	No	No	
TotalHg-ST2-2/16/06	06BR0249-02	Southeast Area (sidewalk bridge level)	2/16/06	0.57	Mercury	EPA 324/1631	BRL	2/20/06	< 26.0	No	No	
TotalHg-ST4-2/16/06	06BR0249-03	Northwest Area (street-level)	2/16/06	0.57	Mercury	EPA 324/1631	BRL	2/20/06	< 26.0	No	No	
TotalHg-ST5-2/16/06	06BR0249-04	Firehouse #10 (roof level)	2/16/06	0.64	Mercury	EPA 324/1631	BRL	2/20/06	< 23.0	No	No	
TotalHg-ST10-2/16/06	06BR0249-05	North Side Sidewalk Bridge	2/16/06	0.58	Mercury	EPA 324/1631	BRL	2/20/06	< 26.0	No	No	
TotalHg-ST11-2/16/06	06BR0249-06	90 Trinity Place (roof level)	2/16/06	0.58	Mercury	EPA 324/1631	BRL	2/20/06	< 26.0	No	No	
TotalHg-ST12-2/16/06	06BR0249-07	110 Greenwich Street (roof level)	2/16/06	0.58	Mercury	EPA 324/1631	BRL	2/20/06	< 26.0	No	No	
TotalHg-ST13-2/16/06	06BR0249-08	Marriott Hotel, 38th Floor (roof level)	2/16/06	0.57	Mercury	EPA 324/1631	BRL	2/20/06	< 26.0	No	No	
TotalHg-ST14-2/16/06	06BR0249-09	West Face - South end at corner (scaffolding level)	2/16/06	0.55	Mercury	EPA 324/1631	BRL	2/20/06	< 27.0	No	No	
TotalHg-ST15-2/16/06	06BR0249-10	South Face - East end at corner (scaffolding level)	2/16/06	0.55	Mercury	EPA 324/1631	BRL	2/20/06	< 27.0	No	No	
TotalHg-ST16-2/16/06	06BR0249-11	East Face - North end at corner (scaffolding level)	2/16/06	0.55	Mercury	EPA 324/1631	BRL	2/20/06	< 27.0	No	No	
TotalHg-ST17-2/16/06	06BR0249-12	North Face - West end at corner (scaffolding level)	2/16/06	0.55	Mercury	EPA 324/1631	BRL	2/20/06	< 27.0	No	No	
TotalHg-ST1-2/17/06	06BR0252-01	Southwest Area (sidewalk bridge level)	2/17/06	0.59	Mercury	EPA 324/1631	BRL	2/21/06	< 25.0	No	No	
TotalHg-ST2-2/17/06	06BR0252-02	Southeast Area (sidewalk bridge level)	2/17/06	0.59	Mercury	EPA 324/1631	BRL	2/21/06	< 25.0	No	No	
TotalHg-ST4-2/17/06	06BR0252-03	Northwest Area (street-level)	2/17/06	0.60	Mercury	EPA 324/1631	BRL	2/21/06	< 25.0	No	No	
TotalHg-ST5-2/17/06	06BR0252-04	Firehouse #10 (roof level)	2/17/06	0.50	Mercury	EPA 324/1631	BRL	2/21/06	< 30.0	No	No	
TotalHg-ST10-2/17/06	06BR0252-05	North Side Sidewalk Bridge	2/17/06	0.61	Mercury	EPA 324/1631	BRL	2/21/06	< 25.0	No	No	
TotalHg-ST11-2/17/06	06BR0252-06	90 Trinity Place (roof level)	2/17/06	0.60	Mercury	EPA 324/1631	BRL	2/21/06	< 25.0	No	No	
TotalHg-ST12-2/17/06	06BR0252-07	110 Greenwich Street (roof level)	2/17/06	0.60	Mercury	EPA 324/1631	BRL	2/21/06	< 25.0	No	No	
TotalHg-ST13-2/17/06	06BR0252-08	Marriott Hotel, 38th Floor (roof level)	2/17/06	0.61	Mercury	EPA 324/1631	BRL	2/21/06	< 25.0	No	No	
TotalHg-ST14-2/17/06	06BR0252-09	West Face - South end at corner (scaffolding level)	2/17/06	0.61	Mercury	EPA 324/1631	BRL	2/21/06	< 25.0	No	No	
TotalHg-ST15-2/17/06	06BR0252-10	South Face - East end at corner (scaffolding level)	2/17/06	0.62	Mercury	EPA 324/1631	BRL	2/21/06	< 24.0	No	No	
TotalHg-ST16-2/17/06	06BR0252-11	East Face - North end at corner (scaffolding level)	2/17/06	0.61	Mercury	EPA 324/1631	BRL	2/21/06	< 25.0	No	No	
TotalHg-ST17-2/17/06	06BR0252-12	North Face - West end at corner (scaffolding level)	2/17/06	0.60	Mercury	EPA 324/1631	BRL	2/21/06	< 25.0	No	No	
TotalHg-ST1-2/18/06	06BR0253-01	Southwest Area (sidewalk bridge level)	2/18/06	0.55	Mercury	EPA 324/1631	BRL	2/21/06	< 27.0	No	No	
TotalHg-ST2-2/18/06	06BR0253-02	Southeast Area (sidewalk bridge level)	2/18/06	0.54	Mercury	EPA 324/1631	BRL	2/21/06	< 28.0	No	No	
TotalHg-ST4-2/18/06	06BR0253-03	Northwest Area (street-level)	2/18/06	0.53	Mercury	EPA 324/1631	BRL	2/21/06	< 28.0	No	No	
TotalHg-ST5-2/18/06	06BR0253-04	Firehouse #10 (roof level)	2/18/06	0.57	Mercury	EPA 324/1631	BRL	2/21/06	< 26.0	No	No	
TotalHg-ST10-2/18/06	06BR0253-05	North Side Sidewalk Bridge	2/18/06	0.51	Mercury	EPA 324/1631	BRL	2/21/06	< 29.0	No	No	
TotalHg-ST11-2/18/06	06BR0253-06	90 Trinity Place (roof level)	2/18/06	0.56	Mercury	EPA 324/1631	BRL	2/21/06	< 27.0	No	No	
TotalHg-ST12-2/18/06	06BR0253-07	110 Greenwich Street (roof level)	2/18/06	0.56	Mercury	EPA 324/1631	BRL	2/21/06	< 27.0	No	No	
TotalHg-ST13-2/18/06	06BR0253-08	Marriott Hotel, 38th Floor (roof level)	2/18/06	0.54	Mercury	EPA 324/1631	BRL	2/21/06	< 28.0	No	No	
TotalHg-ST14-2/18/06	06BR0253-09	West Face - South end at corner (scaffolding level)	2/18/06	0.55	Mercury	EPA 324/1631	BRL	2/21/06	< 27.0	No	No	
TotalHg-ST16-2/18/06	06BR0253-11	East Face - North end at corner (scaffolding level)	2/18/06	0.54	Mercury	EPA 324/1631	BRL	2/21/06	< 28.0	No	No	
TotalHg-ST17-2/18/06	06BR0253-12	North Face - West end at corner (scaffolding level)	2/18/06	0.55	Mercury	EPA 324/1631	BRL	2/21/06	< 27.0	No	No	
TotalHg-ST1-2/19/06	06BR0254-01	Southwest Area (sidewalk bridge level)	2/19/06	0.57	Mercury	EPA 324/1631	BRL	2/21/06	< 26.0	No	No	
TotalHg-ST2-2/19/06	06BR0254-02	Southeast Area (sidewalk bridge level)	2/19/06	0.57	Mercury	EPA 324/1631	BRL	2/21/06	< 26.0	No	No	
TotalHg-ST4-2/19/06	06BR0254-03	Northwest Area (street-level)	2/19/06	0.56	Mercury	EPA 324/1631	BRL	2/21/06	< 27.0	No	No	
TotalHg-ST5-2/19/06	06BR0254-04	Firehouse #10 (roof level)	2/19/06	0.57	Mercury	EPA 324/1631	BRL	2/21/06	< 26.0	No	No	
TotalHg-ST11-2/19/06	06BR0254-05	90 Trinity Place (roof level)	2/19/06	0.57	Mercury	EPA 324/1631	BRL	2/21/06	< 26.0	No	No	
TotalHg-ST12-2/19/06	06BR0254-06	110 Greenwich Street (roof level)	2/19/06	0.54	Mercury	EPA 324/1631	BRL	2/21/06	< 28.0	No	No	
TotalHg-ST13-2/19/06	06BR0254-07	Marriott Hotel, 38th Floor (roof level)	2/19/06	0.57	Mercury	EPA 324/1631	BRL	2/21/06	< 26.0	No	No	
TotalHg-ST14-2/19/06	06BR0254-08	West Face - South end at corner (scaffolding level)	2/19/06	0.58	Mercury	EPA 324/1631	BRL	2/21/06	< 26.0	No	No	
TotalHg-ST15-2/19/06	06BR0254-09	South Face - East end at corner (scaffolding level)	2/19/06	0.58	Mercury	EPA 324/1631	BRL	2/21/06	< 26.0	No	No	
TotalHg-ST16-2/19/06	06BR0254-10	East Face - North end at corner (scaffolding level)	2/19/06	0.57	Mercury	EPA 324/1631	BRL	2/21/06	< 26.0	No	No	
TotalHg-ST17-2/19/06	06BR0254-11	North Face - West end at corner (scaffolding level)	2/19/06	0.55	Mercury	EPA 324/1631	BRL	2/21/06	< 27.0	No	No	

Notes:

1. The result for the mercury sample at Station 15 (South Face - East end at corner [scaffolding level]) on February 18, 2006 was not available due to loss of the sample during laboratory preparation.
2. Mercury sample at Station 10 (North Side (sidewalk bridge level)) on February 19, 2006 was not available for analysis on account of pump failure.