

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg - ST1-2/27/06	06BR0296-01	Southwest Area (sidewalk bridge level)	2/27/06	0.57	Mercury	EPA 324/1631	BRL	3/1/06	< 26.0	No	No	
TotalHg - ST2-2/27/06	06BR0296-02	Southeast Area (sidewalk bridge level)	2/27/06	0.57	Mercury	EPA 324/1631	BRL	3/1/06	< 26.0	No	No	
TotalHg - ST4-2/27/06	06BR0296-03	Northwest Area (street-level)	2/27/06	0.58	Mercury	EPA 324/1631	BRL	3/1/06	< 26.0	No	No	
TotalHg - ST5-2/27/06	06BR0296-04	Firehouse #10 (roof level)	2/27/06	0.57	Mercury	EPA 324/1631	BRL	3/1/06	< 26.0	No	No	
TotalHg - ST10-2/27/06	06BR0296-05	North Side Sidewalk Bridge	2/27/06	0.58	Mercury	EPA 324/1631	BRL	3/1/06	< 26.0	No	No	
TotalHg - ST100-2/27/06FD	06BR0296-13	Station 10 Field Duplicate	2/27/06	0.58	Mercury	EPA 324/1631	BRL	3/1/06	< 26.0	No	No	
TotalHg - ST11-2/27/06	06BR0296-06	90 Trinity Place (roof level)	2/27/06	0.56	Mercury	EPA 324/1631	BRL	3/1/06	< 27.0	No	No	
TotalHg - ST12-2/27/06	06BR0296-07	110 Greenwich Street (roof level)	2/27/06	0.55	Mercury	EPA 324/1631	BRL	3/1/06	< 27.0	No	No	
TotalHg - ST13-2/27/06	06BR0296-08	Marriott Hotel, 38th Floor (roof level)	2/27/06	0.57	Mercury	EPA 324/1631	BRL	3/1/06	< 26.0	No	No	
TotalHg - ST14-2/27/06	06BR0296-09	West Face - South end at corner (scaffolding level)	2/27/06	0.57	Mercury	EPA 324/1631	BRL	3/1/06	< 26.0	No	No	
TotalHg - ST15-2/27/06	06BR0296-10	South Face - East end at corner (scaffolding level)	2/27/06	0.56	Mercury	EPA 324/1631	BRL	3/1/06	< 26.0	No	No	
TotalHg - ST16-2/27/06	06BR0296-11	East Face - North end at corner (scaffolding level)	2/27/06	0.57	Mercury	EPA 324/1631	BRL	3/1/06	< 26.0	No	No	
TotalHg - ST17-2/27/06	06BR0296-12	North Face - West end at corner (scaffolding level)	2/27/06	0.56	Mercury	EPA 324/1631	BRL	3/1/06	< 27.0	No	No	
TotalHg-ST1-2/28/06	06BR0301-01	Southwest Area (sidewalk bridge level)	2/28/06	0.57	Mercury	EPA 324/1631	BRL	3/2/06	< 26.0	No	No	
TotalHg-ST2-2/28/06	06BR0301-02	Southeast Area (sidewalk bridge level)	2/28/06	0.57	Mercury	EPA 324/1631	BRL	3/2/06	< 26.0	No	No	
TotalHg-ST4-2/28/06	06BR0301-03	Northwest Area (street-level)	2/28/06	0.57	Mercury	EPA 324/1631	BRL	3/2/06	< 26.0	No	No	
TotalHg-ST5-2/28/06	06BR0301-04	Firehouse #10 (roof level)	2/28/06	0.57	Mercury	EPA 324/1631	BRL	3/2/06	< 26.0	No	No	
TotalHg-ST10-2/28/06	06BR0301-05	North Side Sidewalk Bridge	2/28/06	0.56	Mercury	EPA 324/1631	BRL	3/2/06	< 27.0	No	No	
TotalHg-ST11-2/28/06	06BR0301-06	90 Trinity Place (roof level)	2/28/06	0.57	Mercury	EPA 324/1631	BRL	3/2/06	< 26.0	No	No	
TotalHg-ST12-2/28/06	06BR0301-07	110 Greenwich Street (roof level)	2/28/06	0.57	Mercury	EPA 324/1631	BRL	3/2/06	< 26.0	No	No	
TotalHg-ST13-2/28/06	06BR0301-08	Marriott Hotel, 38th Floor (roof level)	2/28/06	0.57	Mercury	EPA 324/1631	BRL	3/2/06	< 26.0	No	No	
TotalHg-ST14-2/28/06	06BR0301-09	West Face - South end at corner (scaffolding level)	2/28/06	0.58	Mercury	EPA 324/1631	BRL	3/2/06	< 26.0	No	No	
TotalHg-ST15-2/28/06	06BR0301-10	South Face - East end at corner (scaffolding level)	2/28/06	0.58	Mercury	EPA 324/1631	BRL	3/2/06	< 26.0	No	No	
TotalHg-ST16-2/28/06	06BR0301-11	East Face - North end at corner (scaffolding level)	2/28/06	0.58	Mercury	EPA 324/1631	BRL	3/2/06	< 26.0	No	No	
TotalHg-ST17-2/28/06	06BR0301-12	North Face - West end at corner (scaffolding level)	2/28/06	0.58	Mercury	EPA 324/1631	BRL	3/2/06	< 26.0	No	No	