

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>												
TotalHg-ST1-3/15/06	06BR0394-01	Southwest Area (sidewalk bridge level)	3/15/06	0.59	Mercury	EPA 324/1631	BRL	3/17/06	< 25.0	No	No	
TotalHg-ST2-3/15/06	06BR0394-02	Southeast Area (sidewalk bridge level)	3/15/06	0.59	Mercury	EPA 324/1631	BRL	3/17/06	< 25.0	No	No	
TotalHg-ST4-3/15/06	06BR0394-03	Northwest Area (street-level)	3/15/06	0.57	Mercury	EPA 324/1631	BRL	3/17/06	< 26.0	No	No	
TotalHg-ST5-3/15/06	06BR0394-04	Firehouse #10 (roof level)	3/15/06	0.58	Mercury	EPA 324/1631	BRL	3/17/06	< 26.0	No	No	
TotalHg-ST10-3/15/06	06BR0394-05	North Side Sidewalk Bridge	3/15/06	0.56	Mercury	EPA 324/1631	BRL	3/17/06	< 27.0	No	No	
TotalHg-ST100-3/15/06FD	06BR0394-13	Station 10 Field Duplicate	3/15/06	0.55	Mercury	EPA 324/1631	BRL	3/17/06	< 27.0	No	No	
TotalHg-ST11-3/15/06	06BR0394-06	90 Trinity Place (roof level)	3/15/06	0.58	Mercury	EPA 324/1631	BRL	3/17/06	< 26.0	No	No	
TotalHg-ST12-3/15/06	06BR0394-07	110 Greenwich Street (roof level)	3/15/06	0.58	Mercury	EPA 324/1631	BRL	3/17/06	< 26.0	No	No	
TotalHg-ST13-3/15/06	06BR0394-08	Marriott Hotel, 38th Floor (roof level)	3/15/06	0.58	Mercury	EPA 324/1631	BRL	3/17/06	< 26.0	No	No	
TotalHg-ST14-3/15/06	06BR0394-09	West Face - South end at corner (scaffolding level)	3/15/06	0.57	Mercury	EPA 324/1631	BRL	3/17/06	< 26.0	No	No	
TotalHg-ST15-3/15/06	06BR0394-10	South Face - East end at corner (scaffolding level)	3/15/06	0.57	Mercury	EPA 324/1631	BRL	3/17/06	< 26.0	No	No	
TotalHg-ST16-3/15/06	06BR0394-11	East Face - North end at corner (scaffolding level)	3/15/06	0.58	Mercury	EPA 324/1631	BRL	3/17/06	< 26.0	No	No	
TotalHg-ST17-3/15/06	06BR0394-12	North Face - West end at corner (scaffolding level)	3/15/06	0.58	Mercury	EPA 324/1631	BRL	3/17/06	< 26.0	No	No	
TotalHg-ST1-3/16/06	06BR0400-01	Southwest Area (sidewalk bridge level)	3/16/06	0.54	Mercury	EPA 324/1631	BRL	3/18/06	< 28.0	No	No	
TotalHg-ST2-3/16/06	06BR0400-02	Southeast Area (sidewalk bridge level)	3/16/06	0.55	Mercury	EPA 324/1631	BRL	3/18/06	< 27.0	No	No	
TotalHg-ST4-3/16/06	06BR0400-03	Northwest Area (street-level)	3/16/06	0.57	Mercury	EPA 324/1631	BRL	3/18/06	< 26.0	No	No	
TotalHg-ST5-3/16/06	06BR0400-04	Firehouse #10 (roof level)	3/16/06	0.57	Mercury	EPA 324/1631	BRL	3/18/06	< 26.0	No	No	
TotalHg-ST10-3/16/06	06BR0400-05	North Side Sidewalk Bridge	3/16/06	0.57	Mercury	EPA 324/1631	BRL	3/18/06	< 26.0	No	No	
TotalHg-ST100-3/16/06FD	06BR0400-13	Station 10 Field Duplicate	3/16/06	0.56	Mercury	EPA 324/1631	BRL	3/18/06	< 26.0	No	No	
TotalHg-ST11-3/16/06	06BR0400-06	90 Trinity Place (roof level)	3/16/06	0.57	Mercury	EPA 324/1631	BRL	3/18/06	< 26.0	No	No	
TotalHg-ST12-3/16/06	06BR0400-07	110 Greenwich Street (roof level)	3/16/06	0.57	Mercury	EPA 324/1631	BRL	3/18/06	< 26.0	No	No	
TotalHg-ST13-3/16/06	06BR0400-08	Marriott Hotel, 38th Floor (roof level)	3/16/06	0.55	Mercury	EPA 324/1631	BRL	3/18/06	< 27.0	No	No	
TotalHg-ST14-3/16/06	06BR0400-09	West Face - South end at corner (scaffolding level)	3/16/06	0.56	Mercury	EPA 324/1631	BRL	3/18/06	< 27.0	No	No	
TotalHg-ST15-3/16/06	06BR0400-10	South Face - East end at corner (scaffolding level)	3/16/06	0.56	Mercury	EPA 324/1631	BRL	3/18/06	< 27.0	No	No	
TotalHg-ST16-3/16/06	06BR0400-11	East Face - North end at corner (scaffolding level)	3/16/06	0.55	Mercury	EPA 324/1631	BRL	3/18/06	< 27.0	No	No	
TotalHg-ST17-3/16/06	06BR0400-12	North Face - West end at corner (scaffolding level)	3/16/06	0.57	Mercury	EPA 324/1631	BRL	3/18/06	< 26.0	No	No	