

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-3/17/06	06BR0407-01	Southwest Area (sidewalk bridge level)	3/17/06	0.57	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST2-3/17/06	06BR0407-02	Southeast Area (sidewalk bridge level)	3/17/06	0.57	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST4-3/17/06	06BR0407-03	Northwest Area (street-level)	3/17/06	0.55	Mercury	EPA 324/1631	BRL	3/21/06	< 27.0	No	No	
TotalHg-ST5-3/17/06	06BR0407-04	Firehouse #10 (roof level)	3/17/06	0.56	Mercury	EPA 324/1631	BRL	3/21/06	< 27.0	No	No	
TotalHg-ST10-3/17/06	06BR0407-05	North Side Sidewalk Bridge	3/17/06	0.58	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST100-3/17/06FD	06BR0407-13	Station 10 Field Duplicate	3/17/06	0.60	Mercury	EPA 324/1631	BRL	3/21/06	< 25.0	No	No	
TotalHg-ST11-3/17/06	06BR0407-06	90 Trinity Place (roof level)	3/17/06	0.59	Mercury	EPA 324/1631	BRL	3/21/06	< 25.0	No	No	
TotalHg-ST12-3/17/06	06BR0407-07	110 Greenwich Street (roof level)	3/17/06	0.59	Mercury	EPA 324/1631	BRL	3/21/06	< 25.0	No	No	
TotalHg-ST13-3/17/06	06BR0407-08	Marriott Hotel, 38th Floor (roof level)	3/17/06	0.59	Mercury	EPA 324/1631	BRL	3/21/06	< 25.0	No	No	
TotalHg-ST14-3/17/06	06BR0407-09	West Face - South end at corner (scaffolding level)	3/17/06	0.56	Mercury	EPA 324/1631	BRL	3/21/06	< 27.0	No	No	
TotalHg-ST15-3/17/06	06BR0407-10	South Face - East end at corner (scaffolding level)	3/17/06	0.56	Mercury	EPA 324/1631	BRL	3/21/06	< 27.0	No	No	
TotalHg-ST16-3/17/06	06BR0407-11	East Face - North end at corner (scaffolding level)	3/17/06	0.57	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST17-3/17/06	06BR0407-12	North Face - West end at corner (scaffolding level)	3/17/06	0.56	Mercury	EPA 324/1631	BRL	3/21/06	< 27.0	No	No	
TotalHg-ST1-3/18/06	06BR0408-01	Southwest Area (sidewalk bridge level)	3/18/06	0.59	Mercury	EPA 324/1631	BRL	3/21/06	< 25.0	No	No	
TotalHg-ST2-3/18/06	06BR0408-02	Southeast Area (sidewalk bridge level)	3/18/06	0.59	Mercury	EPA 324/1631	BRL	3/21/06	< 25.0	No	No	
TotalHg-ST4-3/18/06	06BR0408-03	Northwest Area (street-level)	3/18/06	0.58	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST5-3/18/06	06BR0408-04	Firehouse #10 (roof level)	3/18/06	0.58	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST10-3/18/06	06BR0408-05	North Side Sidewalk Bridge	3/18/06	0.58	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST11-3/18/06	06BR0408-06	90 Trinity Place (roof level)	3/18/06	0.57	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST12-3/18/06	06BR0408-07	110 Greenwich Street (roof level)	3/18/06	0.57	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST13-3/18/06	06BR0408-08	Marriott Hotel, 38th Floor (roof level)	3/18/06	0.56	Mercury	EPA 324/1631	BRL	3/21/06	< 27.0	No	No	
TotalHg-ST14-3/18/06	06BR0408-09	West Face - South end at corner (scaffolding level)	3/18/06	0.59	Mercury	EPA 324/1631	BRL	3/21/06	< 25.0	No	No	
TotalHg-ST15-3/18/06	06BR0408-10	South Face - East end at corner (scaffolding level)	3/18/06	0.59	Mercury	EPA 324/1631	BRL	3/21/06	< 25.0	No	No	
TotalHg-ST16-3/18/06	06BR0408-11	East Face - North end at corner (scaffolding level)	3/18/06	0.59	Mercury	EPA 324/1631	BRL	3/21/06	< 25.0	No	No	
TotalHg-ST17-3/18/06	06BR0408-12	North Face - West end at corner (scaffolding level)	3/18/06	0.59	Mercury	EPA 324/1631	BRL	3/21/06	< 25.0	No	No	
TotalHg-ST1-3/19/06	06BR0409-01	Southwest Area (sidewalk bridge level)	3/19/06	0.58	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST2-3/19/06	06BR0409-02	Southeast Area (sidewalk bridge level)	3/19/06	0.58	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST4-3/19/06	06BR0409-03	Northwest Area (street-level)	3/19/06	0.59	Mercury	EPA 324/1631	BRL	3/21/06	< 25.0	No	No	
TotalHg-ST5-3/19/06	06BR0409-04	Firehouse #10 (roof level)	3/19/06	0.57	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST10-3/19/06	06BR0409-05	North Side Sidewalk Bridge	3/19/06	0.58	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST11-3/19/06	06BR0409-06	90 Trinity Place (roof level)	3/19/06	0.55	Mercury	EPA 324/1631	BRL	3/21/06	< 27.0	No	No	
TotalHg-ST12-3/19/06	06BR0409-07	110 Greenwich Street (roof level)	3/19/06	0.56	Mercury	EPA 324/1631	BRL	3/21/06	< 27.0	No	No	
TotalHg-ST13-3/19/06	06BR0409-08	Marriott Hotel, 38th Floor (roof level)	3/19/06	0.56	Mercury	EPA 324/1631	BRL	3/21/06	< 27.0	No	No	
TotalHg-ST14-3/19/06	06BR0409-09	West Face - South end at corner (scaffolding level)	3/19/06	0.57	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST15-3/19/06	06BR0409-10	South Face - East end at corner (scaffolding level)	3/19/06	0.57	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST16-3/19/06	06BR0409-11	East Face - North end at corner (scaffolding level)	3/19/06	0.57	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	
TotalHg-ST17-3/19/06	06BR0409-12	North Face - West end at corner (scaffolding level)	3/19/06	0.57	Mercury	EPA 324/1631	BRL	3/21/06	< 26.0	No	No	