

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-4/28/06	06BR0634-01	Southwest Area (sidewalk bridge level)	4/28/06	0.57	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST2-4/28/06	06BR0634-02	Southeast Area (sidewalk bridge level)	4/28/06	0.57	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST4-4/28/06	06BR0634-03	Northwest Area (street-level)	4/28/06	0.56	Mercury	EPA 324/1631	BRL	5/2/06	< 27.0	No	No	
TotalHg-ST5-4/28/06	06BR0634-04	Firehouse #10 (roof level)	4/28/06	0.56	Mercury	EPA 324/1631	BRL	5/2/06	< 27.0	No	No	
TotalHg-ST10-4/28/06	06BR0634-05	North Side Sidewalk Bridge	4/28/06	0.57	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST100FD-4/28/06	06BR0634-13	Station 10 Field Duplicate	4/28/06	0.57	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST11-4/28/06	06BR0634-06	90 Trinity Place (roof level)	4/28/06	0.58	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST12-4/28/06	06BR0634-07	110 Greenwich Street (roof level)	4/28/06	0.57	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST13-4/28/06	06BR0634-08	Marriott Hotel, 38th Floor (roof level)	4/28/06	0.57	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST14-4/28/06	06BR0634-09	West Face - South end at corner (scaffolding level)	4/28/06	0.55	Mercury	EPA 324/1631	BRL	5/2/06	< 27.0	No	No	
TotalHg-ST15-4/28/06	06BR0634-10	South Face - East end at corner (scaffolding level)	4/28/06	0.55	Mercury	EPA 324/1631	BRL	5/2/06	< 27.0	No	No	
TotalHg-ST16-4/28/06	06BR0634-11	East Face - North end at corner (scaffolding level)	4/28/06	0.55	Mercury	EPA 324/1631	BRL	5/2/06	< 27.0	No	No	
TotalHg-ST17-4/28/06	06BR0634-12	North Face - West end at corner (scaffolding level)	4/28/06	0.55	Mercury	EPA 324/1631	BRL	5/2/06	< 27.0	No	No	
TotalHg-ST1-4/29/06	06BR0636-01	Southwest Area (sidewalk bridge level)	4/29/06	0.57	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST2-4/29/06	06BR0636-02	Southeast Area (sidewalk bridge level)	4/29/06	0.57	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST4-4/29/06	06BR0636-03	Northwest Area (street-level)	4/29/06	0.57	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST5-4/29/06	06BR0636-04	Firehouse #10 (roof level)	4/29/06	0.56	Mercury	EPA 324/1631	BRL	5/2/06	< 27.0	No	No	
TotalHg-ST10-4/29/06	06BR0636-05	North Side Sidewalk Bridge	4/29/06	0.57	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST11-4/29/06	06BR0636-06	90 Trinity Place (roof level)	4/29/06	0.58	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST12-4/29/06	06BR0636-07	110 Greenwich Street (roof level)	4/29/06	0.57	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST13-4/29/06	06BR0636-08	Marriott Hotel, 38th Floor (roof level)	4/29/06	0.57	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST14-4/29/06	06BR0636-09	West Face - South end at corner (scaffolding level)	4/29/06	0.55	Mercury	EPA 324/1631	BRL	5/2/06	< 27.0	No	No	
TotalHg-ST15-4/29/06	06BR0636-10	South Face - East end at corner (scaffolding level)	4/29/06	0.54	Mercury	EPA 324/1631	BRL	5/2/06	< 28.0	No	No	
TotalHg-ST16-4/29/06	06BR0636-11	East Face - North end at corner (scaffolding level)	4/29/06	0.55	Mercury	EPA 324/1631	BRL	5/2/06	< 27.0	No	No	
TotalHg-ST17-4/29/06	06BR0636-12	North Face - West end at corner (scaffolding level)	4/29/06	0.55	Mercury	EPA 324/1631	BRL	5/2/06	< 27.0	No	No	
TotalHg-ST1-4/30/06	06BR0638-01	Southwest Area (sidewalk bridge level)	4/30/06	0.58	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST2-4/30/06	06BR0638-02	Southeast Area (sidewalk bridge level)	4/30/06	0.58	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST4-4/30/06	06BR0638-03	Northwest Area (street-level)	4/30/06	0.58	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST5-4/30/06	06BR0638-04	Firehouse #10 (roof level)	4/30/06	0.57	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST10-4/30/06	06BR0638-05	North Side Sidewalk Bridge	4/30/06	0.58	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST11-4/30/06	06BR0638-06	90 Trinity Place (roof level)	4/30/06	0.56	Mercury	EPA 324/1631	BRL	5/2/06	< 27.0	No	No	
TotalHg-ST12-4/30/06	06BR0638-07	110 Greenwich Street (roof level)	4/30/06	0.56	Mercury	EPA 324/1631	BRL	5/2/06	< 27.0	No	No	
TotalHg-ST13-4/30/06	06BR0638-08	Marriott Hotel, 38th Floor (roof level)	4/30/06	0.58	Mercury	EPA 324/1631	BRL	5/2/06	< 26.0	No	No	
TotalHg-ST14-4/30/06	06BR0638-09	West Face - South end at corner (scaffolding level)	4/30/06	0.62	Mercury	EPA 324/1631	BRL	5/2/06	< 24.0	No	No	
TotalHg-ST15-4/30/06	06BR0638-10	South Face - East end at corner (scaffolding level)	4/30/06	0.63	Mercury	EPA 324/1631	BRL	5/2/06	< 24.0	No	No	
TotalHg-ST16-4/30/06	06BR0638-11	East Face - North end at corner (scaffolding level)	4/30/06	0.62	Mercury	EPA 324/1631	BRL	5/2/06	< 24.0	No	No	
TotalHg-ST17-4/30/06	06BR0638-12	North Face - West end at corner (scaffolding level)	4/30/06	0.61	Mercury	EPA 324/1631	BRL	5/2/06	< 25.0	No	No	

Note:

- The sample collected at Station 4 (Northwest Area [street-level]) on April 28, 2006 was for a 24-hour period but was not continuous; sample collection was interrupted by a 1-hour power failure.