

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-4/30/07	07BR0580-01	Southwest Area (sidewalk bridge level)	4/30/07	0.61	Mercury	EPA 324/1631	BRL	5/2/07	< 25.0	No	No	
TotalHg-ST2-4/30/07	07BR0580-02	Southeast Area (sidewalk bridge level)	4/30/07	0.60	Mercury	EPA 324/1631	BRL	5/2/07	< 25.0	No	No	
TotalHg-ST4-4/30/07	07BR0580-03	Northwest Area (street-level)	4/30/07	0.60	Mercury	EPA 324/1631	BRL	5/2/07	< 25.0	No	No	
TotalHg-ST5-4/30/07	07BR0580-04	Firehouse #10 (roof level)	4/30/07	0.59	Mercury	EPA 324/1631	BRL	5/2/07	< 25.0	No	No	
TotalHg-ST10-4/30/07	07BR0580-05	North Side Sidewalk Bridge	4/30/07	0.57	Mercury	EPA 324/1631	BRL	5/2/07	< 26.0	No	No	
TotalHg-ST11-4/30/07	07BR0580-06	90 Trinity Place (roof level)	4/30/07	0.55	Mercury	EPA 324/1631	BRL	5/2/07	< 27.0	No	No	
TotalHg-ST12-4/30/07	07BR0580-07	110 Greenwich Street (roof level)	4/30/07	0.57	Mercury	EPA 324/1631	BRL	5/2/07	< 26.0	No	No	
TotalHg-ST13-4/30/07	07BR0580-08	Marriott Hotel, 38th Floor (roof level)	4/30/07	0.57	Mercury	EPA 324/1631	BRL	5/2/07	< 26.0	No	No	
TotalHg-ST14-4/30/07	07BR0580-09	West Face - South end at corner (scaffolding level)	4/30/07	0.56	Mercury	EPA 324/1631	BRL	5/2/07	< 27.0	No	No	
TotalHg-ST15-4/30/07	07BR0580-10	South Face - East end at corner (scaffolding level)	4/30/07	0.59	Mercury	EPA 324/1631	BRL	5/2/07	< 25.0	No	No	
TotalHg-ST16-4/30/07	07BR0580-11	East Face - North end at corner (scaffolding level)	4/30/07	0.59	Mercury	EPA 324/1631	BRL	5/2/07	< 25.0	No	No	
TotalHg-ST17-4/30/07	07BR0580-12	North Face - West end at corner (scaffolding level)	4/30/07	0.57	Mercury	EPA 324/1631	BRL	5/2/07	< 26.0	No	No	
TotalHg-ST1-5/1/07	07BR0585-01	Southwest Area (sidewalk bridge level)	5/1/07	0.55	Mercury	EPA 324/1631	BRL	5/3/07	< 27.0	No	No	
TotalHg-ST2-5/1/07	07BR0585-02	Southeast Area (sidewalk bridge level)	5/1/07	0.59	Mercury	EPA 324/1631	BRL	5/3/07	< 25.0	No	No	
TotalHg-ST4-5/1/07	07BR0585-03	Northwest Area (street-level)	5/1/07	0.63	Mercury	EPA 324/1631	BRL	5/3/07	< 24.0	No	No	
TotalHg-ST5-5/1/07	07BR0585-04	Firehouse #10 (roof level)	5/1/07	0.56	Mercury	EPA 324/1631	BRL	5/3/07	< 27.0	No	No	
TotalHg-ST11-5/1/07	07BR0585-05	90 Trinity Place (roof level)	5/1/07	0.53	Mercury	EPA 324/1631	BRL	5/3/07	< 28.0	No	No	
TotalHg-ST12-5/1/07	07BR0585-06	110 Greenwich Street (roof level)	5/1/07	0.60	Mercury	EPA 324/1631	BRL	5/3/07	< 25.0	No	No	
TotalHg-ST13-5/1/07	07BR0585-07	Marriott Hotel, 38th Floor (roof level)	5/1/07	0.57	Mercury	EPA 324/1631	BRL	5/3/07	< 26.0	No	No	
TotalHg-ST14-5/1/07	07BR0585-08	West Face - South end at corner (scaffolding level)	5/1/07	0.56	Mercury	EPA 324/1631	BRL	5/3/07	< 27.0	No	No	
TotalHg-ST15-5/1/07	07BR0585-09	South Face - East end at corner (scaffolding level)	5/1/07	0.58	Mercury	EPA 324/1631	BRL	5/3/07	< 26.0	No	No	
TotalHg-ST16-5/1/07	07BR0585-10	East Face - North end at corner (scaffolding level)	5/1/07	0.60	Mercury	EPA 324/1631	BRL	5/3/07	< 25.0	No	No	
TotalHg-ST17-5/1/07	07BR0585-11	North Face - West end at corner (scaffolding level)	5/1/07	0.60	Mercury	EPA 324/1631	BRL	5/3/07	< 25.0	No	No	

Note:

- Mercury sample at Station 10 (North Side Sidewalk Bridge) on May 1, 2007 was not available for analysis on account of media damage.