

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
									<b>3,000</b>			
TotalHg-ST1-5/1/06	06BR0642-01	Southwest Area (sidewalk bridge level)	5/1/06	0.58	Mercury	EPA 324/1631	BRL	5/3/06	< 26.0	No	No	
TotalHg-ST2-5/1/06	06BR0642-02	Southeast Area (sidewalk bridge level)	5/1/06	0.58	Mercury	EPA 324/1631	BRL	5/3/06	< 26.0	No	No	
TotalHg-ST4-5/1/06	06BR0642-03	Northwest Area (street-level)	5/1/06	0.58	Mercury	EPA 324/1631	BRL	5/3/06	< 26.0	No	No	
TotalHg-ST5-5/1/06	06BR0642-04	Firehouse #10 (roof level)	5/1/06	0.58	Mercury	EPA 324/1631	BRL	5/3/06	< 26.0	No	No	
TotalHg-ST10-5/1/06	06BR0642-05	North Side Sidewalk Bridge	5/1/06	0.58	Mercury	EPA 324/1631	BRL	5/3/06	< 26.0	No	No	
TotalHg-ST11-5/1/06	06BR0642-06	90 Trinity Place (roof level)	5/1/06	0.57	Mercury	EPA 324/1631	BRL	5/3/06	< 26.0	No	No	
TotalHg-ST12-5/1/06	06BR0642-07	110 Greenwich Street (roof level)	5/1/06	0.57	Mercury	EPA 324/1631	BRL	5/3/06	< 26.0	No	No	
TotalHg-ST13-5/1/06	06BR0642-08	Marriott Hotel, 38th Floor (roof level)	5/1/06	0.57	Mercury	EPA 324/1631	BRL	5/3/06	< 26.0	No	No	
TotalHg-ST14-5/1/06	06BR0642-09	West Face - South end at corner (scaffolding level)	5/1/06	0.58	Mercury	EPA 324/1631	BRL	5/3/06	< 26.0	No	No	
TotalHg-ST15-5/1/06	06BR0642-10	South Face - East end at corner (scaffolding level)	5/1/06	0.57	Mercury	EPA 324/1631	BRL	5/3/06	< 26.0	No	No	
TotalHg-ST16-5/1/06	06BR0642-11	East Face - North end at corner (scaffolding level)	5/1/06	0.57	Mercury	EPA 324/1631	BRL	5/3/06	< 26.0	No	No	
TotalHg-ST17-5/1/06	06BR0642-12	North Face - West end at corner (scaffolding level)	5/1/06	0.58	Mercury	EPA 324/1631	BRL	5/3/06	< 26.0	No	No	
TotalHg-ST1-5/2/06	06BR0647-01	Southwest Area (sidewalk bridge level)	5/2/06	0.57	Mercury	EPA 324/1631	BRL	5/4/06	< 26.0	No	No	
TotalHg-ST2-5/2/06	06BR0647-02	Southeast Area (sidewalk bridge level)	5/2/06	0.57	Mercury	EPA 324/1631	BRL	5/4/06	< 26.0	No	No	
TotalHg-ST4-5/2/06	06BR0647-03	Northwest Area (street-level)	5/2/06	0.57	Mercury	EPA 324/1631	BRL	5/4/06	< 26.0	No	No	
TotalHg-ST5-5/2/06	06BR0647-04	Firehouse #10 (roof level)	5/2/06	0.57	Mercury	EPA 324/1631	BRL	5/4/06	< 26.0	No	No	
TotalHg-ST10-5/2/06	06BR0647-05	North Side Sidewalk Bridge	5/2/06	0.57	Mercury	EPA 324/1631	BRL	5/4/06	< 26.0	No	No	
TotalHg-ST11-5/2/06	06BR0647-06	90 Trinity Place (roof level)	5/2/06	0.57	Mercury	EPA 324/1631	BRL	5/4/06	< 26.0	No	No	
TotalHg-ST12-5/2/06	06BR0647-07	110 Greenwich Street (roof level)	5/2/06	0.58	Mercury	EPA 324/1631	BRL	5/4/06	< 26.0	No	No	
TotalHg-ST13-5/2/06	06BR0647-08	Marriott Hotel, 38th Floor (roof level)	5/2/06	0.58	Mercury	EPA 324/1631	BRL	5/4/06	< 26.0	No	No	
TotalHg-ST14-5/2/06	06BR0647-09	West Face - South end at corner (scaffolding level)	5/2/06	0.57	Mercury	EPA 324/1631	BRL	5/4/06	< 26.0	No	No	
TotalHg-ST15-5/2/06	06BR0647-10	South Face - East end at corner (scaffolding level)	5/2/06	0.57	Mercury	EPA 324/1631	BRL	5/4/06	< 26.0	No	No	
TotalHg-ST16-5/2/06	06BR0647-11	East Face - North end at corner (scaffolding level)	5/2/06	0.57	Mercury	EPA 324/1631	BRL	5/4/06	< 26.0	No	No	
TotalHg-ST17-5/2/06	06BR0647-12	North Face - West end at corner (scaffolding level)	5/2/06	0.57	Mercury	EPA 324/1631	BRL	5/4/06	< 26.0	No	No	