

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-5/5/06	06BR0669-01	Southwest Area (sidewalk bridge level)	5/5/06	0.57	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST2-5/5/06	06BR0669-02	Southeast Area (sidewalk bridge level)	5/5/06	0.57	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST4-5/5/06	06BR0669-03	Northwest Area (street-level)	5/5/06	0.58	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST5-5/5/06	06BR0669-04	Firehouse #10 (roof level)	5/5/06	0.59	Mercury	EPA 324/1631	BRL	5/9/06	< 25.0	No	No	
TotalHg-ST10-5/5/06	06BR0669-05	North Side Sidewalk Bridge	5/5/06	0.58	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST11-5/5/06	06BR0669-06	90 Trinity Place (roof level)	5/5/06	0.59	Mercury	EPA 324/1631	BRL	5/9/06	< 25.0	No	No	
TotalHg-ST12-5/5/06	06BR0669-07	110 Greenwich Street (roof level)	5/5/06	0.56	Mercury	EPA 324/1631	BRL	5/9/06	< 27.0	No	No	
TotalHg-ST13-5/5/06	06BR0669-08	Marriott Hotel, 38th Floor (roof level)	5/5/06	0.55	Mercury	EPA 324/1631	BRL	5/9/06	< 27.0	No	No	
TotalHg-ST14-5/5/06	06BR0669-09	West Face - South end at corner (scaffolding level)	5/5/06	0.56	Mercury	EPA 324/1631	BRL	5/9/06	< 27.0	No	No	
TotalHg-ST15-5/5/06	06BR0669-10	South Face - East end at corner (scaffolding level)	5/5/06	0.56	Mercury	EPA 324/1631	BRL	5/9/06	< 27.0	No	No	
TotalHg-ST16-5/5/06	06BR0669-11	East Face - North end at corner (scaffolding level)	5/5/06	0.56	Mercury	EPA 324/1631	BRL	5/9/06	< 27.0	No	No	
TotalHg-ST17-5/5/06	06BR0669-12	North Face - West end at corner (scaffolding level)	5/5/06	0.56	Mercury	EPA 324/1631	BRL	5/9/06	< 27.0	No	No	
TotalHg-ST1-5/6/06	06BR0670-01	Southwest Area (sidewalk bridge level)	5/6/06	0.56	Mercury	EPA 324/1631	BRL	5/9/06	< 27.0	No	No	
TotalHg-ST2-5/6/06	06BR0670-02	Southeast Area (sidewalk bridge level)	5/6/06	0.57	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST4-5/6/06	06BR0670-03	Northwest Area (street-level)	5/6/06	0.56	Mercury	EPA 324/1631	BRL	5/9/06	< 27.0	No	No	
TotalHg-ST5-5/6/06	06BR0670-04	Firehouse #10 (roof level)	5/6/06	0.57	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST11-5/6/06	06BR0670-05	90 Trinity Place (roof level)	5/6/06	0.57	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST12-5/6/06	06BR0670-06	110 Greenwich Street (roof level)	5/6/06	0.60	Mercury	EPA 324/1631	BRL	5/9/06	< 25.0	No	No	
TotalHg-ST13-5/6/06	06BR0670-07	Marriott Hotel, 38th Floor (roof level)	5/6/06	0.57	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST14-5/6/06	06BR0670-08	West Face - South end at corner (scaffolding level)	5/6/06	0.57	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST15-5/6/06	06BR0670-09	South Face - East end at corner (scaffolding level)	5/6/06	0.57	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST16-5/6/06	06BR0670-10	East Face - North end at corner (scaffolding level)	5/6/06	0.57	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST17-5/6/06	06BR0670-11	North Face - West end at corner (scaffolding level)	5/6/06	0.57	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST1-5/7/06	06BR0671-01	Southwest Area (sidewalk bridge level)	5/7/06	0.58	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST2-5/7/06	06BR0671-02	Southeast Area (sidewalk bridge level)	5/7/06	0.59	Mercury	EPA 324/1631	BRL	5/9/06	< 25.0	No	No	
TotalHg-ST5-5/7/06	06BR0671-03	Firehouse #10 (roof level)	5/7/06	0.58	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST10-5/7/06	06BR0671-04	North Side Sidewalk Bridge	5/7/06	0.57	Mercury	EPA 324/1631	BRL	5/9/06	< 26.0	No	No	
TotalHg-ST11-5/7/06	06BR0671-05	90 Trinity Place (roof level)	5/7/06	0.56	Mercury	EPA 324/1631	BRL	5/9/06	< 27.0	No	No	
TotalHg-ST12-5/7/06	06BR0671-06	110 Greenwich Street (roof level)	5/7/06	0.56	Mercury	EPA 324/1631	BRL	5/9/06	< 27.0	No	No	
TotalHg-ST13-5/7/06	06BR0671-07	Marriott Hotel, 38th Floor (roof level)	5/7/06	0.60	Mercury	EPA 324/1631	BRL	5/9/06	< 25.0	No	No	
TotalHg-ST14-5/7/06	06BR0671-08	West Face - South end at corner (scaffolding level)	5/7/06	0.59	Mercury	EPA 324/1631	BRL	5/9/06	< 25.0	No	No	
TotalHg-ST15-5/7/06	06BR0671-09	South Face - East end at corner (scaffolding level)	5/7/06	0.59	Mercury	EPA 324/1631	BRL	5/9/06	< 25.0	No	No	
TotalHg-ST16-5/7/06	06BR0671-10	East Face - North end at corner (scaffolding level)	5/7/06	0.60	Mercury	EPA 324/1631	BRL	5/9/06	< 25.0	No	No	
TotalHg-ST17-5/7/06	06BR0671-11	North Face - West end at corner (scaffolding level)	5/7/06	0.60	Mercury	EPA 324/1631	BRL	5/9/06	< 25.0	No	No	

Notes:

1. Mercury sample at Station 10 (North Side [sidewalk bridge level]) on May 6, 2006 was not available for analysis on account of pump failure.
2. Mercury sample at Station 4 (Northwest Area [street-level]) on May 7, 2006 was not available for analysis on account of temporary power failure.