

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-5/8/06	06BR0676-01	Southwest Area (sidewalk bridge level)	5/8/06	0.56	Mercury	EPA 324/1631	BRL	5/10/06	< 27.0	No	No	
TotalHg-ST2-5/8/06	06BR0676-02	Southeast Area (sidewalk bridge level)	5/8/06	0.57	Mercury	EPA 324/1631	BRL	5/10/06	< 26.0	No	No	
TotalHg-ST4-5/8/06	06BR0676-03	Northwest Area (street-level)	5/8/06	0.56	Mercury	EPA 324/1631	BRL	5/10/06	< 27.0	No	No	
TotalHg-ST5-5/8/06	06BR0676-04	Firehouse #10 (roof level)	5/8/06	0.56	Mercury	EPA 324/1631	BRL	5/10/06	< 27.0	No	No	
TotalHg-ST10-5/8/06	06BR0676-05	North Side Sidewalk Bridge	5/8/06	0.56	Mercury	EPA 324/1631	BRL	5/10/06	< 27.0	No	No	
TotalHg-ST11-5/8/06	06BR0676-06	90 Trinity Place (roof level)	5/8/06	0.57	Mercury	EPA 324/1631	BRL	5/10/06	< 26.0	No	No	
TotalHg-ST12-5/8/06	06BR0676-07	110 Greenwich Street (roof level)	5/8/06	0.57	Mercury	EPA 324/1631	BRL	5/10/06	< 26.0	No	No	
TotalHg-ST13-5/8/06	06BR0676-08	Marriott Hotel, 38th Floor (roof level)	5/8/06	0.57	Mercury	EPA 324/1631	BRL	5/10/06	< 26.0	No	No	
TotalHg-ST14-5/8/06	06BR0676-09	West Face - South end at corner (scaffolding level)	5/8/06	0.57	Mercury	EPA 324/1631	BRL	5/10/06	< 26.0	No	No	
TotalHg-ST15-5/8/06	06BR0676-10	South Face - East end at corner (scaffolding level)	5/8/06	0.59	Mercury	EPA 324/1631	BRL	5/10/06	< 25.0	No	No	
TotalHg-ST16-5/8/06	06BR0676-11	East Face - North end at corner (scaffolding level)	5/8/06	0.57	Mercury	EPA 324/1631	BRL	5/10/06	< 26.0	No	No	
TotalHg-ST17-5/8/06	06BR0676-12	North Face - West end at corner (scaffolding level)	5/8/06	0.57	Mercury	EPA 324/1631	BRL	5/10/06	< 26.0	No	No	
TotalHg-ST1-5/9/06	06BR0679-01	Southwest Area (sidewalk bridge level)	5/9/06	0.58	Mercury	EPA 324/1631	BRL	5/11/06	< 26.0	No	No	
TotalHg-ST2-5/9/06	06BR0679-02	Southeast Area (sidewalk bridge level)	5/9/06	0.58	Mercury	EPA 324/1631	BRL	5/11/06	< 26.0	No	No	
TotalHg-ST4-5/9/06	06BR0679-03	Northwest Area (street-level)	5/9/06	0.57	Mercury	EPA 324/1631	BRL	5/11/06	< 26.0	No	No	
TotalHg-ST5-5/9/06	06BR0679-04	Firehouse #10 (roof level)	5/9/06	0.57	Mercury	EPA 324/1631	BRL	5/11/06	< 26.0	No	No	
TotalHg-ST10-5/9/06	06BR0679-05	North Side Sidewalk Bridge	5/9/06	0.57	Mercury	EPA 324/1631	BRL	5/11/06	< 26.0	No	No	
TotalHg-ST11-5/9/06	06BR0679-06	90 Trinity Place (roof level)	5/9/06	0.57	Mercury	EPA 324/1631	BRL	5/11/06	< 26.0	No	No	
TotalHg-ST12-5/9/06	06BR0679-07	110 Greenwich Street (roof level)	5/9/06	0.57	Mercury	EPA 324/1631	BRL	5/11/06	< 26.0	No	No	
TotalHg-ST13-5/9/06	06BR0679-08	Marriott Hotel, 38th Floor (roof level)	5/9/06	0.56	Mercury	EPA 324/1631	BRL	5/11/06	< 27.0	No	No	
TotalHg-ST14-5/9/06	06BR0679-09	West Face - South end at corner (scaffolding level)	5/9/06	0.56	Mercury	EPA 324/1631	BRL	5/11/06	< 27.0	No	No	
TotalHg-ST15-5/9/06	06BR0679-10	South Face - East end at corner (scaffolding level)	5/9/06	0.55	Mercury	EPA 324/1631	BRL	5/11/06	< 27.0	No	No	
TotalHg-ST16-5/9/06	06BR0679-11	East Face - North end at corner (scaffolding level)	5/9/06	0.56	Mercury	EPA 324/1631	BRL	5/11/06	< 27.0	No	No	
TotalHg-ST17-5/9/06	06BR0679-12	North Face - West end at corner (scaffolding level)	5/9/06	0.56	Mercury	EPA 324/1631	BRL	5/11/06	< 27.0	No	No	