

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m <sup>3</sup> )	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									3,000			
TotalHg-ST1-5/9/09	0920003-01	Southwest Area (sidewalk bridge level)	5/9/09	0.56	Mercury	EPA 324/1631	BRL	5/12/09	< 27.0	No	No	
TotalHg-ST2-5/9/09	0920003-02	Southeast Area (sidewalk bridge level)	5/9/09	0.55	Mercury	EPA 324/1631	BRL	5/12/09	< 27.0	No	No	
TotalHg-ST4-5/9/09	0920003-03	Northwest Area (street-level)	5/9/09	0.53	Mercury	EPA 324/1631	BRL	5/12/09	< 28.0	No	No	
TotalHg-ST5-5/9/09	0920003-04	Firehouse #10 (roof level)	5/9/09	0.58	Mercury	EPA 324/1631	BRL	5/12/09	< 26.0	No	No	
TotalHg-ST10-5/9/09	0920003-05	North Side Sidewalk Bridge	5/9/09	0.58	Mercury	EPA 324/1631	BRL	5/12/09	< 26.0	No	No	
TotalHg-ST11-5/9/09	0920003-06	90 Trinity Place (roof level)	5/9/09	0.56	Mercury	EPA 324/1631	BRL	5/12/09	< 27.0	No	No	
TotalHg-ST12-5/9/09	0920003-07	110 Greenwich Street (roof level)	5/9/09	0.57	Mercury	EPA 324/1631	BRL	5/12/09	< 26.0	No	No	
TotalHg-ST13-5/9/09	0920003-08	Marriott Hotel, 38th Floor (roof level)	5/9/09	0.57	Mercury	EPA 324/1631	BRL	5/12/09	< 26.0	No	No	
TotalHg-ST14-5/9/09	0920003-09	West Face - South end at corner (scaffolding level)	5/9/09	0.54	Mercury	EPA 324/1631	BRL	5/12/09	< 28.0	No	No	
TotalHg-ST15-5/9/09	0920003-10	South Face - East end at corner (scaffolding level)	5/9/09	0.57	Mercury	EPA 324/1631	BRL	5/12/09	< 26.0	No	No	
TotalHg-ST16-5/9/09	0920003-11	East Face - North end at corner (scaffolding level)	5/9/09	0.54	Mercury	EPA 324/1631	BRL	5/12/09	< 28.0	No	No	
TotalHg-ST17-5/9/09	0920003-12	North Face - West end at corner (scaffolding level)	5/9/09	0.55	Mercury	EPA 324/1631	BRL	5/12/09	< 27.0	No	No	
TotalHg-ST1-5/10/09	0920004-01	Southwest Area (sidewalk bridge level)	5/10/09	0.55	Mercury	EPA 324/1631	BRL	5/12/09	< 27.0	No	No	
TotalHg-ST2-5/10/09	0920004-02	Southeast Area (sidewalk bridge level)	5/10/09	0.57	Mercury	EPA 324/1631	BRL	5/12/09	< 26.0	No	No	
TotalHg-ST4-5/10/09	0920004-03	Northwest Area (street-level)	5/10/09	0.56	Mercury	EPA 324/1631	BRL	5/12/09	< 27.0	No	No	
TotalHg-ST5-5/10/09	0920004-04	Firehouse #10 (roof level)	5/10/09	0.59	Mercury	EPA 324/1631	BRL	5/12/09	< 25.0	No	No	
TotalHg-ST10-5/10/09	0920004-05	North Side Sidewalk Bridge	5/10/09	0.56	Mercury	EPA 324/1631	BRL	5/12/09	< 27.0	No	No	
TotalHg-ST11-5/10/09	0920004-06	90 Trinity Place (roof level)	5/10/09	0.56	Mercury	EPA 324/1631	BRL	5/12/09	< 27.0	No	No	
TotalHg-ST12-5/10/09	0920004-07	110 Greenwich Street (roof level)	5/10/09	0.55	Mercury	EPA 324/1631	BRL	5/12/09	< 27.0	No	No	
TotalHg-ST13-5/10/09	0920004-08	Marriott Hotel, 38th Floor (roof level)	5/10/09	0.54	Mercury	EPA 324/1631	BRL	5/12/09	< 28.0	No	No	
TotalHg-ST14-5/10/09	0920004-09	West Face - South end at corner (scaffolding level)	5/10/09	0.58	Mercury	EPA 324/1631	BRL	5/12/09	< 26.0	No	No	
TotalHg-ST15-5/10/09	0920004-10	South Face - East end at corner (scaffolding level)	5/10/09	0.56	Mercury	EPA 324/1631	BRL	5/12/09	< 27.0	No	No	
TotalHg-ST16-5/10/09	0920004-11	East Face - North end at corner (scaffolding level)	5/10/09	0.58	Mercury	EPA 324/1631	BRL	5/12/09	< 26.0	No	No	
TotalHg-ST17-5/10/09	0920004-12	North Face - West end at corner (scaffolding level)	5/10/09	0.56	Mercury	EPA 324/1631	BRL	5/12/09	< 27.0	No	No	
TotalHg-ST1-5/11/09	0920024-01	Southwest Area (sidewalk bridge level)	5/11/09	0.55	Mercury	EPA 324/1631	BRL	5/13/09	< 27.0	No	No	
TotalHg-ST2-5/11/09	0920024-02	Southeast Area (sidewalk bridge level)	5/11/09	0.56	Mercury	EPA 324/1631	BRL	5/13/09	< 27.0	No	No	
TotalHg-ST4-5/11/09	0920024-03	Northwest Area (street-level)	5/11/09	0.56	Mercury	EPA 324/1631	BRL	5/13/09	< 27.0	No	No	
TotalHg-ST5-5/11/09	0920024-04	Firehouse #10 (roof level)	5/11/09	0.58	Mercury	EPA 324/1631	BRL	5/13/09	< 26.0	No	No	
TotalHg-ST10-5/11/09	0920024-05	North Side Sidewalk Bridge	5/11/09	0.56	Mercury	EPA 324/1631	BRL	5/13/09	< 27.0	No	No	
TotalHg-ST11-5/11/09	0920024-06	90 Trinity Place (roof level)	5/11/09	0.54	Mercury	EPA 324/1631	BRL	5/13/09	< 28.0	No	No	
TotalHg-ST12-5/11/09	0920024-07	110 Greenwich Street (roof level)	5/11/09	0.55	Mercury	EPA 324/1631	BRL	5/13/09	< 27.0	No	No	
TotalHg-ST13-5/11/09	0920024-08	Marriott Hotel, 38th Floor (roof level)	5/11/09	0.57	Mercury	EPA 324/1631	BRL	5/13/09	< 26.0	No	No	
TotalHg-ST14-5/11/09	0920024-09	West Face - South end at corner (scaffolding level)	5/11/09	0.59	Mercury	EPA 324/1631	BRL	5/13/09	< 25.0	No	No	
TotalHg-ST15-5/11/09	0920024-10	South Face - East end at corner (scaffolding level)	5/11/09	0.59	Mercury	EPA 324/1631	BRL	5/13/09	< 25.0	No	No	
TotalHg-ST16-5/11/09	0920024-11	East Face - North end at corner (scaffolding level)	5/11/09	0.56	Mercury	EPA 324/1631	BRL	5/13/09	< 27.0	No	No	
TotalHg-ST17-5/11/09	0920024-12	North Face - West end at corner (scaffolding level)	5/11/09	0.54	Mercury	EPA 324/1631	BRL	5/13/09	< 28.0	No	No	