

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-5/12/06	06BR0724-01	Southwest Area (sidewalk bridge level)	5/12/06	0.58	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST2-5/12/06	06BR0724-02	Southeast Area (sidewalk bridge level)	5/12/06	0.58	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST4-5/12/06	06BR0724-03	Northwest Area (street-level)	5/12/06	0.57	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST5-5/12/06	06BR0724-04	Firehouse #10 (roof level)	5/12/06	0.56	Mercury	EPA 324/1631	BRL	5/16/06	< 27.0	No	No	
TotalHg-ST10-5/12/06	06BR0724-05	North Side Sidewalk Bridge	5/12/06	0.58	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST11-5/12/06	06BR0724-06	90 Trinity Place (roof level)	5/12/06	0.58	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST12-5/12/06	06BR0724-07	110 Greenwich Street (roof level)	5/12/06	0.60	Mercury	EPA 324/1631	BRL	5/16/06	< 25.0	No	No	
TotalHg-ST13-5/12/06	06BR0724-08	Marriott Hotel, 38th Floor (roof level)	5/12/06	0.59	Mercury	EPA 324/1631	BRL	5/16/06	< 25.0	No	No	
TotalHg-ST14-5/12/06	06BR0724-09	West Face - South end at corner (scaffolding level)	5/12/06	0.58	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST15-5/12/06	06BR0724-10	South Face - East end at corner (scaffolding level)	5/12/06	0.58	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST16-5/12/06	06BR0724-11	East Face - North end at corner (scaffolding level)	5/12/06	0.58	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST17-5/12/06	06BR0724-12	North Face - West end at corner (scaffolding level)	5/12/06	0.58	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST1-5/13/06	06BR0725-01	Southwest Area (sidewalk bridge level)	5/13/06	0.57	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST2-5/13/06	06BR0725-02	Southeast Area (sidewalk bridge level)	5/13/06	0.57	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST4-5/13/06	06BR0725-03	Northwest Area (street-level)	5/13/06	0.56	Mercury	EPA 324/1631	BRL	5/16/06	< 27.0	No	No	
TotalHg-ST5-5/13/06	06BR0725-04	Firehouse #10 (roof level)	5/13/06	0.57	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST10-5/13/06	06BR0725-05	North Side Sidewalk Bridge	5/13/06	0.56	Mercury	EPA 324/1631	BRL	5/16/06	< 27.0	No	No	
TotalHg-ST11-5/13/06	06BR0725-06	90 Trinity Place (roof level)	5/13/06	0.57	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST12-5/13/06	06BR0725-07	110 Greenwich Street (roof level)	5/13/06	0.57	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST13-5/13/06	06BR0725-08	Marriott Hotel, 38th Floor (roof level)	5/13/06	0.57	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST14-5/13/06	06BR0725-09	West Face - South end at corner (scaffolding level)	5/13/06	0.56	Mercury	EPA 324/1631	BRL	5/16/06	< 27.0	No	No	
TotalHg-ST15-5/13/06	06BR0725-10	South Face - East end at corner (scaffolding level)	5/13/06	0.56	Mercury	EPA 324/1631	BRL	5/16/06	< 27.0	No	No	
TotalHg-ST16-5/13/06	06BR0725-11	East Face - North end at corner (scaffolding level)	5/13/06	0.56	Mercury	EPA 324/1631	BRL	5/16/06	< 27.0	No	No	
TotalHg-ST17-5/13/06	06BR0725-12	North Face - West end at corner (scaffolding level)	5/13/06	0.56	Mercury	EPA 324/1631	BRL	5/16/06	< 27.0	No	No	
TotalHg-ST1-5/14/06	06BR0726-01	Southwest Area (sidewalk bridge level)	5/14/06	0.58	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST2-5/14/06	06BR0726-02	Southeast Area (sidewalk bridge level)	5/14/06	0.58	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST4-5/14/06	06BR0726-03	Northwest Area (street-level)	5/14/06	0.58	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST5-5/14/06	06BR0726-04	Firehouse #10 (roof level)	5/14/06	0.57	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST10-5/14/06	06BR0726-05	North Side Sidewalk Bridge	5/14/06	0.58	Mercury	EPA 324/1631	BRL	5/16/06	< 26.0	No	No	
TotalHg-ST11-5/14/06	06BR0726-06	90 Trinity Place (roof level)	5/14/06	0.56	Mercury	EPA 324/1631	BRL	5/16/06	< 27.0	No	No	
TotalHg-ST12-5/14/06	06BR0726-07	110 Greenwich Street (roof level)	5/14/06	0.56	Mercury	EPA 324/1631	BRL	5/16/06	< 27.0	No	No	
TotalHg-ST13-5/14/06	06BR0726-08	Marriott Hotel, 38th Floor (roof level)	5/14/06	0.56	Mercury	EPA 324/1631	BRL	5/16/06	< 27.0	No	No	
TotalHg-ST14-5/14/06	06BR0726-09	West Face - South end at corner (scaffolding level)	5/14/06	0.62	Mercury	EPA 324/1631	BRL	5/16/06	< 24.0	No	No	
TotalHg-ST15-5/14/06	06BR0726-10	South Face - East end at corner (scaffolding level)	5/14/06	0.61	Mercury	EPA 324/1631	BRL	5/16/06	< 25.0	No	No	

Note:

- Mercury sample at Station 17 (North Face - West end at corner [scaffolding level]) on May 14, 2006 was not available for analysis on account of a pump failure.
- Mercury sample at Station 16 (East Face - North end at corner [scaffolding level]) on May 14, 2006 were not available for analysis on account of a temporary power failure.