

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target	Exceeds EPA	Comments
									300	Air Quality Levels	Site Specific Trigger Levels	
Target Air Quality Levels									3,000			
EPA Site Specific Trigger Levels												
TotalHg-ST1-5/14/08	0820037-01	Southwest Area (sidewalk bridge level)	5/14/08	0.57	Mercury	EPA 324/1631	BRL	5/16/08	< 26.0	No	No	
TotalHg-ST2-5/14/08	0820037-02	Southeast Area (sidewalk bridge level)	5/14/08	0.57	Mercury	EPA 324/1631	BRL	5/16/08	< 26.0	No	No	
TotalHg-ST4-5/14/08	0820037-03	Northwest Area (street-level)	5/14/08	0.58	Mercury	EPA 324/1631	BRL	5/16/08	< 26.0	No	No	
TotalHg-ST5-5/14/08	0820037-04	Firehouse #10 (roof level)	5/14/08	0.55	Mercury	EPA 324/1631	BRL	5/16/08	< 27.0	No	No	
TotalHg-ST10-5/14/08	0820037-05	North Side Sidewalk Bridge	5/14/08	0.58	Mercury	EPA 324/1631	BRL	5/16/08	< 26.0	No	No	
TotalHg-ST11-5/14/08	0820037-06	90 Trinity Place (roof level)	5/14/08	0.56	Mercury	EPA 324/1631	BRL	5/16/08	< 27.0	No	No	
TotalHg-ST12-5/14/08	0820037-07	110 Greenwich Street (roof level)	5/14/08	0.56	Mercury	EPA 324/1631	BRL	5/16/08	< 27.0	No	No	
TotalHg-ST13-5/14/08	0820037-08	Marriott Hotel, 38th Floor (roof level)	5/14/08	0.58	Mercury	EPA 324/1631	BRL	5/16/08	< 26.0	No	No	
TotalHg-ST14-5/14/08	0820037-09	West Face - South end at corner (scaffolding level)	5/14/08	0.62	Mercury	EPA 324/1631	BRL	5/16/08	< 24.0	No	No	
TotalHg-ST15-5/14/08	0820037-10	South Face - East end at corner (scaffolding level)	5/14/08	0.67	Mercury	EPA 324/1631	BRL	5/16/08	< 22.0	No	No	
TotalHg-ST16-5/14/08	0820037-11	East Face - North end at corner (scaffolding level)	5/14/08	0.65	Mercury	EPA 324/1631	BRL	5/16/08	< 23.0	No	No	
TotalHg-ST17-5/14/08	0820037-12	North Face - West end at corner (scaffolding level)	5/14/08	0.65	Mercury	EPA 324/1631	BRL	5/16/08	< 23.0	No	No	
TotalHg-ST1-5/15/08	0820044-01	Southwest Area (sidewalk bridge level)	5/15/08	0.55	Mercury	EPA 324/1631	BRL	5/17/08	< 27.0	No	No	
TotalHg-ST2-5/15/08	0820044-02	Southeast Area (sidewalk bridge level)	5/15/08	0.56	Mercury	EPA 324/1631	BRL	5/17/08	< 27.0	No	No	
TotalHg-ST4-5/15/08	0820044-03	Northwest Area (street-level)	5/15/08	0.57	Mercury	EPA 324/1631	BRL	5/17/08	< 26.0	No	No	
TotalHg-ST5-5/15/08	0820044-04	Firehouse #10 (roof level)	5/15/08	0.56	Mercury	EPA 324/1631	BRL	5/17/08	< 27.0	No	No	
TotalHg-ST10-5/15/08	0820044-05	North Side Sidewalk Bridge	5/15/08	0.57	Mercury	EPA 324/1631	BRL	5/17/08	< 26.0	No	No	
TotalHg-ST11-5/15/08	0820044-06	90 Trinity Place (roof level)	5/15/08	0.59	Mercury	EPA 324/1631	BRL	5/17/08	< 25.0	No	No	
TotalHg-ST12-5/15/08	0820044-07	110 Greenwich Street (roof level)	5/15/08	0.55	Mercury	EPA 324/1631	BRL	5/17/08	< 27.0	No	No	
TotalHg-ST13-5/15/08	0820044-08	Marriott Hotel, 38th Floor (roof level)	5/15/08	0.55	Mercury	EPA 324/1631	BRL	5/17/08	< 27.0	No	No	
TotalHg-ST14-5/15/08	0820044-09	West Face - South end at corner (scaffolding level)	5/15/08	0.54	Mercury	EPA 324/1631	BRL	5/17/08	< 28.0	No	No	
TotalHg-ST15-5/15/08	0820044-10	South Face - East end at corner (scaffolding level)	5/15/08	0.52	Mercury	EPA 324/1631	BRL	5/17/08	< 29.0	No	No	
TotalHg-ST16-5/15/08	0820044-11	East Face - North end at corner (scaffolding level)	5/15/08	0.55	Mercury	EPA 324/1631	BRL	5/17/08	< 27.0	No	No	
TotalHg-ST17-5/15/08	0820044-12	North Face - West end at corner (scaffolding level)	5/15/08	0.53	Mercury	EPA 324/1631	BRL	5/17/08	< 28.0	No	No	
TotalHg-ST1-5/16/08	0821004-01	Southwest Area (sidewalk bridge level)	5/16/08	0.55	Mercury	EPA 324/1631	BRL	5/19/08	< 27.0	No	No	
TotalHg-ST2-5/16/08	0821004-02	Southeast Area (sidewalk bridge level)	5/16/08	0.56	Mercury	EPA 324/1631	BRL	5/19/08	< 27.0	No	No	
TotalHg-ST4-5/16/08	0821004-03	Northwest Area (street-level)	5/16/08	0.61	Mercury	EPA 324/1631	BRL	5/19/08	< 25.0	No	No	
TotalHg-ST5-5/16/08	0821004-04	Firehouse #10 (roof level)	5/16/08	0.59	Mercury	EPA 324/1631	BRL	5/19/08	< 25.0	No	No	
TotalHg-ST10-5/16/08	0821004-05	North Side Sidewalk Bridge	5/16/08	0.56	Mercury	EPA 324/1631	BRL	5/19/08	< 27.0	No	No	
TotalHg-ST11-5/16/08	0821004-06	90 Trinity Place (roof level)	5/16/08	0.57	Mercury	EPA 324/1631	BRL	5/19/08	< 26.0	No	No	
TotalHg-ST12-5/16/08	0821004-07	110 Greenwich Street (roof level)	5/16/08	0.59	Mercury	EPA 324/1631	BRL	5/19/08	< 25.0	No	No	
TotalHg-ST13-5/16/08	0821004-08	Marriott Hotel, 38th Floor (roof level)	5/16/08	0.53	Mercury	EPA 324/1631	BRL	5/19/08	< 28.0	No	No	
TotalHg-ST14-5/16/08	0821004-09	West Face - South end at corner (scaffolding level)	5/16/08	0.52	Mercury	EPA 324/1631	BRL	5/19/08	< 29.0	No	No	
TotalHg-ST15-5/16/08	0821004-10	South Face - East end at corner (scaffolding level)	5/16/08	0.52	Mercury	EPA 324/1631	BRL	5/19/08	< 29.0	No	No	
TotalHg-ST16-5/16/08	0821004-11	East Face - North end at corner (scaffolding level)	5/16/08	0.50	Mercury	EPA 324/1631	BRL	5/19/08	< 30.0	No	No	
TotalHg-ST17-5/16/08	0821004-12	North Face - West end at corner (scaffolding level)	5/16/08	0.49	Mercury	EPA 324/1631	BRL	5/19/08	< 31.0	No	No	