

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-6/9/06	06BR0904-01	Southwest Area (sidewalk bridge level)	6/9/06	0.57	Mercury	EPA 324/1631	BRL	6/13/06	< 26.0	No	No	
TotalHg-ST2-6/9/06	06BR0904-02	Southeast Area (sidewalk bridge level)	6/9/06	0.57	Mercury	EPA 324/1631	BRL	6/13/06	< 26.0	No	No	
TotalHg-ST4-6/9/06	06BR0904-03	Northwest Area (street-level)	6/9/06	0.59	Mercury	EPA 324/1631	BRL	6/13/06	< 25.0	No	No	
TotalHg-ST5-6/9/06	06BR0904-04	Firehouse #10 (roof level)	6/9/06	0.52	Mercury	EPA 324/1631	BRL	6/13/06	< 29.0	No	No	
TotalHg-ST10-6/9/06	06BR0904-05	North Side Sidewalk Bridge	6/9/06	0.53	Mercury	EPA 324/1631	BRL	6/13/06	< 28.0	No	No	
TotalHg-ST100-6/9/06FD	06BR0904-13	Station 10 Field Duplicate	6/9/06	0.54	Mercury	EPA 324/1631	BRL	6/13/06	< 28.0	No	No	
TotalHg-ST11-6/9/06	06BR0904-06	90 Trinity Place (roof level)	6/9/06	0.59	Mercury	EPA 324/1631	BRL	6/13/06	< 25.0	No	No	
TotalHg-ST12-6/9/06	06BR0904-07	110 Greenwich Street (roof level)	6/9/06	0.57	Mercury	EPA 324/1631	BRL	6/13/06	< 26.0	No	No	
TotalHg-ST13-6/9/06	06BR0904-08	Marriott Hotel, 38th Floor (roof level)	6/9/06	0.55	Mercury	EPA 324/1631	BRL	6/13/06	< 27.0	No	No	
TotalHg-ST14-6/9/06	06BR0904-09	West Face - South end at corner (scaffolding level)	6/9/06	0.49	Mercury	EPA 324/1631	BRL	6/13/06	< 31.0	No	No	
TotalHg-ST15-6/9/06	06BR0904-10	South Face - East end at corner (scaffolding level)	6/9/06	0.49	Mercury	EPA 324/1631	BRL	6/13/06	< 31.0	No	No	
TotalHg-ST16-6/9/06	06BR0904-11	East Face - North end at corner (scaffolding level)	6/9/06	0.49	Mercury	EPA 324/1631	BRL	6/13/06	< 31.0	No	No	
TotalHg-ST17-6/9/06	06BR0904-12	North Face - West end at corner (scaffolding level)	6/9/06	0.49	Mercury	EPA 324/1631	BRL	6/13/06	< 31.0	No	No	
TotalHg-ST1-6/10/06	06BR0908-01	Southwest Area (sidewalk bridge level)	6/10/06	0.57	Mercury	EPA 324/1631	BRL	6/13/06	< 26.0	No	No	
TotalHg-ST2-6/10/06	06BR0908-02	Southeast Area (sidewalk bridge level)	6/10/06	0.57	Mercury	EPA 324/1631	BRL	6/13/06	< 26.0	No	No	
TotalHg-ST4-6/10/06	06BR0908-03	Northwest Area (street-level)	6/10/06	0.55	Mercury	EPA 324/1631	BRL	6/13/06	< 27.0	No	No	
TotalHg-ST5-6/10/06	06BR0908-04	Firehouse #10 (roof level)	6/10/06	0.61	Mercury	EPA 324/1631	BRL	6/13/06	< 25.0	No	No	
TotalHg-ST10-6/10/06	06BR0908-05	North Side Sidewalk Bridge	6/10/06	0.59	Mercury	EPA 324/1631	BRL	6/13/06	< 25.0	No	No	
TotalHg-ST11-6/10/06	06BR0908-06	90 Trinity Place (roof level)	6/10/06	0.57	Mercury	EPA 324/1631	BRL	6/13/06	< 26.0	No	No	
TotalHg-ST12-6/10/06	06BR0908-07	110 Greenwich Street (roof level)	6/10/06	0.58	Mercury	EPA 324/1631	BRL	6/13/06	< 26.0	No	No	
TotalHg-ST13-6/10/06	06BR0908-08	Marriott Hotel, 38th Floor (roof level)	6/10/06	0.58	Mercury	EPA 324/1631	BRL	6/13/06	< 26.0	No	No	
TotalHg-ST14-6/10/06	06BR0908-09	West Face - South end at corner (scaffolding level)	6/10/06	0.61	Mercury	EPA 324/1631	BRL	6/13/06	< 25.0	No	No	
TotalHg-ST15-6/10/06	06BR0908-10	South Face - East end at corner (scaffolding level)	6/10/06	0.61	Mercury	EPA 324/1631	BRL	6/13/06	< 25.0	No	No	
TotalHg-ST16-6/10/06	06BR0908-11	East Face - North end at corner (scaffolding level)	6/10/06	0.61	Mercury	EPA 324/1631	BRL	6/13/06	< 25.0	No	No	
TotalHg-ST17-6/10/06	06BR0908-12	North Face - West end at corner (scaffolding level)	6/10/06	0.61	Mercury	EPA 324/1631	BRL	6/13/06	< 25.0	No	No	
TotalHg-ST1-6/11/06	06BR0909-01	Southwest Area (sidewalk bridge level)	6/11/06	0.58	Mercury	EPA 324/1631	BRL	6/13/06	< 26.0	No	No	
TotalHg-ST2-6/11/06	06BR0909-02	Southeast Area (sidewalk bridge level)	6/11/06	0.59	Mercury	EPA 324/1631	BRL	6/13/06	< 25.0	No	No	
TotalHg-ST4-6/11/06	06BR0909-03	Northwest Area (street-level)	6/11/06	0.56	Mercury	EPA 324/1631	BRL	6/13/06	< 27.0	No	No	
TotalHg-ST5-6/11/06	06BR0909-04	Firehouse #10 (roof level)	6/11/06	0.59	Mercury	EPA 324/1631	BRL	6/13/06	< 25.0	No	No	
TotalHg-ST10-6/11/06	06BR0909-05	North Side Sidewalk Bridge	6/11/06	0.56	Mercury	EPA 324/1631	BRL	6/13/06	< 27.0	No	No	
TotalHg-ST11-6/11/06	06BR0909-06	90 Trinity Place (roof level)	6/11/06	0.57	Mercury	EPA 324/1631	BRL	6/13/06	< 26.0	No	No	
TotalHg-ST12-6/11/06	06BR0909-07	110 Greenwich Street (roof level)	6/11/06	0.58	Mercury	EPA 324/1631	BRL	6/13/06	< 26.0	No	No	
TotalHg-ST13-6/11/06	06BR0909-08	Marriott Hotel, 38th Floor (roof level)	6/11/06	0.57	Mercury	EPA 324/1631	BRL	6/13/06	< 26.0	No	No	
TotalHg-ST14-6/11/06	06BR0909-09	West Face - South end at corner (scaffolding level)	6/11/06	0.61	Mercury	EPA 324/1631	BRL	6/13/06	< 25.0	No	No	
TotalHg-ST15-6/11/06	06BR0909-10	South Face - East end at corner (scaffolding level)	6/11/06	0.61	Mercury	EPA 324/1631	BRL	6/13/06	< 25.0	No	No	
TotalHg-ST16-6/11/06	06BR0909-11	East Face - North end at corner (scaffolding level)	6/11/06	0.61	Mercury	EPA 324/1631	BRL	6/13/06	< 25.0	No	No	
TotalHg-ST17-6/11/06	06BR0909-12	North Face - West end at corner (scaffolding level)	6/11/06	0.62	Mercury	EPA 324/1631	BRL	6/13/06	< 24.0	No	No	