

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-7/2/08	0827033-01	Southwest Area (sidewalk bridge level)	7/2/08	0.64	Mercury	EPA 324/1631	BRL	7/5/08	< 23.0	No	No	
TotalHg-ST2-7/2/08	0827033-02	Southeast Area (sidewalk bridge level)	7/2/08	0.55	Mercury	EPA 324/1631	BRL	7/5/08	< 27.0	No	No	
TotalHg-ST4-7/2/08	0827033-03	Northwest Area (street-level)	7/2/08	0.58	Mercury	EPA 324/1631	BRL	7/5/08	< 26.0	No	No	
TotalHg-ST5-7/2/08	0827033-04	Firehouse #10 (roof level)	7/2/08	0.58	Mercury	EPA 324/1631	BRL	7/5/08	< 26.0	No	No	
TotalHg-ST10-7/2/08	0827033-05	North Side Sidewalk Bridge	7/2/08	0.56	Mercury	EPA 324/1631	BRL	7/5/08	< 27.0	No	No	
TotalHg-ST11-7/2/08	0827033-06	90 Trinity Place (roof level)	7/2/08	0.55	Mercury	EPA 324/1631	BRL	7/5/08	< 27.0	No	No	
TotalHg-ST12-7/2/08	0827033-07	110 Greenwich Street (roof level)	7/2/08	0.58	Mercury	EPA 324/1631	BRL	7/5/08	< 26.0	No	No	
TotalHg-ST13-7/2/08	0827033-08	Marriott Hotel, 38th Floor (roof level)	7/2/08	0.57	Mercury	EPA 324/1631	BRL	7/5/08	< 26.0	No	No	
TotalHg-ST14-7/2/08	0827033-09	West Face - South end at corner (scaffolding level)	7/2/08	0.59	Mercury	EPA 324/1631	BRL	7/5/08	< 25.0	No	No	
TotalHg-ST15-7/2/08	0827033-10	South Face - East end at corner (scaffolding level)	7/2/08	0.61	Mercury	EPA 324/1631	BRL	7/5/08	< 25.0	No	No	
TotalHg-ST16-7/2/08	0827033-11	East Face - North end at corner (scaffolding level)	7/2/08	0.62	Mercury	EPA 324/1631	BRL	7/5/08	< 24.0	No	No	
TotalHg-ST17-7/2/08	0827033-12	North Face - West end at corner (scaffolding level)	7/2/08	0.58	Mercury	EPA 324/1631	BRL	7/5/08	< 26.0	No	No	
TotalHg-ST1-7/3/08	0828002-01	Southwest Area (sidewalk bridge level)	7/3/08	0.58	Mercury	EPA 324/1631	BRL	7/8/08	< 26.0	No	No	
TotalHg-ST2-7/3/08	0828002-02	Southeast Area (sidewalk bridge level)	7/3/08	0.59	Mercury	EPA 324/1631	BRL	7/8/08	< 25.0	No	No	
TotalHg-ST4-7/3/08	0828002-03	Northwest Area (street-level)	7/3/08	0.54	Mercury	EPA 324/1631	BRL	7/8/08	< 28.0	No	No	
TotalHg-ST5-7/3/08	0828002-04	Firehouse #10 (roof level)	7/3/08	0.55	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST10-7/3/08	0828002-05	North Side Sidewalk Bridge	7/3/08	0.60	Mercury	EPA 324/1631	BRL	7/8/08	< 25.0	No	No	
TotalHg-ST11-7/3/08	0828002-06	90 Trinity Place (roof level)	7/3/08	0.56	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST12-7/3/08	0828002-07	110 Greenwich Street (roof level)	7/3/08	0.57	Mercury	EPA 324/1631	BRL	7/8/08	< 26.0	No	No	
TotalHg-ST13-7/3/08	0828002-08	Marriott Hotel, 38th Floor (roof level)	7/3/08	0.56	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST14-7/3/08	0828002-09	West Face - South end at corner (scaffolding level)	7/3/08	0.53	Mercury	EPA 324/1631	BRL	7/8/08	< 28.0	No	No	
TotalHg-ST15-7/3/08	0828002-10	South Face - East end at corner (scaffolding level)	7/3/08	0.52	Mercury	EPA 324/1631	BRL	7/8/08	< 29.0	No	No	
TotalHg-ST16-7/3/08	0828002-11	East Face - North end at corner (scaffolding level)	7/3/08	0.52	Mercury	EPA 324/1631	BRL	7/8/08	< 29.0	No	No	
TotalHg-ST17-7/3/08	0828002-12	North Face - West end at corner (scaffolding level)	7/3/08	0.55	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST1-7/4/08	0828003-01	Southwest Area (sidewalk bridge level)	7/4/08	0.57	Mercury	EPA 324/1631	BRL	7/8/08	< 26.0	No	No	
TotalHg-ST2-7/4/08	0828003-02	Southeast Area (sidewalk bridge level)	7/4/08	0.57	Mercury	EPA 324/1631	BRL	7/8/08	< 26.0	No	No	
TotalHg-ST4-7/4/08	0828003-03	Northwest Area (street-level)	7/4/08	0.55	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST5-7/4/08	0828003-04	Firehouse #10 (roof level)	7/4/08	0.57	Mercury	EPA 324/1631	BRL	7/8/08	< 26.0	No	No	
TotalHg-ST10-7/4/08	0828003-05	North Side Sidewalk Bridge	7/4/08	0.58	Mercury	EPA 324/1631	BRL	7/8/08	< 26.0	No	No	
TotalHg-ST11-7/4/08	0828003-06	90 Trinity Place (roof level)	7/4/08	0.60	Mercury	EPA 324/1631	BRL	7/8/08	< 25.0	No	No	
TotalHg-ST12-7/4/08	0828003-07	110 Greenwich Street (roof level)	7/4/08	0.59	Mercury	EPA 324/1631	BRL	7/8/08	< 25.0	No	No	
TotalHg-ST13-7/4/08	0828003-08	Marriott Hotel, 38th Floor (roof level)	7/4/08	0.56	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST14-7/4/08	0828003-09	West Face - South end at corner (scaffolding level)	7/4/08	0.55	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST15-7/4/08	0828003-10	South Face - East end at corner (scaffolding level)	7/4/08	0.59	Mercury	EPA 324/1631	BRL	7/8/08	< 25.0	No	No	
TotalHg-ST16-7/4/08	0828003-11	East Face - North end at corner (scaffolding level)	7/4/08	0.54	Mercury	EPA 324/1631	BRL	7/8/08	< 28.0	No	No	
TotalHg-ST17-7/4/08	0828003-12	North Face - West end at corner (scaffolding level)	7/4/08	0.58	Mercury	EPA 324/1631	BRL	7/8/08	< 26.0	No	No	
TotalHg-ST1-7/5/08	0828004-01	Southwest Area (sidewalk bridge level)	7/5/08	0.56	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST2-7/5/08	0828004-02	Southeast Area (sidewalk bridge level)	7/5/08	0.58	Mercury	EPA 324/1631	BRL	7/8/08	< 26.0	No	No	
TotalHg-ST4-7/5/08	0828004-03	Northwest Area (street-level)	7/5/08	0.59	Mercury	EPA 324/1631	BRL	7/8/08	< 25.0	No	No	
TotalHg-ST5-7/5/08	0828004-04	Firehouse #10 (roof level)	7/5/08	0.56	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST10-7/5/08	0828004-05	North Side Sidewalk Bridge	7/5/08	0.55	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST11-7/5/08	0828004-06	90 Trinity Place (roof level)	7/5/08	0.55	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST12-7/5/08	0828004-07	110 Greenwich Street (roof level)	7/5/08	0.57	Mercury	EPA 324/1631	BRL	7/8/08	< 26.0	No	No	
TotalHg-ST13-7/5/08	0828004-08	Marriott Hotel, 38th Floor (roof level)	7/5/08	0.59	Mercury	EPA 324/1631	BRL	7/8/08	< 25.0	No	No	
TotalHg-ST14-7/5/08	0828004-09	West Face - South end at corner (scaffolding level)	7/5/08	0.58	Mercury	EPA 324/1631	BRL	7/8/08	< 26.0	No	No	
TotalHg-ST15-7/5/08	0828004-10	South Face - East end at corner (scaffolding level)	7/5/08	0.59	Mercury	EPA 324/1631	BRL	7/8/08	< 25.0	No	No	
TotalHg-ST16-7/5/08	0828004-11	East Face - North end at corner (scaffolding level)	7/5/08	0.54	Mercury	EPA 324/1631	BRL	7/8/08	< 28.0	No	No	
TotalHg-ST17-7/5/08	0828004-12	North Face - West end at corner (scaffolding level)	7/5/08	0.60	Mercury	EPA 324/1631	BRL	7/8/08	< 25.0	No	No	
TotalHg-ST1-7/6/08	0828005-01	Southwest Area (sidewalk bridge level)	7/6/08	0.53	Mercury	EPA 324/1631	BRL	7/8/08	< 28.0	No	No	
TotalHg-ST2-7/6/08	0828005-02	Southeast Area (sidewalk bridge level)	7/6/08	0.57	Mercury	EPA 324/1631	BRL	7/8/08	< 26.0	No	No	
TotalHg-ST4-7/6/08	0828005-03	Northwest Area (street-level)	7/6/08	0.57	Mercury	EPA 324/1631	BRL	7/8/08	< 26.0	No	No	
TotalHg-ST5-7/6/08	0828005-04	Firehouse #10 (roof level)	7/6/08	0.60	Mercury	EPA 324/1631	BRL	7/8/08	< 25.0	No	No	
TotalHg-ST10-7/6/08	0828005-05	North Side Sidewalk Bridge	7/6/08	0.54	Mercury	EPA 324/1631	BRL	7/8/08	< 28.0	No	No	
TotalHg-ST11-7/6/08	0828005-06	90 Trinity Place (roof level)	7/6/08	0.56	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST12-7/6/08	0828005-07	110 Greenwich Street (roof level)	7/6/08	0.55	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST13-7/6/08	0828005-08	Marriott Hotel, 38th Floor (roof level)	7/6/08	0.55	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST14-7/6/08	0828005-09	West Face - South end at corner (scaffolding level)	7/6/08	0.56	Mercury	EPA 324/1631	BRL	7/8/08	< 27.0	No	No	
TotalHg-ST15-7/6/08	0828005-10	South Face - East end at corner (scaffolding level)	7/6/08	0.60	Mercury	EPA 324/1631	BRL	7/8/08	< 25.0	No	No	
TotalHg-ST16-7/6/08	0828005-11	East Face - North end at corner (scaffolding level)	7/6/08	0.60	Mercury	EPA 324/1631	BRL	7/8/08	< 25.0	No	No	
TotalHg-ST17-7/6/08	0828005-12	North Face - West end at corner (scaffolding level)	7/6/08	0.60	Mercury	EPA 324/1631	BRL	7/8/08	< 25.0	No	No	