

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-9/29/06	06BR1572-01	Southwest Area (sidewalk bridge level)	9/29/06	0.57	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST2-9/29/06	06BR1572-02	Southeast Area (sidewalk bridge level)	9/29/06	0.57	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST4-9/29/06	06BR1572-03	Northwest Area (street-level)	9/29/06	0.57	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST5-9/29/06	06BR1572-04	Firehouse #10 (roof level)	9/29/06	0.57	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST10-9/29/06	06BR1572-05	North Side Sidewalk Bridge	9/29/06	0.57	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST11-9/29/06	06BR1572-06	90 Trinity Place (roof level)	9/29/06	0.57	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST12-9/29/06	06BR1572-07	110 Greenwich Street (roof level)	9/29/06	0.57	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST13-9/29/06	06BR1572-08	Marriott Hotel, 38th Floor (roof level)	9/29/06	0.56	Mercury	EPA 324/1631	BRL	10/3/06	< 27.0	No	No	
TotalHg-ST14-9/29/06	06BR1572-09	West Face - South end at corner (scaffolding level)	9/29/06	0.53	Mercury	EPA 324/1631	BRL	10/3/06	< 28.0	No	No	
TotalHg-ST15-9/29/06	06BR1572-10	South Face - East end at corner (scaffolding level)	9/29/06	0.53	Mercury	EPA 324/1631	BRL	10/3/06	< 28.0	No	No	
TotalHg-ST16-9/29/06	06BR1572-11	East Face - North end at corner (scaffolding level)	9/29/06	0.53	Mercury	EPA 324/1631	BRL	10/3/06	< 28.0	No	No	
TotalHg-ST17-9/29/06	06BR1572-12	North Face - West end at corner (scaffolding level)	9/29/06	0.53	Mercury	EPA 324/1631	BRL	10/3/06	< 28.0	No	No	
TotalHg-ST1-9/30/06	06BR1573-01	Southwest Area (sidewalk bridge level)	9/30/06	0.56	Mercury	EPA 324/1631	BRL	10/3/06	< 27.0	No	No	
TotalHg-ST2-9/30/06	06BR1573-02	Southeast Area (sidewalk bridge level)	9/30/06	0.56	Mercury	EPA 324/1631	BRL	10/3/06	< 27.0	No	No	
TotalHg-ST4-9/30/06	06BR1573-03	Northwest Area (street-level)	9/30/06	0.58	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST5-9/30/06	06BR1573-04	Firehouse #10 (roof level)	9/30/06	0.58	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST10-9/30/06	06BR1573-05	North Side Sidewalk Bridge	9/30/06	0.57	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST11-9/30/06	06BR1573-06	90 Trinity Place (roof level)	9/30/06	0.61	Mercury	EPA 324/1631	BRL	10/3/06	< 25.0	No	No	
TotalHg-ST12-9/30/06	06BR1573-07	110 Greenwich Street (roof level)	9/30/06	0.56	Mercury	EPA 324/1631	BRL	10/3/06	< 27.0	No	No	
TotalHg-ST13-9/30/06	06BR1573-08	Marriott Hotel, 38th Floor (roof level)	9/30/06	0.58	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST14-9/30/06	06BR1573-09	West Face - South end at corner (scaffolding level)	9/30/06	0.58	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST15-9/30/06	06BR1573-10	South Face - East end at corner (scaffolding level)	9/30/06	0.59	Mercury	EPA 324/1631	BRL	10/3/06	< 25.0	No	No	
TotalHg-ST16-9/30/06	06BR1573-11	East Face - North end at corner (scaffolding level)	9/30/06	0.59	Mercury	EPA 324/1631	BRL	10/3/06	< 25.0	No	No	
TotalHg-ST17-9/30/06	06BR1573-12	North Face - West end at corner (scaffolding level)	9/30/06	0.59	Mercury	EPA 324/1631	BRL	10/3/06	< 25.0	No	No	
TotalHg-ST1-10/1/06	06BR1574-01	Southwest Area (sidewalk bridge level)	10/1/06	0.58	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST2-10/1/06	06BR1574-02	Southeast Area (sidewalk bridge level)	10/1/06	0.58	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST4-10/1/06	06BR1574-03	Northwest Area (street-level)	10/1/06	0.55	Mercury	EPA 324/1631	BRL	10/3/06	< 27.0	No	No	
TotalHg-ST5-10/1/06	06BR1574-04	Firehouse #10 (roof level)	10/1/06	0.58	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST10-10/1/06	06BR1574-05	North Side Sidewalk Bridge	10/1/06	0.58	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST11-10/1/06	06BR1574-06	90 Trinity Place (roof level)	10/1/06	0.55	Mercury	EPA 324/1631	BRL	10/3/06	< 27.0	No	No	
TotalHg-ST12-10/1/06	06BR1574-07	110 Greenwich Street (roof level)	10/1/06	0.60	Mercury	EPA 324/1631	BRL	10/3/06	< 25.0	No	No	
TotalHg-ST13-10/1/06	06BR1574-08	Marriott Hotel, 38th Floor (roof level)	10/1/06	0.58	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST14-10/1/06	06BR1574-09	West Face - South end at corner (scaffolding level)	10/1/06	0.60	Mercury	EPA 324/1631	BRL	10/3/06	< 25.0	No	No	
TotalHg-ST15-10/1/06	06BR1574-10	South Face - East end at corner (scaffolding level)	10/1/06	0.59	Mercury	EPA 324/1631	BRL	10/3/06	< 25.0	No	No	
TotalHg-ST16-10/1/06	06BR1574-11	East Face - North end at corner (scaffolding level)	10/1/06	0.58	Mercury	EPA 324/1631	BRL	10/3/06	< 26.0	No	No	
TotalHg-ST17-10/1/06	06BR1574-12	North Face - West end at corner (scaffolding level)	10/1/06	0.60	Mercury	EPA 324/1631	BRL	10/3/06	< 25.0	No	No	