

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-10/1/08	0840039-01	Southwest Area (sidewalk bridge level)	10/1/08	0.55	Mercury	EPA 324/1631	BRL	10/3/08	< 27.0	No	No	
TotalHg-ST2-10/1/08	0840039-02	Southeast Area (sidewalk bridge level)	10/1/08	0.56	Mercury	EPA 324/1631	BRL	10/3/08	< 27.0	No	No	
TotalHg-ST4-10/1/08	0840039-03	Northwest Area (street-level)	10/1/08	0.54	Mercury	EPA 324/1631	BRL	10/3/08	< 28.0	No	No	
TotalHg-ST5-10/1/08	0840039-04	Firehouse #10 (roof level)	10/1/08	0.58	Mercury	EPA 324/1631	BRL	10/3/08	< 26.0	No	No	
TotalHg-ST10-10/1/08	0840039-05	North Side Sidewalk Bridge	10/1/08	0.57	Mercury	EPA 324/1631	BRL	10/3/08	< 26.0	No	No	
TotalHg-ST11-10/1/08	0840039-06	90 Trinity Place (roof level)	10/1/08	0.56	Mercury	EPA 324/1631	BRL	10/3/08	< 27.0	No	No	
TotalHg-ST12-10/1/08	0840039-07	110 Greenwich Street (roof level)	10/1/08	0.55	Mercury	EPA 324/1631	BRL	10/3/08	< 27.0	No	No	
TotalHg-ST13-10/1/08	0840039-08	Marriott Hotel, 38th Floor (roof level)	10/1/08	0.55	Mercury	EPA 324/1631	BRL	10/3/08	< 27.0	No	No	
TotalHg-ST14-10/1/08	0840039-09	West Face - South end at corner (scaffolding level)	10/1/08	0.57	Mercury	EPA 324/1631	BRL	10/3/08	< 26.0	No	No	
TotalHg-ST15-10/1/08	0840039-10	South Face - East end at corner (scaffolding level)	10/1/08	0.57	Mercury	EPA 324/1631	BRL	10/3/08	< 26.0	No	No	
TotalHg-ST16-10/1/08	0840039-11	East Face - North end at corner (scaffolding level)	10/1/08	0.58	Mercury	EPA 324/1631	BRL	10/3/08	< 26.0	No	No	
TotalHg-ST17-10/1/08	0840039-12	North Face - West end at corner (scaffolding level)	10/1/08	0.53	Mercury	EPA 324/1631	BRL	10/3/08	< 28.0	No	No	
TotalHg-ST1-10/2/08	0840050-01	Southwest Area (sidewalk bridge level)	10/2/08	0.57	Mercury	EPA 324/1631	BRL	10/4/08	< 26.0	No	No	
TotalHg-ST2-10/2/08	0840050-02	Southeast Area (sidewalk bridge level)	10/2/08	0.56	Mercury	EPA 324/1631	BRL	10/4/08	< 27.0	No	No	
TotalHg-ST4-10/2/08	0840050-03	Northwest Area (street-level)	10/2/08	0.52	Mercury	EPA 324/1631	BRL	10/4/08	< 29.0	No	No	
TotalHg-ST5-10/2/08	0840050-04	Firehouse #10 (roof level)	10/2/08	0.57	Mercury	EPA 324/1631	BRL	10/4/08	< 26.0	No	No	
TotalHg-ST10-10/2/08	0840050-05	North Side Sidewalk Bridge	10/2/08	0.54	Mercury	EPA 324/1631	BRL	10/4/08	< 28.0	No	No	
TotalHg-ST11-10/2/08	0840050-06	90 Trinity Place (roof level)	10/2/08	0.55	Mercury	EPA 324/1631	BRL	10/4/08	< 27.0	No	No	
TotalHg-ST12-10/2/08	0840050-07	110 Greenwich Street (roof level)	10/2/08	0.55	Mercury	EPA 324/1631	BRL	10/4/08	< 27.0	No	No	
TotalHg-ST13-10/2/08	0840050-08	Marriott Hotel, 38th Floor (roof level)	10/2/08	0.55	Mercury	EPA 324/1631	BRL	10/4/08	< 27.0	No	No	
TotalHg-ST14-10/2/08	0840050-09	West Face - South end at corner (scaffolding level)	10/2/08	0.57	Mercury	EPA 324/1631	BRL	10/4/08	< 26.0	No	No	
TotalHg-ST15-10/2/08	0840050-10	South Face - East end at corner (scaffolding level)	10/2/08	0.54	Mercury	EPA 324/1631	BRL	10/4/08	< 28.0	No	No	
TotalHg-ST16-10/2/08	0840050-11	East Face - North end at corner (scaffolding level)	10/2/08	0.57	Mercury	EPA 324/1631	BRL	10/4/08	< 26.0	No	No	
TotalHg-ST17-10/2/08	0840050-12	North Face - West end at corner (scaffolding level)	10/2/08	0.57	Mercury	EPA 324/1631	BRL	10/4/08	< 26.0	No	No	
TotalHg-ST1-10/3/08	0841001-01	Southwest Area (sidewalk bridge level)	10/3/08	0.58	Mercury	EPA 324/1631	BRL	10/6/08	< 26.0	No	No	
TotalHg-ST2-10/3/08	0841001-02	Southeast Area (sidewalk bridge level)	10/3/08	0.58	Mercury	EPA 324/1631	BRL	10/6/08	< 26.0	No	No	
TotalHg-ST4-10/3/08	0841001-03	Northwest Area (street-level)	10/3/08	0.55	Mercury	EPA 324/1631	BRL	10/6/08	< 27.0	No	No	
TotalHg-ST5-10/3/08	0841001-04	Firehouse #10 (roof level)	10/3/08	0.57	Mercury	EPA 324/1631	BRL	10/6/08	< 26.0	No	No	
TotalHg-ST10-10/3/08	0841001-05	North Side Sidewalk Bridge	10/3/08	0.55	Mercury	EPA 324/1631	BRL	10/6/08	< 27.0	No	No	
TotalHg-ST11-10/3/08	0841001-06	90 Trinity Place (roof level)	10/3/08	0.56	Mercury	EPA 324/1631	BRL	10/6/08	< 27.0	No	No	
TotalHg-ST12-10/3/08	0841001-07	110 Greenwich Street (roof level)	10/3/08	0.55	Mercury	EPA 324/1631	BRL	10/6/08	< 27.0	No	No	
TotalHg-ST13-10/3/08	0841001-08	Marriott Hotel, 38th Floor (roof level)	10/3/08	0.57	Mercury	EPA 324/1631	BRL	10/6/08	< 26.0	No	No	
TotalHg-ST14-10/3/08	0841001-09	West Face - South end at corner (scaffolding level)	10/3/08	0.53	Mercury	EPA 324/1631	BRL	10/6/08	< 28.0	No	No	
TotalHg-ST15-10/3/08	0841001-10	South Face - East end at corner (scaffolding level)	10/3/08	0.52	Mercury	EPA 324/1631	BRL	10/6/08	< 29.0	No	No	
TotalHg-ST16-10/3/08	0841001-11	East Face - North end at corner (scaffolding level)	10/3/08	0.54	Mercury	EPA 324/1631	BRL	10/6/08	< 28.0	No	No	
TotalHg-ST17-10/3/08	0841001-12	North Face - West end at corner (scaffolding level)	10/3/08	0.55	Mercury	EPA 324/1631	BRL	10/6/08	< 27.0	No	No	