

| TRC Field Sample No.  | Sample No. | Sampling Location                                   | Collection Start Date | Sample Volume (m <sup>3</sup> ) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Mercury (Total) Concentration (ng/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|-----------------------|------------|---|-----------------------|---------------------------------|---------|-------------------|-----|-------------------------|---------------------------------------|-----------------------------------|--|----------|
|                       |            |   |                       |                                 |         |                   |     |                         | 300                                   |                                   |  |          |
|                       |            |   |                       |                                 |         |                   |     |                         | 3,000                                 |                                   |  |          |
| TotalHg-ST1-10/04/07  | 0741001-01 | Southwest Area (sidewalk bridge level)              | 10/4/07               | 0.53                            | Mercury | EPA 324/1631      | BRL | 10/6/07                 | < 28.0                                | No                                | No                                       |          |
| TotalHg-ST2-10/04/07  | 0741001-02 | Southeast Area (sidewalk bridge level)              | 10/4/07               | 0.51                            | Mercury | EPA 324/1631      | BRL | 10/6/07                 | < 29.0                                | No                                | No                                       | Note 1   |
| TotalHg-ST4-10/04/07  | 0741001-03 | Northwest Area (street-level)                       | 10/4/07               | 0.60                            | Mercury | EPA 324/1631      | BRL | 10/6/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST5-10/04/07  | 0741001-04 | Firehouse #10 (roof level)                          | 10/4/07               | 0.58                            | Mercury | EPA 324/1631      | BRL | 10/6/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST10-10/04/07 | 0741001-05 | North Side Sidewalk Bridge                          | 10/4/07               | 0.60                            | Mercury | EPA 324/1631      | BRL | 10/6/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST11-10/04/07 | 0741001-06 | 90 Trinity Place (roof level)                       | 10/4/07               | 0.56                            | Mercury | EPA 324/1631      | BRL | 10/6/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST12-10/04/07 | 0741001-07 | 110 Greenwich Street (roof level)                   | 10/4/07               | 0.61                            | Mercury | EPA 324/1631      | BRL | 10/6/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST13-10/04/07 | 0741001-08 | Marriott Hotel, 38th Floor (roof level)             | 10/4/07               | 0.57                            | Mercury | EPA 324/1631      | BRL | 10/6/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST14-10/04/07 | 0741001-09 | West Face - South end at corner (scaffolding level) | 10/4/07               | 0.56                            | Mercury | EPA 324/1631      | BRL | 10/6/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST15-10/04/07 | 0741001-10 | South Face - East end at corner (scaffolding level) | 10/4/07               | 0.56                            | Mercury | EPA 324/1631      | BRL | 10/6/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST16-10/04/07 | 0741001-11 | East Face - North end at corner (scaffolding level) | 10/4/07               | 0.56                            | Mercury | EPA 324/1631      | BRL | 10/6/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST17-10/04/07 | 0741001-12 | North Face - West end at corner (scaffolding level) | 10/4/07               | 0.54                            | Mercury | EPA 324/1631      | BRL | 10/6/07                 | < 28.0                                | No                                | No                                       |          |
| TotalHg-ST1-10/05/07  | 0741002-01 | Southwest Area (sidewalk bridge level)              | 10/5/07               | 0.57                            | Mercury | EPA 324/1631      | BRL | 10/8/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST2-10/05/07  | 0741002-02 | Southeast Area (sidewalk bridge level)              | 10/5/07               | 0.59                            | Mercury | EPA 324/1631      | BRL | 10/8/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST4-10/05/07  | 0741002-03 | Northwest Area (street-level)                       | 10/5/07               | 0.59                            | Mercury | EPA 324/1631      | BRL | 10/8/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST5-10/05/07  | 0741002-04 | Firehouse #10 (roof level)                          | 10/5/07               | 0.58                            | Mercury | EPA 324/1631      | BRL | 10/8/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST10-10/05/07 | 0741002-05 | North Side Sidewalk Bridge                          | 10/5/07               | 0.56                            | Mercury | EPA 324/1631      | BRL | 10/8/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST11-10/05/07 | 0741002-06 | 90 Trinity Place (roof level)                       | 10/5/07               | 0.55                            | Mercury | EPA 324/1631      | BRL | 10/8/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST12-10/05/07 | 0741002-07 | 110 Greenwich Street (roof level)                   | 10/5/07               | 0.59                            | Mercury | EPA 324/1631      | BRL | 10/8/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST13-10/05/07 | 0741002-08 | Marriott Hotel, 38th Floor (roof level)             | 10/5/07               | 0.56                            | Mercury | EPA 324/1631      | BRL | 10/8/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST14-10/05/07 | 0741002-09 | West Face - South end at corner (scaffolding level) | 10/5/07               | 0.54                            | Mercury | EPA 324/1631      | BRL | 10/8/07                 | < 28.0                                | No                                | No                                       |          |
| TotalHg-ST15-10/05/07 | 0741002-10 | South Face - East end at corner (scaffolding level) | 10/5/07               | 0.46                            | Mercury | EPA 324/1631      | BRL | 10/8/07                 | < 33.0                                | No                                | No                                       | Note 2   |
| TotalHg-ST16-10/05/07 | 0741002-11 | East Face - North end at corner (scaffolding level) | 10/5/07               | 0.52                            | Mercury | EPA 324/1631      | BRL | 10/8/07                 | < 29.0                                | No                                | No                                       |          |
| TotalHg-ST17-10/05/07 | 0741002-12 | North Face - West end at corner (scaffolding level) | 10/5/07               | 0.54                            | Mercury | EPA 324/1631      | BRL | 10/8/07                 | < 28.0                                | No                                | No                                       |          |

Note:

1. Due to flow rate RPD exceedance (25.4%) for mercury at Station 2 (Southeast Area [sidewalk bridge level]) on October 4, 2007, the sample volume and subsequent sample result are estimated.
2. Due to flow rate RPD exceedance (38.8%) for mercury at Station 15 (South Face - East end at corner [scaffolding level]) on October 5, 2007, the sample volume and subsequent sample result are estimated.