

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-10/11/06	06BR1645-01	Southwest Area (sidewalk bridge level)	10/11/06	0.59	Mercury	EPA 324/1631	BRL	10/13/06	< 25.0	No	No	
TotalHg-ST2-10/11/06	06BR1645-02	Southeast Area (sidewalk bridge level)	10/11/06	0.58	Mercury	EPA 324/1631	BRL	10/13/06	< 26.0	No	No	
TotalHg-ST4-10/11/06	06BR1645-03	Northwest Area (street-level)	10/11/06	0.61	Mercury	EPA 324/1631	BRL	10/13/06	< 25.0	No	No	
TotalHg-ST5-10/11/06	06BR1645-04	Firehouse #10 (roof level)	10/11/06	0.60	Mercury	EPA 324/1631	BRL	10/13/06	< 25.0	No	No	
TotalHg-ST10-10/11/06	06BR1645-05	North Side Sidewalk Bridge	10/11/06	0.59	Mercury	EPA 324/1631	BRL	10/13/06	< 25.0	No	No	
TotalHg-ST11-10/11/06	06BR1645-06	90 Trinity Place (roof level)	10/11/06	0.57	Mercury	EPA 324/1631	BRL	10/13/06	< 26.0	No	No	
TotalHg-ST12-10/11/06	06BR1645-07	110 Greenwich Street (roof level)	10/11/06	0.57	Mercury	EPA 324/1631	BRL	10/13/06	< 26.0	No	No	
TotalHg-ST13-10/11/06	06BR1645-08	Marriott Hotel, 38th Floor (roof level)	10/11/06	0.58	Mercury	EPA 324/1631	BRL	10/13/06	< 26.0	No	No	
TotalHg-ST14-10/11/06	06BR1645-09	West Face - South end at corner (scaffolding level)	10/11/06	0.55	Mercury	EPA 324/1631	BRL	10/13/06	< 27.0	No	No	
TotalHg-ST15-10/11/06	06BR1645-10	South Face - East end at corner (scaffolding level)	10/11/06	0.58	Mercury	EPA 324/1631	BRL	10/13/06	< 26.0	No	No	
TotalHg-ST16-10/11/06	06BR1645-11	East Face - North end at corner (scaffolding level)	10/11/06	0.58	Mercury	EPA 324/1631	BRL	10/13/06	< 26.0	No	No	
TotalHg-ST17-10/11/06	06BR1645-12	North Face - West end at corner (scaffolding level)	10/11/06	0.58	Mercury	EPA 324/1631	BRL	10/13/06	< 26.0	No	No	
TotalHg-ST1-10/12/06	06BR1650-01	Southwest Area (sidewalk bridge level)	10/12/06	0.57	Mercury	EPA 324/1631	BRL	10/16/06	< 26.0	No	No	
TotalHg-ST2-10/12/06	06BR1650-02	Southeast Area (sidewalk bridge level)	10/12/06	0.58	Mercury	EPA 324/1631	BRL	10/16/06	< 26.0	No	No	
TotalHg-ST4-10/12/06	06BR1650-03	Northwest Area (street-level)	10/12/06	0.57	Mercury	EPA 324/1631	BRL	10/16/06	< 26.0	No	No	
TotalHg-ST5-10/12/06	06BR1650-04	Firehouse #10 (roof level)	10/12/06	0.58	Mercury	EPA 324/1631	BRL	10/16/06	< 26.0	No	No	
TotalHg-ST10-10/12/06	06BR1650-05	North Side Sidewalk Bridge	10/12/06	0.56	Mercury	EPA 324/1631	BRL	10/16/06	< 27.0	No	No	
TotalHg-ST11-10/12/06	06BR1650-06	90 Trinity Place (roof level)	10/12/06	0.57	Mercury	EPA 324/1631	BRL	10/16/06	< 26.0	No	No	
TotalHg-ST12-10/12/06	06BR1650-07	110 Greenwich Street (roof level)	10/12/06	0.58	Mercury	EPA 324/1631	BRL	10/16/06	< 26.0	No	No	
TotalHg-ST13-10/12/06	06BR1650-08	Marriott Hotel, 38th Floor (roof level)	10/12/06	0.58	Mercury	EPA 324/1631	BRL	10/16/06	< 26.0	No	No	
TotalHg-ST14-10/12/06	06BR1650-09	West Face - South end at corner (scaffolding level)	10/12/06	0.58	Mercury	EPA 324/1631	BRL	10/16/06	< 26.0	No	No	
TotalHg-ST15-10/12/06	06BR1650-10	South Face - East end at corner (scaffolding level)	10/12/06	0.58	Mercury	EPA 324/1631	BRL	10/16/06	< 26.0	No	No	
TotalHg-ST16-10/12/06	06BR1650-11	East Face - North end at corner (scaffolding level)	10/12/06	0.56	Mercury	EPA 324/1631	BRL	10/16/06	< 27.0	No	No	
TotalHg-ST17-10/12/06	06BR1650-12	North Face - West end at corner (scaffolding level)	10/12/06	0.58	Mercury	EPA 324/1631	BRL	10/16/06	< 26.0	No	No	