

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target	Exceeds EPA	Comments
									300	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
Target Air Quality Levels									3,000			
EPA Site Specific Trigger Levels												
TotalHg-ST1-10/26/07	0744004-01	Southwest Area (sidewalk bridge level)	10/26/07	0.54	Mercury	EPA 324/1631	BRL	10/30/07	< 28.0	No	No	
TotalHg-ST2-10/26/07	0744004-02	Southeast Area (sidewalk bridge level)	10/26/07	0.59	Mercury	EPA 324/1631	BRL	10/30/07	< 25.0	No	No	
TotalHg-ST4-10/26/07	0744004-03	Northwest Area (street-level)	10/26/07	0.55	Mercury	EPA 324/1631	BRL	10/30/07	< 27.0	No	No	
TotalHg-ST5-10/26/07	0744004-04	Firehouse #10 (roof level)	10/26/07	0.54	Mercury	EPA 324/1631	BRL	10/30/07	< 28.0	No	No	
TotalHg-ST10-10/26/07	0744004-05	North Side Sidewalk Bridge	10/26/07	0.59	Mercury	EPA 324/1631	BRL	10/30/07	< 25.0	No	No	
TotalHg-ST11-10/26/07	0744004-06	90 Trinity Place (roof level)	10/26/07	0.57	Mercury	EPA 324/1631	BRL	10/30/07	< 26.0	No	No	
TotalHg-ST12-10/26/07	0744004-07	110 Greenwich Street (roof level)	10/26/07	0.52	Mercury	EPA 324/1631	BRL	10/30/07	< 29.0	No	No	
TotalHg-ST13-10/26/07	0744004-08	Marriott Hotel, 38th Floor (roof level)	10/26/07	0.57	Mercury	EPA 324/1631	BRL	10/30/07	< 26.0	No	No	
TotalHg-ST14-10/26/07	0744004-09	West Face - South end at corner (scaffolding level)	10/26/07	0.50	Mercury	EPA 324/1631	BRL	10/30/07	< 30.0	No	No	
TotalHg-ST15-10/26/07	0744004-10	South Face - East end at corner (scaffolding level)	10/26/07	0.56	Mercury	EPA 324/1631	BRL	10/30/07	< 27.0	No	No	
TotalHg-ST16-10/26/07	0744004-11	East Face - North end at corner (scaffolding level)	10/26/07	0.54	Mercury	EPA 324/1631	BRL	10/30/07	< 28.0	No	No	
TotalHg-ST17-10/26/07	0744004-12	North Face - West end at corner (scaffolding level)	10/26/07	0.53	Mercury	EPA 324/1631	BRL	10/30/07	< 28.0	No	No	
TotalHg-ST1-10/27/07	0744006-01	Southwest Area (sidewalk bridge level)	10/27/07	0.53	Mercury	EPA 324/1631	BRL	10/30/07	< 28.0	No	No	
TotalHg-ST2-10/27/07	0744006-02	Southeast Area (sidewalk bridge level)	10/27/07	0.54	Mercury	EPA 324/1631	BRL	10/30/07	< 28.0	No	No	
TotalHg-ST4-10/27/07	0744006-03	Northwest Area (street-level)	10/27/07	0.56	Mercury	EPA 324/1631	BRL	10/30/07	< 27.0	No	No	
TotalHg-ST5-10/27/07	0744006-04	Firehouse #10 (roof level)	10/27/07	0.57	Mercury	EPA 324/1631	BRL	10/30/07	< 26.0	No	No	
TotalHg-ST10-10/27/07	0744006-05	North Side Sidewalk Bridge	10/27/07	0.55	Mercury	EPA 324/1631	BRL	10/30/07	< 27.0	No	No	
TotalHg-ST11-10/27/07	0744006-06	90 Trinity Place (roof level)	10/27/07	0.55	Mercury	EPA 324/1631	BRL	10/30/07	< 27.0	No	No	
TotalHg-ST12-10/27/07	0744006-07	110 Greenwich Street (roof level)	10/27/07	0.56	Mercury	EPA 324/1631	BRL	10/30/07	< 27.0	No	No	
TotalHg-ST13-10/27/07	0744006-08	Marriott Hotel, 38th Floor (roof level)	10/27/07	0.58	Mercury	EPA 324/1631	BRL	10/30/07	< 26.0	No	No	
TotalHg-ST14-10/27/07	0744006-09	West Face - South end at corner (scaffolding level)	10/27/07	0.55	Mercury	EPA 324/1631	BRL	10/30/07	< 27.0	No	No	
TotalHg-ST15-10/27/07	0744006-10	South Face - East end at corner (scaffolding level)	10/27/07	0.58	Mercury	EPA 324/1631	BRL	10/30/07	< 26.0	No	No	
TotalHg-ST16-10/27/07	0744006-11	East Face - North end at corner (scaffolding level)	10/27/07	0.56	Mercury	EPA 324/1631	BRL	10/30/07	< 27.0	No	No	
TotalHg-ST17-10/27/07	0744006-12	North Face - West end at corner (scaffolding level)	10/27/07	0.56	Mercury	EPA 324/1631	BRL	10/30/07	< 27.0	No	No	
TotalHg-ST1-10/28/07	0744008-01	Southwest Area (sidewalk bridge level)	10/28/07	0.59	Mercury	EPA 324/1631	BRL	10/30/07	< 25.0	No	No	
TotalHg-ST2-10/28/07	0744008-02	Southeast Area (sidewalk bridge level)	10/28/07	0.61	Mercury	EPA 324/1631	BRL	10/30/07	< 25.0	No	No	
TotalHg-ST4-10/28/07	0744008-03	Northwest Area (street-level)	10/28/07	0.59	Mercury	EPA 324/1631	BRL	10/30/07	< 25.0	No	No	
TotalHg-ST5-10/28/07	0744008-04	Firehouse #10 (roof level)	10/28/07	0.58	Mercury	EPA 324/1631	BRL	10/30/07	< 26.0	No	No	
TotalHg-ST10-10/28/07	0744008-05	North Side Sidewalk Bridge	10/28/07	0.61	Mercury	EPA 324/1631	BRL	10/30/07	< 25.0	No	No	
TotalHg-ST11-10/28/07	0744008-06	90 Trinity Place (roof level)	10/28/07	0.56	Mercury	EPA 324/1631	BRL	10/30/07	< 27.0	No	No	
TotalHg-ST12-10/28/07	0744008-07	110 Greenwich Street (roof level)	10/28/07	0.57	Mercury	EPA 324/1631	BRL	10/30/07	< 26.0	No	No	
TotalHg-ST13-10/28/07	0744008-08	Marriott Hotel, 38th Floor (roof level)	10/28/07	0.56	Mercury	EPA 324/1631	BRL	10/30/07	< 27.0	No	No	
TotalHg-ST14-10/28/07	0744008-09	West Face - South end at corner (scaffolding level)	10/28/07	0.63	Mercury	EPA 324/1631	BRL	10/30/07	< 24.0	No	No	
TotalHg-ST15-10/28/07	0744008-10	South Face - East end at corner (scaffolding level)	10/28/07	0.61	Mercury	EPA 324/1631	BRL	10/30/07	< 25.0	No	No	
TotalHg-ST16-10/28/07	0744008-11	East Face - North end at corner (scaffolding level)	10/28/07	0.58	Mercury	EPA 324/1631	BRL	10/30/07	< 26.0	No	No	
TotalHg-ST17-10/28/07	0744008-12	North Face - West end at corner (scaffolding level)	10/28/07	0.56	Mercury	EPA 324/1631	BRL	10/30/07	< 27.0	No	No	