

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-11/08/06	06BR1787-01	Southwest Area (sidewalk bridge level)	11/8/06	0.56	Mercury	EPA 324/1631	BRL	11/10/06	< 27.0	No	No	
TotalHg-ST2-11/08/06	06BR1787-02	Southeast Area (sidewalk bridge level)	11/8/06	0.61	Mercury	EPA 324/1631	BRL	11/10/06	< 25.0	No	No	
TotalHg-ST4-11/08/06	06BR1787-03	Northwest Area (street-level)	11/8/06	0.60	Mercury	EPA 324/1631	BRL	11/10/06	< 25.0	No	No	
TotalHg-ST5-11/08/06	06BR1787-04	Firehouse #10 (roof level)	11/8/06	0.56	Mercury	EPA 324/1631	BRL	11/10/06	< 27.0	No	No	
TotalHg-ST10-11/08/06	06BR1787-05	North Side Sidewalk Bridge	11/8/06	0.58	Mercury	EPA 324/1631	BRL	11/10/06	< 26.0	No	No	
TotalHg-ST11-11/08/06	06BR1787-06	90 Trinity Place (roof level)	11/8/06	0.58	Mercury	EPA 324/1631	BRL	11/10/06	< 26.0	No	No	
TotalHg-ST12-11/08/06	06BR1787-07	110 Greenwich Street (roof level)	11/8/06	0.60	Mercury	EPA 324/1631	BRL	11/10/06	< 25.0	No	No	
TotalHg-ST13-11/08/06	06BR1787-08	Marriott Hotel, 38th Floor (roof level)	11/8/06	0.55	Mercury	EPA 324/1631	BRL	11/10/06	< 27.0	No	No	
TotalHg-ST14-11/08/06	06BR1787-09	West Face - South end at corner (scaffolding level)	11/8/06	0.61	Mercury	EPA 324/1631	BRL	11/10/06	< 25.0	No	No	
TotalHg-ST15-11/08/06	06BR1787-10	South Face - East end at corner (scaffolding level)	11/8/06	0.59	Mercury	EPA 324/1631	BRL	11/10/06	< 25.0	No	No	
TotalHg-ST16-11/08/06	06BR1787-11	East Face - North end at corner (scaffolding level)	11/8/06	0.55	Mercury	EPA 324/1631	BRL	11/10/06	< 27.0	No	No	
TotalHg-ST17-11/08/06	06BR1787-12	North Face - West end at corner (scaffolding level)	11/8/06	0.58	Mercury	EPA 324/1631	BRL	11/10/06	< 26.0	No	No	
TotalHg-ST1-11/09/06	06BR1792-01	Southwest Area (sidewalk bridge level)	11/9/06	0.57	Mercury	EPA 324/1631	BRL	11/11/06	< 26.0	No	No	
TotalHg-ST2-11/09/06	06BR1792-02	Southeast Area (sidewalk bridge level)	11/9/06	0.58	Mercury	EPA 324/1631	BRL	11/11/06	< 26.0	No	No	
TotalHg-ST4-11/09/06	06BR1792-03	Northwest Area (street-level)	11/9/06	0.57	Mercury	EPA 324/1631	BRL	11/11/06	< 26.0	No	No	
TotalHg-ST5-11/09/06	06BR1792-04	Firehouse #10 (roof level)	11/9/06	0.56	Mercury	EPA 324/1631	BRL	11/11/06	< 27.0	No	No	
TotalHg-ST10-11/09/06	06BR1792-05	North Side Sidewalk Bridge	11/9/06	0.58	Mercury	EPA 324/1631	BRL	11/11/06	< 26.0	No	No	
TotalHg-ST11-11/09/06	06BR1792-06	90 Trinity Place (roof level)	11/9/06	0.57	Mercury	EPA 324/1631	BRL	11/11/06	< 26.0	No	No	
TotalHg-ST12-11/09/06	06BR1792-07	110 Greenwich Street (roof level)	11/9/06	0.61	Mercury	EPA 324/1631	BRL	11/11/06	< 25.0	No	No	
TotalHg-ST13-11/09/06	06BR1792-08	Marriott Hotel, 38th Floor (roof level)	11/9/06	0.57	Mercury	EPA 324/1631	BRL	11/11/06	< 26.0	No	No	
TotalHg-ST14-11/09/06	06BR1792-09	West Face - South end at corner (scaffolding level)	11/9/06	0.57	Mercury	EPA 324/1631	BRL	11/11/06	< 26.0	No	No	
TotalHg-ST15-11/09/06	06BR1792-10	South Face - East end at corner (scaffolding level)	11/9/06	0.56	Mercury	EPA 324/1631	BRL	11/11/06	< 26.0	No	No	
TotalHg-ST16-11/09/06	06BR1792-11	East Face - North end at corner (scaffolding level)	11/9/06	0.63	Mercury	EPA 324/1631	BRL	11/11/06	< 24.0	No	No	
TotalHg-ST17-11/09/06	06BR1792-12	North Face - West end at corner (scaffolding level)	11/9/06	0.60	Mercury	EPA 324/1631	BRL	11/11/06	< 25.0	No	No	

Note:

- Mercury sample at Station 100 (Station 10 Field Duplicate) on November 8, 2006 was not available for analysis on account of pump failure.