

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-11/22/05	05BR1773-1	Southwest Area (sidewalk bridge level)	11/22/05	0.58	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST2-11/22/05	05BR1773-2	Southeast Area (sidewalk bridge level)	11/22/05	0.58	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST4-11/22/05	05BR1773-3	Northwest Area (street-level)	11/22/05	0.57	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST5-11/22/05	05BR1773-4	Firehouse #10 (roof level)	11/22/05	0.57	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST10-11/22/05	05BR1773-5	North Side Sidewalk Bridge	11/22/05	0.58	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST11-11/22/05	05BR1773-6	90 Trinity Place (roof level)	11/22/05	0.58	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST12-11/22/05	05BR1773-7	110 Greenwich Street (roof level)	11/22/05	0.58	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST13-11/22/05	05BR1773-8	Marriott Hotel, 38th Floor (roof level)	11/22/05	0.57	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST14-11/22/05	05BR1773-9	West Face - South end at corner (scaffolding level)	11/22/05	0.58	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST15-11/22/05	05BR1773-10	South Face - East end at corner (scaffolding level)	11/22/05	0.57	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST16-11/22/05	05BR1773-11	East Face - North end at corner (scaffolding level)	11/22/05	0.57	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST17-11/22/05	05BR1773-12	North Face - West end at corner (scaffolding level)	11/22/05	0.57	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST1-11/23/05	05BR1774-1	Southwest Area (sidewalk bridge level)	11/23/05	0.55	Mercury	EPA 324/1631	BRL	11/26/05	< 27.0	No	No	
TotalHg-ST2-11/23/05	05BR1774-2	Southeast Area (sidewalk bridge level)	11/23/05	0.56	Mercury	EPA 324/1631	BRL	11/26/05	< 27.0	No	No	
TotalHg-ST4-11/23/05	05BR1774-3	Northwest Area (street-level)	11/23/05	0.56	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST5-11/23/05	05BR1774-4	Firehouse #10 (roof level)	11/23/05	0.57	Mercury	EPA 324/1631	BRL	11/26/05	< 27.0	No	No	
TotalHg-ST10-11/23/05	05BR1774-5	North Side Sidewalk Bridge	11/23/05	0.56	Mercury	EPA 324/1631	BRL	11/26/05	< 27.0	No	No	
TotalHg-ST11-11/23/05	05BR1774-6	90 Trinity Place (roof level)	11/23/05	0.56	Mercury	EPA 324/1631	BRL	11/26/05	< 27.0	No	No	
TotalHg-ST12-11/23/05	05BR1774-7	110 Greenwich Street (roof level)	11/23/05	0.56	Mercury	EPA 324/1631	BRL	11/26/05	< 27.0	No	No	
TotalHg-ST13-11/23/05	05BR1774-8	Marriott Hotel, 38th Floor (roof level)	11/23/05	0.55	Mercury	EPA 324/1631	BRL	11/26/05	< 27.0	No	No	
TotalHg-ST14-11/23/05	05BR1774-9	West Face - South end at corner (scaffolding level)	11/23/05	0.60	Mercury	EPA 324/1631	BRL	11/26/05	< 25.0	No	No	
TotalHg-ST15-11/23/05	05BR1774-10	South Face - East end at corner (scaffolding level)	11/23/05	0.58	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST16-11/23/05	05BR1774-11	East Face - North end at corner (scaffolding level)	11/23/05	0.58	Mercury	EPA 324/1631	BRL	11/26/05	< 26.0	No	No	
TotalHg-ST17-11/23/05	05BR1774-12	North Face - West end at corner (scaffolding level)	11/23/05	0.59	Mercury	EPA 324/1631	BRL	11/26/05	< 25.0	No	No	
TotalHg-ST1-11/24/05	05BR1775-1	Southwest Area (sidewalk bridge level)	11/24/05	0.59	Mercury	EPA 324/1631	BRL	11/26/05	< 25.0	No	No	
TotalHg-ST2-11/24/05	05BR1775-2	Southeast Area (sidewalk bridge level)	11/24/05	0.59	Mercury	EPA 324/1631	BRL	11/26/05	< 25.0	No	No	
TotalHg-ST4-11/24/05	05BR1775-3	Northwest Area (street-level)	11/24/05	0.59	Mercury	EPA 324/1631	BRL	11/26/05	< 25.0	No	No	
TotalHg-ST5-11/24/05	05BR1775-4	Firehouse #10 (roof level)	11/24/05	0.66	Mercury	EPA 324/1631	BRL	11/26/05	< 23.0	No	No	
TotalHg-ST10-11/24/05	05BR1775-5	North Side Sidewalk Bridge	11/24/05	0.59	Mercury	EPA 324/1631	BRL	11/26/05	< 25.0	No	No	
TotalHg-ST11-11/24/05	05BR1775-6	90 Trinity Place (roof level)	11/24/05	0.60	Mercury	EPA 324/1631	BRL	11/26/05	< 25.0	No	No	
TotalHg-ST12-11/24/05	05BR1775-7	110 Greenwich Street (roof level)	11/24/05	0.60	Mercury	EPA 324/1631	BRL	11/26/05	< 25.0	No	No	
TotalHg-ST14-11/24/05	05BR1775-9	West Face - South end at corner (scaffolding level)	11/24/05	0.61	Mercury	EPA 324/1631	BRL	11/26/05	< 25.0	No	No	
TotalHg-ST15-11/24/05	05BR1775-10	South Face - East end at corner (scaffolding level)	11/24/05	0.60	Mercury	EPA 324/1631	BRL	11/26/05	< 25.0	No	No	
TotalHg-ST16-11/24/05	05BR1775-11	East Face - North end at corner (scaffolding level)	11/24/05	0.61	Mercury	EPA 324/1631	BRL	11/26/05	< 25.0	No	No	
TotalHg-ST17-11/24/05	05BR1775-12	North Face - West end at corner (scaffolding level)	11/24/05	0.61	Mercury	EPA 324/1631	BRL	11/26/05	< 25.0	No	No	Sample at Station 13 (Marriott Hotel, 38th Floor (roof level)) was deemed invalid on November 24, 2005 due to interruption of power and therefore was not submitted for analysis.