

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-11/25/05	05BR1782-1	Southwest Area (sidewalk bridge level)	11/25/05	0.26	Mercury	EPA 324/1631	BRL	11/29/05	< 58.0	No	No	
TotalHg-ST2-11/25/05	05BR1782-2	Southeast Area (sidewalk bridge level)	11/25/05	0.27	Mercury	EPA 324/1631	BRL	11/29/05	< 56.0	No	No	
TotalHg-ST4-11/25/05	05BR1782-3	Northwest Area (street-level)	11/25/05	0.26	Mercury	EPA 324/1631	BRL	11/29/05	< 58.0	No	No	
TotalHg-ST5-11/25/05	05BR1782-4	Firehouse #10 (roof level)	11/25/05	0.22	Mercury	EPA 324/1631	BRL	11/29/05	< 68.0	No	No	
TotalHg-ST10-11/25/05	05BR1782-5	North Side Sidewalk Bridge	11/25/05	0.26	Mercury	EPA 324/1631	BRL	11/29/05	< 58.0	No	No	
TotalHg-ST11-11/25/05	05BR1782-10	90 Trinity Place (roof level)	11/25/05	0.58	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST12-11/25/05	05BR1782-11	110 Greenwich Street (roof level)	11/25/05	0.58	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST13-11/25/05	05BR1782-12	Marriott Hotel, 38th Floor (roof level)	11/25/05	0.52	Mercury	EPA 324/1631	BRL	11/29/05	< 29.0	No	No	
TotalHg-ST14-11/25/05	05BR1782-6	West Face - South end at corner (scaffolding level)	11/25/05	0.22	Mercury	EPA 324/1631	BRL	11/29/05	< 68.0	No	No	
TotalHg-ST15-11/25/05	05BR1782-7	South Face - East end at corner (scaffolding level)	11/25/05	0.25	Mercury	EPA 324/1631	BRL	11/29/05	N/A	No	No	1
TotalHg-ST16-11/25/05	05BR1782-8	East Face - North end at corner (scaffolding level)	11/25/05	0.24	Mercury	EPA 324/1631	BRL	11/29/05	< 63.0	No	No	
TotalHg-ST17-11/25/05	05BR1782-9	North Face - West end at corner (scaffolding level)	11/25/05	0.23	Mercury	EPA 324/1631	BRL	11/29/05	< 65.0	No	No	
TotalHg-ST1-11/26/05	05BR1791-1	Southwest Area (sidewalk bridge level)	11/26/05	0.26	Mercury	EPA 324/1631	BRL	11/29/05	< 58.0	No	No	
TotalHg-ST2-11/26/05	05BR1791-2	Southeast Area (sidewalk bridge level)	11/26/05	0.56	Mercury	EPA 324/1631	BRL	11/29/05	< 27.0	No	No	
TotalHg-ST4-11/26/05	05BR1791-3	Northwest Area (street-level)	11/26/05	0.56	Mercury	EPA 324/1631	BRL	11/29/05	< 27.0	No	No	
TotalHg-ST5-11/26/05	05BR1791-4	Firehouse #10 (roof level)	11/26/05	0.56	Mercury	EPA 324/1631	BRL	11/29/05	< 27.0	No	No	
TotalHg-ST10-11/26/05	05BR1791-5	North Side Sidewalk Bridge	11/26/05	0.56	Mercury	EPA 324/1631	BRL	11/29/05	< 27.0	No	No	
TotalHg-ST11-11/26/05	05BR1791-6	90 Trinity Place (roof level)	11/26/05	0.57	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST12-11/26/05	05BR1791-7	110 Greenwich Street (roof level)	11/26/05	0.54	Mercury	EPA 324/1631	BRL	11/29/05	< 28.0	No	No	
TotalHg-ST13-11/26/05	05BR1791-8	Marriott Hotel, 38th Floor (roof level)	11/26/05	0.55	Mercury	EPA 324/1631	BRL	11/29/05	< 27.0	No	No	
TotalHg-ST14-11/26/05	05BR1791-9	West Face - South end at corner (scaffolding level)	11/26/05	0.60	Mercury	EPA 324/1631	BRL	11/29/05	< 25.0	No	No	
TotalHg-ST15-11/26/05	05BR1791-10	South Face - East end at corner (scaffolding level)	11/26/05	0.57	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST16-11/26/05	05BR1791-11	East Face - North end at corner (scaffolding level)	11/26/05	0.58	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST17-11/26/05	05BR1791-12	North Face - West end at corner (scaffolding level)	11/26/05	0.60	Mercury	EPA 324/1631	BRL	11/29/05	< 25.0	No	No	
TotalHg-ST1-11/27/05	05BR1792-1	Southwest Area (sidewalk bridge level)	11/27/05	0.57	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST2-11/27/05	05BR1792-2	Southeast Area (sidewalk bridge level)	11/27/05	0.58	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST4-11/27/05	05BR1792-3	Northwest Area (street-level)	11/27/05	0.58	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST5-11/27/05	05BR1792-4	Firehouse #10 (roof level)	11/27/05	0.57	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST10-11/27/05	05BR1792-5	North Side Sidewalk Bridge	11/27/05	0.56	Mercury	EPA 324/1631	BRL	11/29/05	< 27.0	No	No	
TotalHg-ST11-11/27/05	05BR1792-6	90 Trinity Place (roof level)	11/27/05	0.57	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST12-11/27/05	05BR1792-7	110 Greenwich Street (roof level)	11/27/05	0.60	Mercury	EPA 324/1631	BRL	11/29/05	< 25.0	No	No	
TotalHg-ST13-11/27/05	05BR1792-8	Marriott Hotel, 38th Floor (roof level)	11/27/05	0.58	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST14-11/27/05	05BR1792-9	West Face - South end at corner (scaffolding level)	11/27/05	0.58	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST15-11/27/05	05BR1792-10	South Face - East end at corner (scaffolding level)	11/27/05	0.57	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST16-11/27/05	05BR1792-11	East Face - North end at corner (scaffolding level)	11/27/05	0.57	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST17-11/27/05	05BR1792-12	North Face - West end at corner (scaffolding level)	11/27/05	0.58	Mercury	EPA 324/1631	BRL	11/29/05	< 26.0	No	No	
TotalHg-ST1-11/28/05	05BR1793-1	Southwest Area (sidewalk bridge level)	11/28/05	0.57	Mercury	EPA 324/1631	BRL	11/30/05	< 26.0	No	No	
TotalHg-ST2-11/28/05	05BR1793-2	Southeast Area (sidewalk bridge level)	11/28/05	0.56	Mercury	EPA 324/1631	BRL	11/30/05	< 27.0	No	No	
TotalHg-ST4-11/28/05	05BR1793-3	Northwest Area (street-level)	11/28/05	0.56	Mercury	EPA 324/1631	BRL	11/30/05	< 27.0	No	No	
TotalHg-ST5-11/28/05	05BR1793-4	Firehouse #10 (roof level)	11/28/05	0.51	Mercury	EPA 324/1631	BRL	11/30/05	< 29.0	No	No	
TotalHg-ST10-11/28/05	05BR1793-5	North Side Sidewalk Bridge	11/28/05	0.58	Mercury	EPA 324/1631	BRL	11/30/05	< 26.0	No	No	
TotalHg-ST11-11/28/05	05BR1793-6	90 Trinity Place (roof level)	11/28/05	0.58	Mercury	EPA 324/1631	BRL	11/30/05	< 26.0	No	No	
TotalHg-ST12-11/28/05	05BR1793-7	110 Greenwich Street (roof level)	11/28/05	0.58	Mercury	EPA 324/1631	BRL	11/30/05	< 26.0	No	No	
TotalHg-ST13-11/28/05	05BR1793-8	Marriott Hotel, 38th Floor (roof level)	11/28/05	0.54	Mercury	EPA 324/1631	BRL	11/30/05	< 28.0	No	No	
TotalHg-ST14-11/28/05	05BR1793-9	West Face - South end at corner (scaffolding level)	11/28/05	0.57	Mercury	EPA 324/1631	BRL	11/30/05	< 26.0	No	No	
TotalHg-ST15-11/28/05	05BR1793-10	South Face - East end at corner (scaffolding level)	11/28/05	0.57	Mercury	EPA 324/1631	BRL	11/30/05	< 26.0	No	No	
TotalHg-ST16-11/28/05	05BR1793-11	East Face - North end at corner (scaffolding level)	11/28/05	0.57	Mercury	EPA 324/1631	BRL	11/30/05	< 26.0	No	No	
TotalHg-ST17-11/28/05	05BR1793-12	North Face - West end at corner (scaffolding level)	11/28/05	0.57	Mercury	EPA 324/1631	BRL	11/30/05	< 26.0	No	No	
TotalHg-ST1-11/29/05	05BR1801-1	Southwest Area (sidewalk bridge level)	11/29/05	0.56	Mercury	EPA 324/1631	BRL	12/1/05	< 27.0	No	No	
TotalHg-ST2-11/29/05	05BR1801-2	Southeast Area (sidewalk bridge level)	11/29/05	0.56	Mercury	EPA 324/1631	BRL	12/1/05	< 27.0	No	No	
TotalHg-ST4-11/29/05	05BR1801-3	Northwest Area (street-level)	11/29/05	0.57	Mercury	EPA 324/1631	BRL	12/1/05	< 26.0	No	No	
TotalHg-ST5-11/29/05	05BR1801-4	Firehouse #10 (roof level)	11/29/05	0.44	Mercury	EPA 324/1631	BRL	12/1/05	< 34.0	No	No	
TotalHg-ST11-11/29/05	05BR1801-6	90 Trinity Place (roof level)	11/29/05	0.58	Mercury	EPA 324/1631	BRL	12/1/05	< 26.0	No	No	
TotalHg-ST12-11/29/05	05BR1801-7	110 Greenwich Street (roof level)	11/29/05	0.60	Mercury	EPA 324/1631	BRL	12/1/05	< 25.0	No	No	
TotalHg-ST13-11/29/05	05BR1801-8	Marriott Hotel, 38th Floor (roof level)	11/29/05	0.56	Mercury	EPA 324/1631	BRL	12/1/05	< 27.0	No	No	
TotalHg-ST14-11/29/05	05BR1801-9	West Face - South end at corner (scaffolding level)	11/29/05	0.58	Mercury	EPA 324/1631	BRL	12/1/05	< 26.0	No	No	
TotalHg-ST15-11/29/05	05BR1801-10	South Face - East end at corner (scaffolding level)	11/29/05	0.59	Mercury	EPA 324/1631	BRL	12/1/05	< 25.0	No	No	
TotalHg-ST16-11/29/05	05BR1801-11	East Face - North end at corner (scaffolding level)	11/29/05	0.59	Mercury	EPA 324/1631	BRL	12/1/05	< 25.0	No	No	
TotalHg-ST17-11/29/05	05BR1801-12	North Face - West end at corner (scaffolding level)	11/29/05	0.58	Mercury	EPA 324/1631	BRL	12/1/05	< 26.0	No	No	
TotalHg-ST1-11/30/05	05BR1815-1	Southwest Area (sidewalk bridge level)	11/30/05	0.57	Mercury	EPA 324/1631	BRL	12/3/05	< 26.0	No	No	
TotalHg-ST2-11/30/05	05BR1815-2	Southeast Area (sidewalk bridge level)	11/30/05	0.58	Mercury	EPA 324/1631	BRL	12/3/05	< 26.0	No	No	
TotalHg-ST4-11/30/05	05BR1815-3	Northwest Area (street-level)	11/30/05	0.58	Mercury	EPA 324/1631	BRL	12/3/05	< 26.0	No	No	
TotalHg-ST5-11/30/05	05BR1815-4	Firehouse #10 (roof level)	11/30/05	0.51	Mercury	EPA 324/1631	BRL	12/3/05	< 26.0	No	No	
TotalHg-ST10-11/30/05	05BR1815-5	North Side Sidewalk Bridge	11/30/05	0.58	Mercury	EPA 324/1631	BRL	12/3/05	< 26.0	No	No	
TotalHg-ST11-11/30/05	05BR1815-6	90 Trinity Place (roof level)	11/30/05	0.54	Mercury	EPA 324/1631	BRL	12/3/05	< 28.0	No	No	
TotalHg-ST12-11/30/05	05BR1815-7	110 Greenwich Street (roof level)	11/30/05	0.50	Mercury	EPA 324/1631	BRL	12/3/05	< 30.0	No	No	
TotalHg-ST13-11/30/05	05BR1815-8	Marriott Hotel, 38th Floor (roof level)	11/30/05	0.49	Mercury	EPA 324/1631	BRL	12/3/05	< 31.0	No	No	
TotalHg-ST14-11/30/05	05BR1815-9	West Face - South end at corner (scaffolding level)	11/30/05	0.52	Mercury	EPA 324/1631	BRL	12/3/05	< 29.0	No	No	
TotalHg-ST15-11/30/05	05BR1815-10	South Face - East end at corner (scaffolding level)	11/30/05	0.57	Mercury	EPA 324/1631	BRL	12/3/05	< 26.0	No	No	
TotalHg-ST16-11/30/05	05BR1815-11	East Face - North end at corner (scaffolding level)	11/30/05	0.57	Mercury	EPA 324/1631	BRL	12/3/05	< 26.0	No	No	
TotalHg-ST17-11/30/05	05BR1815-12	North Face - West end at corner (scaffolding level)	11/30/05	0.58	Mercury	EPA 324/1631	BRL	12/3/05	< 26.0	No	No	
TotalHg-ST1-12/1/05	05BR1816-1	Southwest Area (sidewalk bridge level)	12/1/05	0.56	Mercury	EPA 324/1631	BRL	12/3/05	< 27.0	No	No	
TotalHg-ST4-12/1/05	05BR1816-2	Northwest Area (street-level)	12/1/05	0.55	Mercury	EPA 324/1631	BRL	12/3/05	< 27.0	No	No	
TotalHg-ST5-12/1/05	05BR1816-3	Firehouse #10 (roof level)	12/1/05	0.55	Mercury	EPA 324/1631	BRL	12/3/05	< 27.0	No	No	
TotalHg-ST10-12/1/05	05BR1816-4	North Side Sidewalk Bridge	12/1/05	0.60	Mercury	EPA 324/1631	BRL	12/3/05	< 25.0	No	No	
TotalHg-ST11-12/1/05	05BR1816-5	90 Trinity Place (roof level)	12/1/05	0.56	Mercury	EPA 324/1631	BRL	12/3/05	< 27.0	No	No	
TotalHg-ST12-12/1/05	05BR1816-6	110 Greenwich Street (roof level)	12/1/05	0.58	Mercury	EPA 324/1631	BRL	12/3/05	< 26.0	No	No	
TotalHg-ST13-12/1/05	05BR1816-7	Marriott Hotel, 38th Floor (roof level)	12/1/05	0.52	Mercury	EPA 324/1631	BRL	12/3/05	< 29.0	No	No	
TotalHg-ST14-12/1/05	05BR1816-8	West Face - South end at corner (scaffolding level)	12/1/05	0.51	Mercury	EPA 324/1631	BRL	12/3/05	< 26.0	No	No	
TotalHg-ST15-12/1/05	05BR1816-9	South Face - East end at corner (scaffolding level)	12/1/05	0.56	Mercury	EPA 324/1631	BRL	12/3/05	< 27.0	No	No	
TotalHg-ST16-12/1/05	05BR1816-10	East Face - North end at corner (scaffolding level)	12/1/05	0.56	Mercury	EPA 324/1631	BRL	12/3/05	< 27.0	No	No	
TotalHg-ST17-12/1/05	05BR1816-11	North Face - West end at corner (scaffolding level)	12/1/05	0.57	Mercury	EPA 324/1631	BRL	12/3/05	< 26.0	No	No	

- Notes:
- Mercury sample at Station 15 (South Face - East end at corner [scaffolding level]) on November 25, 2005 was not available for analysis on account of sample damage.
 - Mercury sample at Station 10 (North Side [sidewalk bridge level]) on November 29, 2005 was not available for analysis on account of pump failure.
 - Mercury sample at Station 2 (Southeast Area [sidewalk bridge level]) on December 1, 2005 was not available for analysis on account of pump failure.