

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-12/2/05	05BR1831-1	Southwest Area (sidewalk bridge level)	12/2/05	0.58	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	
TotalHg-ST2-12/2/05	05BR1831-2	Southeast Area (sidewalk bridge level)	12/2/05	0.57	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	
TotalHg-ST4-12/2/05	05BR1831-3	Northwest Area (street-level)	12/2/05	0.59	Mercury	EPA 324/1631	BRL	12/6/05	< 25.0	No	No	
TotalHg-ST5-12/2/05	05BR1831-4	Firehouse #10 (roof level)	12/2/05	0.54	Mercury	EPA 324/1631	BRL	12/6/05	< 28.0	No	No	
TotalHg-ST10-12/2/05	05BR1831-5	North Side Sidewalk Bridge	12/2/05	0.65	Mercury	EPA 324/1631	BRL	12/6/05	< 23.0	No	No	
TotalHg-ST11-12/2/05	05BR1831-6	90 Trinity Place (roof level)	12/2/05	0.64	Mercury	EPA 324/1631	BRL	12/6/05	< 23.0	No	No	
TotalHg-ST12-12/2/05	05BR1831-7	110 Greenwich Street (roof level)	12/2/05	0.55	Mercury	EPA 324/1631	BRL	12/6/05	< 27.0	No	No	
TotalHg-ST13-12/2/05	05BR1831-8	Marriott Hotel, 38th Floor (roof level)	12/2/05	0.52	Mercury	EPA 324/1631	BRL	12/6/05	< 29.0	No	No	
TotalHg-ST14-12/2/05	05BR1831-9	West Face - South end at corner (scaffolding level)	12/2/05	0.51	Mercury	EPA 324/1631	BRL	12/6/05	< 29.0	No	No	
TotalHg-ST15-12/2/05	05BR1831-10	South Face - East end at corner (scaffolding level)	12/2/05	0.58	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	
TotalHg-ST16-12/2/05	05BR1831-11	East Face - North end at corner (scaffolding level)	12/2/05	0.57	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	
TotalHg-ST17-12/2/05	05BR1831-12	North Face - West end at corner (scaffolding level)	12/2/05	0.56	Mercury	EPA 324/1631	BRL	12/6/05	< 27.0	No	No	
TotalHg-ST1-12/3/05	05BR1832-1	Southwest Area (sidewalk bridge level)	12/3/05	0.57	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	
TotalHg-ST2-12/3/05	05BR1832-2	Southeast Area (sidewalk bridge level)	12/3/05	0.56	Mercury	EPA 324/1631	BRL	12/6/05	< 27.0	No	No	
TotalHg-ST4-12/3/05	05BR1832-3	Northwest Area (street-level)	12/3/05	0.57	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	
TotalHg-ST5-12/3/05	05BR1832-4	Firehouse #10 (roof level)	12/3/05	0.59	Mercury	EPA 324/1631	BRL	12/6/05	< 25.0	No	No	
TotalHg-ST10-12/3/05	05BR1832-5	North Side Sidewalk Bridge	12/3/05	0.56	Mercury	EPA 324/1631	BRL	12/6/05	< 27.0	No	No	
TotalHg-ST11-12/3/05	05BR1832-6	90 Trinity Place (roof level)	12/3/05	0.50	Mercury	EPA 324/1631	BRL	12/6/05	< 30.0	No	No	
TotalHg-ST12-12/3/05	05BR1832-7	110 Greenwich Street (roof level)	12/3/05	0.56	Mercury	EPA 324/1631	BRL	12/6/05	< 27.0	No	No	
TotalHg-ST13-12/3/05	05BR1832-8	Marriott Hotel, 38th Floor (roof level)	12/3/05	0.57	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	
TotalHg-ST14-12/3/05	05BR1832-9	West Face - South end at corner (scaffolding level)	12/3/05	0.59	Mercury	EPA 324/1631	BRL	12/6/05	< 25.0	No	No	
TotalHg-ST15-12/3/05	05BR1832-10	South Face - East end at corner (scaffolding level)	12/3/05	0.58	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	
TotalHg-ST16-12/3/05	05BR1832-11	East Face - North end at corner (scaffolding level)	12/3/05	0.56	Mercury	EPA 324/1631	BRL	12/6/05	< 27.0	No	No	
TotalHg-ST17-12/3/05	05BR1832-12	North Face - West end at corner (scaffolding level)	12/3/05	0.58	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	
TotalHg-ST1-12/4/05	05BR1833-1	Southwest Area (sidewalk bridge level)	12/4/05	0.55	Mercury	EPA 324/1631	BRL	12/6/05	< 27.0	No	No	
TotalHg-ST2-12/4/05	05BR1833-2	Southeast Area (sidewalk bridge level)	12/4/05	0.56	Mercury	EPA 324/1631	BRL	12/6/05	< 27.0	No	No	
TotalHg-ST4-12/4/05	05BR1833-3	Northwest Area (street-level)	12/4/05	0.56	Mercury	EPA 324/1631	BRL	12/6/05	< 27.0	No	No	
TotalHg-ST5-12/4/05	05BR1833-4	Firehouse #10 (roof level)	12/4/05	0.58	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	
TotalHg-ST10-12/4/05	05BR1833-5	North Side Sidewalk Bridge	12/4/05	0.57	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	
TotalHg-ST11-12/4/05	05BR1833-6	90 Trinity Place (roof level)	12/4/05	0.56	Mercury	EPA 324/1631	BRL	12/6/05	< 27.0	No	No	
TotalHg-ST12-12/4/05	05BR1833-7	110 Greenwich Street (roof level)	12/4/05	0.58	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	
TotalHg-ST13-12/4/05	05BR1833-8	Marriott Hotel, 38th Floor (roof level)	12/4/05	0.57	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	
TotalHg-ST14-12/4/05	05BR1833-9	West Face - South end at corner (scaffolding level)	12/4/05	0.56	Mercury	EPA 324/1631	BRL	12/6/05	< 27.0	No	No	
TotalHg-ST15-12/4/05	05BR1833-10	South Face - East end at corner (scaffolding level)	12/4/05	0.59	Mercury	EPA 324/1631	BRL	12/6/05	< 25.0	No	No	
TotalHg-ST16-12/4/05	05BR1833-11	East Face - North end at corner (scaffolding level)	12/4/05	0.60	Mercury	EPA 324/1631	BRL	12/6/05	< 25.0	No	No	
TotalHg-ST17-12/4/05	05BR1833-12	North Face - West end at corner (scaffolding level)	12/4/05	0.57	Mercury	EPA 324/1631	BRL	12/6/05	< 26.0	No	No	