

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST2-12/22/05	05BR1958-1	Southeast Area (sidewalk bridge level)	12/22/05	0.54	Mercury	EPA 324/1631	BRL	12/28/05	< 28.0	No	No	
TotalHg-ST4-12/22/05	05BR1958-2	Northwest Area (street-level)	12/22/05	0.54	Mercury	EPA 324/1631	BRL	12/28/05	< 28.0	No	No	
TotalHg-ST5-12/22/05	05BR1958-3	Firehouse #10 (roof level)	12/22/05	0.56	Mercury	EPA 324/1631	BRL	12/28/05	< 27.0	No	No	
TotalHg-ST10-12/22/05	05BR1958-4	North Side Sidewalk Bridge	12/22/05	0.46	Mercury	EPA 324/1631	BRL	12/28/05	< 33.0	No	No	
TotalHg-ST11-12/22/05	05BR1958-5	90 Trinity Place (roof level)	12/22/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST12-12/22/05	05BR1958-6	110 Greenwich Street (roof level)	12/22/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST13-12/22/05	05BR1958-7	Marriott Hotel, 38th Floor (roof level)	12/22/05	0.60	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST14-12/22/05	05BR1958-8	West Face - South end at corner (scaffolding level)	12/22/05	0.61	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST15-12/22/05	05BR1958-9	South Face - East end at corner (scaffolding level)	12/22/05	0.61	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST16-12/22/05	05BR1958-10	East Face - North end at corner (scaffolding level)	12/22/05	0.61	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST17-12/22/05	05BR1958-11	North Face - West end at corner (scaffolding level)	12/22/05	0.61	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST1-12/23/05	05BR1959-1	Southwest Area (sidewalk bridge level)	12/23/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST2-12/23/05	05BR1959-2	Southeast Area (sidewalk bridge level)	12/23/05	0.57	Mercury	EPA 324/1631	BRL	12/28/05	< 26.0	No	No	
TotalHg-ST4-12/23/05	05BR1959-3	Northwest Area (street-level)	12/23/05	0.56	Mercury	EPA 324/1631	BRL	12/28/05	< 27.0	No	No	
TotalHg-ST5-12/23/05	05BR1959-4	Firehouse #10 (roof level)	12/23/05	0.41	Mercury	EPA 324/1631	BRL	12/28/05	< 37.0	No	No	
TotalHg-ST10-12/23/05	05BR1959-5	North Side Sidewalk Bridge	12/23/05	0.55	Mercury	EPA 324/1631	BRL	12/28/05	< 27.0	No	No	
TotalHg-ST11-12/23/05	05BR1959-6	90 Trinity Place (roof level)	12/23/05	0.60	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST12-12/23/05	05BR1959-7	110 Greenwich Street (roof level)	12/23/05	0.59	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	
TotalHg-ST13-12/23/05	05BR1959-8	Marriott Hotel, 38th Floor (roof level)	12/23/05	0.52	Mercury	EPA 324/1631	BRL	12/28/05	< 29.0	No	No	
TotalHg-ST14-12/23/05	05BR1959-9	West Face - South end at corner (scaffolding level)	12/23/05	0.55	Mercury	EPA 324/1631	BRL	12/28/05	< 27.0	No	No	
TotalHg-ST15-12/23/05	05BR1959-10	South Face - East end at corner (scaffolding level)	12/23/05	0.55	Mercury	EPA 324/1631	BRL	12/28/05	< 27.0	No	No	
TotalHg-ST16-12/23/05	05BR1959-11	East Face - North end at corner (scaffolding level)	12/23/05	0.55	Mercury	EPA 324/1631	BRL	12/28/05	< 27.0	No	No	
TotalHg-ST17-12/23/05	05BR1959-12	North Face - West end at corner (scaffolding level)	12/23/05	0.61	Mercury	EPA 324/1631	BRL	12/28/05	< 25.0	No	No	

Note:

- Mercury sample at Station 1 (Southwest Area [sidewalk bridge level]) on December 22, 2005 was not available for analysis on account of power supply failure.