

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m ³)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels									300	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-12/30/05	06BR0006-01	Southwest Area (sidewalk bridge level)	12/30/05	0.55	Mercury	EPA 324/1631	BRL	1/4/06	< 27.0	No	No	
TotalHg-ST2-12/30/05	06BR0006-02	Southeast Area (sidewalk bridge level)	12/30/05	0.54	Mercury	EPA 324/1631	BRL	1/4/06	< 28.0	No	No	
TotalHg-ST4-12/30/05	06BR0006-03	Northwest Area (street-level)	12/30/05	0.56	Mercury	EPA 324/1631	BRL	1/4/06	< 27.0	No	No	
TotalHg-ST5-12/30/05	06BR0006-04	Firehouse #10 (roof level)	12/30/05	0.57	Mercury	EPA 324/1631	BRL	1/4/06	< 26.0	No	No	
TotalHg-ST10-12/30/05	06BR0006-05	North Side Sidewalk Bridge	12/30/05	0.56	Mercury	EPA 324/1631	BRL	1/4/06	< 27.0	No	No	
TotalHg-ST11-12/30/05	06BR0006-06	90 Trinity Place (roof level)	12/30/05	0.59	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST12-12/30/05	06BR0006-07	110 Greenwich Street (roof level)	12/30/05	0.61	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST13-12/30/05	06BR0006-08	Marriott Hotel, 38th Floor (roof level)	12/30/05	0.56	Mercury	EPA 324/1631	BRL	1/4/06	< 27.0	No	No	
TotalHg-ST14-12/30/05	06BR0006-09	West Face - South end at corner (scaffolding level)	12/30/05	0.56	Mercury	EPA 324/1631	BRL	1/4/06	< 27.0	No	No	
TotalHg-ST15-12/30/05	06BR0006-10	South Face - East end at corner (scaffolding level)	12/30/05	0.55	Mercury	EPA 324/1631	BRL	1/4/06	< 27.0	No	No	
TotalHg-ST16-12/30/05	06BR0006-11	East Face - North end at corner (scaffolding level)	12/30/05	0.56	Mercury	EPA 324/1631	BRL	1/4/06	< 27.0	No	No	
TotalHg-ST17-12/30/05	06BR0006-12	North Face - West end at corner (scaffolding level)	12/30/05	0.57	Mercury	EPA 324/1631	BRL	1/4/06	< 26.0	No	No	
TotalHg-ST1-12/31/05	06BR0007-01	Southwest Area (sidewalk bridge level)	12/31/05	0.75	Mercury	EPA 324/1631	BRL	1/4/06	< 20.0	No	No	
TotalHg-ST2-12/31/05	06BR0007-02	Southeast Area (sidewalk bridge level)	12/31/05	0.68	Mercury	EPA 324/1631	BRL	1/4/06	< 22.0	No	No	
TotalHg-ST4-12/31/05	06BR0007-03	Northwest Area (street-level)	12/31/05	0.60	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST5-12/31/05	06BR0007-04	Firehouse #10 (roof level)	12/31/05	0.57	Mercury	EPA 324/1631	BRL	1/4/06	< 26.0	No	No	
TotalHg-ST10-12/31/05	06BR0007-05	North Side Sidewalk Bridge	12/31/05	0.61	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST11-12/31/05	06BR0007-06	90 Trinity Place (roof level)	12/31/05	0.56	Mercury	EPA 324/1631	BRL	1/4/06	< 27.0	No	No	
TotalHg-ST12-12/31/05	06BR0007-07	110 Greenwich Street (roof level)	12/31/05	0.57	Mercury	EPA 324/1631	BRL	1/4/06	< 26.0	No	No	
TotalHg-ST13-12/31/05	06BR0007-08	Marriott Hotel, 38th Floor (roof level)	12/31/05	0.56	Mercury	EPA 324/1631	BRL	1/4/06	< 27.0	No	No	
TotalHg-ST14-12/31/05	06BR0007-09	West Face - South end at corner (scaffolding level)	12/31/05	0.59	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST15-12/31/05	06BR0007-10	South Face - East end at corner (scaffolding level)	12/31/05	0.59	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST16-12/31/05	06BR0007-11	East Face - North end at corner (scaffolding level)	12/31/05	0.60	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST17-12/31/05	06BR0007-12	North Face - West end at corner (scaffolding level)	12/31/05	0.59	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST1-1/1/06	06BR0008-01	Southwest Area (sidewalk bridge level)	1/1/06	0.70	Mercury	EPA 324/1631	BRL	1/4/06	< 21.0	No	No	
TotalHg-ST2-1/1/06	06BR0008-02	Southeast Area (sidewalk bridge level)	1/1/06	0.62	Mercury	EPA 324/1631	BRL	1/4/06	< 24.0	No	No	
TotalHg-ST4-1/1/06	06BR0008-03	Northwest Area (street-level)	1/1/06	0.55	Mercury	EPA 324/1631	BRL	1/4/06	< 27.0	No	No	
TotalHg-ST5-1/1/06	06BR0008-04	Firehouse #10 (roof level)	1/1/06	0.58	Mercury	EPA 324/1631	BRL	1/4/06	< 26.0	No	No	
TotalHg-ST10-1/1/06	06BR0008-05	North Side Sidewalk Bridge	1/1/06	0.55	Mercury	EPA 324/1631	BRL	1/4/06	< 27.0	No	No	
TotalHg-ST11-1/1/06	06BR0008-06	90 Trinity Place (roof level)	1/1/06	0.57	Mercury	EPA 324/1631	BRL	1/4/06	< 26.0	No	No	
TotalHg-ST12-1/1/06	06BR0008-07	110 Greenwich Street (roof level)	1/1/06	0.55	Mercury	EPA 324/1631	BRL	1/4/06	< 27.0	No	No	
TotalHg-ST13-1/1/06	06BR0008-08	Marriott Hotel, 38th Floor (roof level)	1/1/06	0.55	Mercury	EPA 324/1631	BRL	1/4/06	< 27.0	No	No	
TotalHg-ST14-1/1/06	06BR0008-09	West Face - South end at corner (scaffolding level)	1/1/06	0.54	Mercury	EPA 324/1631	BRL	1/4/06	< 28.0	No	No	
TotalHg-ST15-1/1/06	06BR0008-10	South Face - East end at corner (scaffolding level)	1/1/06	0.53	Mercury	EPA 324/1631	BRL	1/4/06	< 28.0	No	No	
TotalHg-ST16-1/1/06	06BR0008-11	East Face - North end at corner (scaffolding level)	1/1/06	0.53	Mercury	EPA 324/1631	BRL	1/4/06	< 28.0	No	No	
TotalHg-ST17-1/1/06	06BR0008-12	North Face - West end at corner (scaffolding level)	1/1/06	0.54	Mercury	EPA 324/1631	BRL	1/4/06	< 28.0	No	No	
TotalHg-ST1-1/2/06	06BR0009-01	Southwest Area (sidewalk bridge level)	1/2/06	0.64	Mercury	EPA 324/1631	BRL	1/4/06	< 23.0	No	No	
TotalHg-ST2-1/2/06	06BR0009-02	Southeast Area (sidewalk bridge level)	1/2/06	0.61	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST4-1/2/06	06BR0009-03	Northwest Area (street-level)	1/2/06	0.58	Mercury	EPA 324/1631	BRL	1/4/06	< 26.0	No	No	
TotalHg-ST5-1/2/06	06BR0009-04	Firehouse #10 (roof level)	1/2/06	0.57	Mercury	EPA 324/1631	BRL	1/4/06	< 26.0	No	No	
TotalHg-ST10-1/2/06	06BR0009-05	North Side Sidewalk Bridge	1/2/06	0.58	Mercury	EPA 324/1631	BRL	1/4/06	< 26.0	No	No	
TotalHg-ST11-1/2/06	06BR0009-06	90 Trinity Place (roof level)	1/2/06	0.57	Mercury	EPA 324/1631	BRL	1/4/06	< 26.0	No	No	
TotalHg-ST12-1/2/06	06BR0009-07	110 Greenwich Street (roof level)	1/2/06	0.59	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST13-1/2/06	06BR0009-08	Marriott Hotel, 38th Floor (roof level)	1/2/06	0.59	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST14-1/2/06	06BR0009-09	West Face - South end at corner (scaffolding level)	1/2/06	0.61	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST15-1/2/06	06BR0009-10	South Face - East end at corner (scaffolding level)	1/2/06	0.61	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST16-1/2/06	06BR0009-11	East Face - North end at corner (scaffolding level)	1/2/06	0.61	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST17-1/2/06	06BR0009-12	North Face - West end at corner (scaffolding level)	1/2/06	0.61	Mercury	EPA 324/1631	BRL	1/4/06	< 25.0	No	No	
TotalHg-ST1-1/3/06	06BR0017-01	Southwest Area (sidewalk bridge level)	1/3/06	0.63	Mercury	EPA 324/1631	BRL	1/5/06	< 24.0	No	No	
TotalHg-ST2-1/3/06	06BR0017-02	Southeast Area (sidewalk bridge level)	1/3/06	0.56	Mercury	EPA 324/1631	BRL	1/5/06	< 27.0	No	No	
TotalHg-ST4-1/3/06	06BR0017-03	Northwest Area (street-level)	1/3/06	0.56	Mercury	EPA 324/1631	BRL	1/5/06	< 27.0	No	No	
TotalHg-ST5-1/3/06	06BR0017-04	Firehouse #10 (roof level)	1/3/06	0.58	Mercury	EPA 324/1631	BRL	1/5/06	< 26.0	No	No	
TotalHg-ST10-1/3/06	06BR0017-05	North Side Sidewalk Bridge	1/3/06	0.56	Mercury	EPA 324/1631	BRL	1/5/06	< 27.0	No	No	
TotalHg-ST11-1/3/06	06BR0017-06	90 Trinity Place (roof level)	1/3/06	0.57	Mercury	EPA 324/1631	BRL	1/5/06	< 26.0	No	No	
TotalHg-ST12-1/3/06	06BR0017-07	110 Greenwich Street (roof level)	1/3/06	0.58	Mercury	EPA 324/1631	BRL	1/5/06	< 26.0	No	No	
TotalHg-ST13-1/3/06	06BR0017-08	Marriott Hotel, 38th Floor (roof level)	1/3/06	0.57	Mercury	EPA 324/1631	BRL	1/5/06	< 26.0	No	No	
TotalHg-ST14-1/3/06	06BR0017-09	West Face - South end at corner (scaffolding level)	1/3/06	0.57	Mercury	EPA 324/1631	BRL	1/5/06	< 26.0	No	No	
TotalHg-ST15-1/3/06	06BR0017-10	South Face - East end at corner (scaffolding level)	1/3/06	0.57	Mercury	EPA 324/1631	BRL	1/5/06	< 26.0	No	No	
TotalHg-ST16-1/3/06	06BR0017-11	East Face - North end at corner (scaffolding level)	1/3/06	0.58	Mercury	EPA 324/1631	BRL	1/5/06	< 26.0	No	No	
TotalHg-ST17-1/3/06	06BR0017-12	North Face - West end at corner (scaffolding level)	1/3/06	0.57	Mercury	EPA 324/1631	BRL	1/5/06	< 26.0	No	No	
TotalHg-ST1-1/4/06	06BR0023-01	Southwest Area (sidewalk bridge level)	1/4/06	0.64	Mercury	EPA 324/1631	BRL	1/6/06	< 23.0	No	No	
TotalHg-ST2-1/4/06	06BR0023-02	Southeast Area (sidewalk bridge level)	1/4/06	0.57	Mercury	EPA 324/1631	BRL	1/6/06	< 26.0	No	No	
TotalHg-ST5-1/4/06	06BR0023-03	Firehouse #10 (roof level)	1/4/06	0.57	Mercury	EPA 324/1631	BRL	1/6/06	< 26.0	No	No	
TotalHg-ST10-1/4/06	06BR0023-04	North Side Sidewalk Bridge	1/4/06	0.59	Mercury	EPA 324/1631	BRL	1/6/06	< 25.0	No	No	
TotalHg-ST11-1/4/06	06BR0023-05	90 Trinity Place (roof level)	1/4/06	0.57	Mercury	EPA 324/1631	BRL	1/6/06	< 26.0	No	No	
TotalHg-ST12-1/4/06	06BR0023-06	110 Greenwich Street (roof level)	1/4/06	0.57	Mercury	EPA 324/1631	BRL	1/6/06	< 26.0	No	No	
TotalHg-ST13-1/4/06	06BR0023-07	Marriott Hotel, 38th Floor (roof level)	1/4/06	0.58	Mercury	EPA 324/1631	BRL	1/6/06	< 26.0	No	No	
TotalHg-ST14-1/4/06	06BR0023-08	West Face - South end at corner (scaffolding level)	1/4/06	0.58	Mercury	EPA 324/1631	BRL	1/6/06	< 26.0	No	No	
TotalHg-ST15-1/4/06	06BR0023-09	South Face - East end at corner (scaffolding level)	1/4/06	0.58	Mercury	EPA 324/1631	BRL	1/6/06	< 26.0	No	No	
TotalHg-ST16-1/4/06	06BR0023-10	East Face - North end at corner (scaffolding level)	1/4/06	0.58	Mercury	EPA 324/1631	BRL	1/6/06	< 26.0	No	No	
TotalHg-ST17-1/4/06	06BR0023-11	North Face - West end at corner (scaffolding level)	1/4/06	0.59	Mercury	EPA 324/1631	BRL	1/6/06	< 25.0	No	No	

Note:

1. Mercury sample at Station 4 (Northwest Area [street-level]) on January 4, 2006 was not available for analysis on account of pump failure.