

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m <sup>3</sup> )	Barium Concentration (ng/m <sup>3</sup> )	Beryllium Concentration (ng/m <sup>3</sup> )	Cadmium Concentration (ng/m <sup>3</sup> )	Chromium (Total) Concentration (ng/m <sup>3</sup> )	Copper Concentration (ng/m <sup>3</sup> )	Lead Concentration (ng/m <sup>3</sup> )	Manganese Concentration (ng/m <sup>3</sup> )	Nickel Concentration (ng/m <sup>3</sup> )	Zinc Concentration (ng/m <sup>3</sup> )	Exceeds Target	Exceeds EPA	Comments
									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000	Air Quality	Site Specific	Comments
									Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels
METALS-ST11-1/30/06	G6B010176001	Southwest Area (sidewalk bridge level)	1/30/06	1797.2	Metals	6020	STL-SAC	2/1/06	3.4	< 66.8	< 0.67	< 0.67	< 6.7	187	30.0	20.9	16.9	66.4	No	No	
METALS-ST2-1/30/06	G6B010176002	Southeast Area (sidewalk bridge level)	1/30/06	1793.2	Metals	6020	STL-SAC	2/1/06	4.2	74.7	< 0.67	< 0.67	< 6.7	84.5	25.8	41.6	17.7	88.4	No	No	
METALS-ST4-1/30/06	G6B010176003	Northwest Area (street-level)	1/30/06	1751	Metals	6020	STL-SAC	2/1/06	3.1	< 68.5	< 0.68	< 0.68	< 6.8	238	27.5	18.7	17.5	106	No	No	
METALS-ST5-1/30/06	G6B010176004	Firehouse #10 (roof level)	1/30/06	1793.8	Metals	6020	STL-SAC	2/1/06	3.5	< 66.9	< 0.67	< 0.67	< 6.7	305	28.0	26.7	21.4	71.4	No	No	
METALS-ST10-1/30/06	G6B010176005	North Side Sidewalk Bridge	1/30/06	1749.2	Metals	6020	STL-SAC	2/1/06	3.5	< 68.6	< 0.69	< 0.69	< 6.9	133	28.7	28.1	20.4	105	No	No	
METALS-ST11-1/30/06	G6B010176006	90 Trinity Place (roof level)	1/30/06	1674.3	Metals	6020	STL-SAC	2/1/06	2.9	< 71.7	< 0.72	< 0.72	< 7.2	63.1	26.6	18.5	21.0	54.9	No	No	
METALS-ST12-1/30/06	G6B010176007	110 Greenwich Street (roof level)	1/30/06	1842.5	Metals	6020	STL-SAC	2/1/06	3.0	< 65.1	< 0.65	< 0.65	< 6.5	77.4	23.9	17.4	20.9	54.4	No	No	
METALS-ST13-1/30/06	G6B010176008	Mariotti Hotel, 38th Floor (roof level)	1/30/06	1817.7	Metals	6020	STL-SAC	2/1/06	2.6	< 66.0	< 0.66	< 0.66	< 6.6	72.4	16.6	14.9	20.0	52.3	No	No	
METALS-ST14-1/30/06	G6B010176009	West Face - South end at corner (scaffolding level)	1/30/06	1778.6	Metals	6020	STL-SAC	2/1/06	2.2	< 67.5	< 0.67	< 0.67	< 6.7	234	13.4	18.6	41.0	No	No		
METALS-ST15-1/30/06	G6B010176010	South Face - East end at corner (scaffolding level)	1/30/06	1778.9	Metals	6020	STL-SAC	2/1/06	2.4	< 67.5	< 0.68	< 0.68	< 6.8	143	14.3	14.8	19.8	43.9	No	No	
METALS-ST16-1/30/06	G6B010176011	East Face - North end at corner (scaffolding level)	1/30/06	1734.7	Metals	6020	STL-SAC	2/1/06	2.2	< 69.2	< 0.69	< 0.69	< 6.9	232	12.8	12.6	19.2	50.4	No	No	
METALS-ST17-1/30/06	G6B010176012	North Face - West end at corner (scaffolding level)	1/30/06	1658.2	Metals	6020	STL-SAC	2/1/06	2.2	< 72.4	< 0.72	< 0.72	< 7.2	34.3	14.6	12.4	17.9	44.7	No	No	
METALS-ST1-1/31/06	G6B020215001	Southwest Area (sidewalk bridge level)	1/31/06	1766.9	Metals	6020	STL-SAC	2/2/06	< 1.4	< 67.9	< 0.68	< 0.68	< 6.8	58.5	6.8	7.0	24.6	8.6	No	No	
METALS-ST2-1/31/06	G6B020215002	Southeast Area (sidewalk bridge level)	1/31/06	1773.9	Metals	6020	STL-SAC	2/2/06	2.9	< 68.8	< 0.68	< 0.68	< 6.8	111	16.2	68.4	11.8	71.5	No	No	
METALS-ST4-1/31/06	G6B020215003	Northwest Area (street-level)	1/31/06	1809.5	Metals	6020	STL-SAC	2/2/06	< 1.3	< 66.3	< 0.66	< 0.66	< 6.6	181	5.3	6.7	5.9	21.6	No	No	
METALS-ST5-1/31/06	G6B020215004	Firehouse #10 (roof level)	1/31/06	1780.4	Metals	6020	STL-SAC	2/2/06	< 1.3	< 67.4	< 0.67	< 0.67	< 6.7	304	5.3	6.5	4.3	27.3	No	No	
METALS-ST10-1/31/06	G6B020215005	North Side Sidewalk Bridge	1/31/06	1773.1	Metals	6020	STL-SAC	2/2/06	< 1.3	< 67.4	< 0.67	< 0.67	< 6.7	136	5.2	7.0	6.1	24.6	No	No	
METALS-ST11-1/31/06	G6B020215006	90 Trinity Place (roof level)	1/31/06	1639.8	Metals	6020	STL-SAC	2/2/06	< 1.5	< 73.2	< 0.73	< 0.73	< 7.3	46.2	6.5	8.0	8.4	25.6	No	No	
METALS-ST12-1/31/06	G6B020215007	110 Greenwich Street (roof level)	1/31/06	1799.6	Metals	6020	STL-SAC	2/2/06	< 1.3	< 66.7	< 0.67	< 0.67	< 6.7	48.3	6.8	6.7	4.3	20.4	No	No	
METALS-ST13-1/31/06	G6B020215008	Mariotti Hotel, 38th Floor (roof level)	1/31/06	1670.7	Metals	6020	STL-SAC	2/2/06	< 1.4	< 71.8	< 0.72	< 0.72	< 7.2	97.0	3.4	5.0	< 3.6	17.7	No	No	
METALS-ST14-1/31/06	G6B020215009	West Face - South end at corner (scaffolding level)	1/31/06	1807.4	Metals	6020	STL-SAC	2/2/06	< 1.3	< 66.4	< 0.66	< 0.66	< 6.6	177	3.1	3.7	< 3.3	14.3	No	No	
METALS-ST15-1/31/06	G6B020215010	South Face - East end at corner (scaffolding level)	1/31/06	1826.2	Metals	6020	STL-SAC	2/2/06	< 1.3	< 65.7	< 0.66	< 0.66	< 6.6	95.6	6.6	7.8	< 3.6	22.2	No	No	
METALS-ST16-1/31/06	G6B020215011	East Face - North end at corner (scaffolding level)	1/31/06	1779	Metals	6020	STL-SAC	2/2/06	< 1.3	< 67.4	< 0.67	< 0.67	< 6.7	206	5.3	5.3	< 3.4	21.7	No	No	
METALS-ST17-1/31/06	G6B020215012	North Face - West end at corner (scaffolding level)	1/31/06	1681.3	Metals	6020	STL-SAC	2/2/06	< 1.4	< 71.4	< 0.71	< 0.71	< 7.1	22.2	3.7	4.2	< 3.6	15.6	No	No	