

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target	Exceeds EPA	Comments	
									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000				
EPA Site Specific Trigger Levels									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000	Air Quality	Site Specific	Comments	
									Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels
METALS-ST11-5/19/06	G6E230212001	Southwest Area (sidewalk bridge level)	5/19/06	1710.9	Metals	6020	STL-SAC	5/23/06	2.3	< 70.1	< 0.70	< 0.70	< 7.0	102	12.7	13.8	5.3	65.0	No	No		
METALS-ST2-5/19/06	G6E230212002	Southeast Area (sidewalk bridge level)	5/19/06	1747.7	Metals	6020	STL-SAC	5/23/06	2.0	< 68.7	< 0.69	< 0.69	< 6.9	69.3	10.7	15.0	5.1	50.5	No	No		
METALS-ST4-5/19/06	G6E230212003	Northwest Area (street-level)	5/19/06	1753	Metals	6020	STL-SAC	5/23/06	2.0	< 68.4	< 0.68	< 0.68	< 6.8	129	24.7	12.7	5.4	65.2	No	No		
METALS-ST5-5/19/06	G6E230212004	Firehouse #10 (roof level)	5/19/06	1756.4	Metals	6020	STL-SAC	5/23/06	1.6	< 68.3	< 0.68	< 0.68	< 6.8	50.8	14.9	16.7	5.3	42.2	No	No		
METALS-ST10-5/19/06	G6E230212005	North Side Sidewalk Bridge	5/19/06	1731.4	Metals	6020	STL-SAC	5/23/06	1.8	< 69.3	< 0.69	< 0.69	< 6.9	54.9	13.2	14.1	5.7	52.2	No	No		
METALS-ST11-5/19/06	G6E230212006	90 Trinity Place (roof level)	5/19/06	1834.2	Metals	6020	STL-SAC	5/23/06	1.4	< 65.4	< 0.65	< 0.65	< 6.5	40.1	12.1	11.5	4.9	51.1	No	No		
METALS-ST12-5/19/06	G6E230212007	110 Greenwich Street (roof level)	5/19/06	1798.9	Metals	6020	STL-SAC	5/23/06	1.4	< 66.7	< 0.67	< 0.67	< 6.7	60.4	10.0	9.2	4.5	35.9	No	No		
METALS-ST13-5/19/06	G6E230212008	Marrion Hotel, 38th Floor (roof level)	5/19/06	1796.7	Metals	6020	STL-SAC	5/23/06	< 1.3	< 66.8	< 0.67	< 0.67	< 6.7	48.8	7.1	7.5	5.0	28.3	No	No		
METALS-ST14-5/19/06	G6E230212009	West Face - South end at corner (scaffolding level)	5/19/06	1692.2	Metals	6020	STL-SAC	5/23/06	< 1.4	< 70.9	< 0.71	< 0.71	< 7.1	29.1	6.0	6.2	4.5	22.7	No	No		
METALS-ST15-5/19/06	G6E230212010	South Face - East end at corner (scaffolding level)	5/19/06	1719.2	Metals	6020	STL-SAC	5/23/06	< 1.4	< 69.8	< 0.70	< 0.70	< 7.0	172	7.6	6.3	4.4	24.7	No	No		
METALS-ST16-5/19/06	G6E230212011	East Face - North end at corner (scaffolding level)	5/19/06	1670.1	Metals	6020	STL-SAC	5/23/06	< 1.4	< 71.8	< 0.72	< 0.72	< 7.2	85.1	11.0	12.3	5.3	33.0	No	No		
METALS-ST17-5/19/06	G6E230212012	North Face - West end at corner (scaffolding level)	5/19/06	1737.3	Metals	6020	STL-SAC	5/23/06	< 1.4	< 69.1	< 0.69	< 0.69	< 6.9	59.6	9.1	8.0	4.5	31.7	No	No		
METALS-ST1-5/20/06	G6E230208001	Southwest Area (sidewalk bridge level)	5/20/06	1894.1	Metals	6020	STL-SAC	5/23/06	1.5	< 66.5	< 0.66	< 0.66	< 6.6	98.9	13.3	13.3	21.1	4.7	43.0	No	No	
METALS-ST2-5/20/06	G6E230208002	Southeast Area (sidewalk bridge level)	5/20/06	1800.9	Metals	6020	STL-SAC	5/23/06	1.7	< 66.6	< 0.67	< 0.67	< 6.7	82.6	13.2	26.6	6.4	56.5	No	No		
METALS-ST4-5/20/06	G6E230208003	Northwest Area (street-level)	5/20/06	1769.2	Metals	6020	STL-SAC	5/23/06	1.4	< 67.8	< 0.68	< 0.68	< 6.8	125	37.7	17.7	4.5	51.1	No	No		
METALS-ST5-5/20/06	G6E230208004	Firehouse #10 (roof level)	5/20/06	1825.9	Metals	6020	STL-SAC	5/23/06	1.5	< 65.7	< 0.66	< 0.66	< 6.6	43.0	16.7	23.2	5.2	53.2	No	No		
METALS-ST10-5/20/06	G6E230208005	North Side Sidewalk Bridge	5/20/06	1737.2	Metals	6020	STL-SAC	5/23/06	< 1.4	< 69.1	< 0.69	< 0.69	< 6.9	41.8	12.0	15.8	4.1	41.2	No	No		
METALS-ST11-5/20/06	G6E230208006	90 Trinity Place (roof level)	5/20/06	1812.1	Metals	6020	STL-SAC	5/23/06	< 1.3	< 66.2	< 0.66	< 0.66	< 6.6	30.5	10.1	13.1	3.7	30.5	No	No		
METALS-ST12-5/20/06	G6E230208007	110 Greenwich Street (roof level)	5/20/06	1709	Metals	6020	STL-SAC	5/23/06	< 1.4	< 70.2	< 0.70	< 0.70	< 7.0	59.4	7.6	11.8	3.7	30.2	No	No		
METALS-ST13-5/20/06	G6E230208008	Marrion Hotel, 38th Floor (roof level)	5/20/06	1714.3	Metals	6020	STL-SAC	5/23/06	< 1.4	< 70.0	< 0.70	< 0.70	< 7.0	110	4.5	8.8	3.6	18.2	No	No		
METALS-ST14-5/20/06	G6E230208009	West Face - South end at corner (scaffolding level)	5/20/06	1749	Metals	6020	STL-SAC	5/23/06	< 1.4	< 68.6	< 0.69	< 0.69	< 6.9	24.0	4.4	7.3	< 3.4	19.7	No	No		
METALS-ST15-5/20/06	G6E230208010	South Face - East end at corner (scaffolding level)	5/20/06	1760.6	Metals	6020	STL-SAC	5/23/06	< 1.4	< 68.2	< 0.68	< 0.68	< 6.8	100	6.2	10.3	< 3.4	23.7	No	No		
METALS-ST16-5/20/06	G6E230208011	East Face - North end at corner (scaffolding level)	5/20/06	1736.5	Metals	6020	STL-SAC	5/23/06	< 1.4	< 69.1	< 0.69	< 0.69	< 6.9	76.7	9.1	16.4	4.4	34.2	No	No		
METALS-ST17-5/20/06	G6E230208012	North Face - West end at corner (scaffolding level)	5/20/06	1772.3	Metals	6020	STL-SAC	5/23/06	< 1.4	< 67.7	< 0.68	< 0.68	< 6.8	40.1	7.4	12.4	< 3.4	33.8	No	No		
METALS-ST1-5/21/06	G6E230210001	Southwest Area (sidewalk bridge level)	5/21/06	1812.5	Metals	6020	STL-SAC	5/23/06	< 1.3	< 66.2	< 0.66	< 0.66	< 6.6	143	14.9	20.4	< 3.3	54.1	No	No		
METALS-ST2-5/21/06	G6E230210002	Southeast Area (sidewalk bridge level)	5/21/06	1819.6	Metals	6020	STL-SAC	5/23/06	1.4	< 65.9	< 0.66	< 0.66	< 6.6	73.6	21.6	36.4	5.6	61.1	No	No		
METALS-ST4-5/21/06	G6E230210003	Northwest Area (street-level)	5/21/06	1854.9	Metals	6020	STL-SAC	5/23/06	< 1.3	< 64.7	< 0.65	< 0.65	< 6.5	129	63.1	19.2	< 3.2	61.1	No	No		
METALS-ST5-5/21/06	G6E230210004	Firehouse #10 (roof level)	5/21/06	1792.4	Metals	6020	STL-SAC	5/23/06	< 1.3	< 66.9	< 0.67	< 0.67	< 6.7	51.0	16.9	26.9	4.2	61.0	No	No		
METALS-ST10-5/21/06	G6E230210005	North Side Sidewalk Bridge	5/21/06	1803.4	Metals	6020	STL-SAC	5/23/06	< 1.3	< 66.5	< 0.66	< 0.66	< 6.6	44.6	12.4	18.8	< 3.3	45.3	No	No		
METALS-ST11-5/21/06	G6E230210006	90 Trinity Place (roof level)	5/21/06	1732.5	Metals	6020	STL-SAC	5/23/06	< 1.4	< 69.3	< 0.69	< 0.69	< 6.9	33.0	9.8	14.2	< 3.5	34.1	No	No		
METALS-ST12-5/21/06	G6E230210007	110 Greenwich Street (roof level)	5/21/06	1784.1	Metals	6020	STL-SAC	5/23/06	< 1.3	< 67.3	< 0.67	< 0.67	< 6.7	84.3	8.7	13.2	< 3.4	29.5	No	No		
METALS-ST13-5/21/06	G6E230210008	Marrion Hotel, 38th Floor (roof level)	5/21/06	1810.6	Metals	6020	STL-SAC	5/23/06	< 1.3	< 66.3	< 0.66	< 0.66	< 6.6	130	4.7	9.2	< 3.3	20.4	No	No		
METALS-ST14-5/21/06	G6E230210009	West Face - South end at corner (scaffolding level)	5/21/06	1942.6	Metals	6020	STL-SAC	5/23/06	< 1.3	< 65.1	< 0.65	< 0.65	< 6.5	24.7	4.7	8.8	< 3.2	23.9	No	No		
METALS-ST15-5/21/06	G6E230210010	South Face - East end at corner (scaffolding level)	5/21/06	1875.6	Metals	6020	STL-SAC	5/23/06	< 1.3	< 64.0	< 0.64	< 0.64	< 6.4	149	6.1	11.7	< 3.2	22.7	No	No		
METALS-ST16-5/21/06	G6E230210011	East Face - North end at corner (scaffolding level)	5/21/06	1834.6	Metals	6020	STL-SAC	5/23/06	< 1.3	< 65.4	< 0.65	< 0.65	< 6.5	76.8	9.8	16.6	< 3.3	37.6	No	No		
METALS-ST17-5/21/06	G6E230210012	North Face - West end at corner (scaffolding level)	5/21/06	1905.5	Metals	6020	STL-SAC	5/23/06	< 1.2	< 63.0	< 0.63	< 0.63	< 6.3	35.3	6.4	9.6	< 3.1	26.7	No	No		