

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m3)		Barium Concentration (ng/m3)		Beryllium Concentration (ng/m3)		Cadmium Concentration (ng/m3)		Chromium (Total) Concentration (ng/m3)		Copper Concentration (ng/m3)		Lead Concentration (ng/m3)		Manganese Concentration (ng/m3)		Nickel Concentration (ng/m3)		Zinc Concentration (ng/m3)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments		
									5,000	14,000	5,000	200	40	600	10,000	5,000	500	200	16,000														
METALS-ST11-6/22/09	G9F240149001	Southwest Area (sidewalk bridge leve	6/22/09	1873.6	Metals	6020	STL-SAC	6/24/09	2.3	255	< 0.64	< 0.64	< 6.4	50.2	16.1	46.2	6.9	163	No	No													
METALS-ST12-6/22/09	G9F240149002	Southwest Area (sidewalk bridge leve	6/22/09	1872.3	Metals	6020	STL-SAC	6/24/09	1.9	180	< 0.64	< 0.64	< 6.4	74.6	6.0	30.8	5.6	118	No	No													
METALS-ST14-6/22/09	G9F240149003	Northwest Area (street-level	6/22/09	1847.6	Metals	6020	STL-SAC	6/24/09	2.0	251	< 0.65	< 0.65	< 6.5	94.0	17.5	43.4	6.5	126	No	No													
METALS-ST5-6/22/09	G9F240149004	Firehouse #10 (roof level)	6/22/09	1755.6	Metals	6020	STL-SAC	6/24/09	1.9	259	< 0.68	< 0.68	< 6.8	45.6	6.6	38.2	8.4	112	No	No													
METALS-ST10-6/22/09	G9F240149005	North Side Sidewalk Bridg	6/22/09	1856.7	Metals	6020	STL-SAC	6/24/09	1.9	418	< 0.65	< 0.65	< 6.5	44.0	6.3	54.2	9.1	134	No	No													
METALS-ST11-6/22/09	G9F240149006	90 Trinity Place (roof level)	6/22/09	1763.3	Metals	6020	STL-SAC	6/24/09	1.8	133	< 0.68	< 0.68	< 6.8	33.8	3.8	22.0	5.0	64.0	No	No													
METALS-ST12-6/22/09	G9F240149007	110 Greenwich Street (roof level)	6/22/09	1796.5	Metals	6020	STL-SAC	6/24/09	1.8	130	< 0.67	< 0.67	< 6.7	22.9	4.5	24.3	4.6	84.5	No	No													
METALS-ST13-6/22/09	G9F240149008	Marriott Hotel, 38th Floor (roof leve	6/22/09	1766.2	Metals	6020	STL-SAC	6/24/09	1.5	< 67.9	< 0.68	< 0.68	< 6.8	59.2	4.2	16.0	< 3.4	48.1	No	No													
METALS-ST1-6/23/09	G9F250187001	Southwest Area (sidewalk bridge leve	6/23/09	1741.5	Metals	6020	STL-SAC	6/25/09	3.2	357	< 0.69	< 0.69	< 6.9	168	16.3	52.6	11.3	146	No	No													
METALS-ST2-6/23/09	G9F250187002	Southwest Area (sidewalk bridge leve	6/23/09	1711.7	Metals	6020	STL-SAC	6/25/09	3.4	285	< 0.70	< 0.70	< 7.0	759	12.8	46.1	10.1	157	No	No													
METALS-ST4-6/23/09	G9F250187003	Northwest Area (street-level	6/23/09	1741.5	Metals	6020	STL-SAC	6/25/09	3.2	304	< 0.69	< 0.69	< 6.9	200	14.3	47.9	11.5	120	No	No													
METALS-ST5-6/23/09	G9F250187004	Firehouse #10 (roof level)	6/23/09	1688.6	Metals	6020	STL-SAC	6/25/09	3.0	383	< 0.71	< 0.71	< 7.1	95.0	9.4	54.7	12.5	138	No	No													
METALS-ST10-6/23/09	G9F250187005	North Side Sidewalk Bridg	6/23/09	1717.9	Metals	6020	STL-SAC	6/25/09	3.1	403	< 0.70	< 0.70	< 7.0	161	8.8	56.3	12.4	133	No	No													
METALS-ST100-6/23/09	G9F250187009	Station 10 Field Duplicat	6/23/09	1700.6	Metals	6020	STL-SAC	6/25/09	3.2	391	< 0.70	< 0.70	< 7.0	751	9.5	56.9	12.8	146	No	No													
METALS-ST11-6/23/09	G9F250187006	90 Trinity Place (roof level)	6/23/09	1773.5	Metals	6020	STL-SAC	6/25/09	2.4	167	< 0.68	< 0.68	< 6.8	77.3	7.9	26.2	7.4	88.6	No	No													
METALS-ST12-6/23/09	G9F250187007	110 Greenwich Street (roof level)	6/23/09	1740.2	Metals	6020	STL-SAC	6/25/09	2.5	153	< 0.69	< 0.69	< 6.9	50.0	7.9	25.8	7.4	82.5	No	No													
METALS-ST13-6/23/09	G9F250187008	Marriott Hotel, 38th Floor (roof leve	6/23/09	1769.2	Metals	6020	STL-SAC	6/25/09	2.5	89.4	< 0.68	< 0.68	< 6.8	151	7.0	18.1	5.8	53.6	No	No													
METALS-ST1-6/24/09	G9F260163001	Southwest Area (sidewalk bridge leve	6/24/09	1713	Metals	6020	STL-SAC	6/26/09	4.8	171	< 0.70	< 0.70	< 7.0	86.1	46.7	39.8	11.9	133	No	No													
METALS-ST2-6/24/09	G9F260163002	Southwest Area (sidewalk bridge leve	6/24/09	1704.3	Metals	6020	STL-SAC	6/26/09	5.1	176	< 0.70	< 0.70	< 7.0	341	20.1	45.9	13.0	131	No	No													
METALS-ST4-6/24/09	G9F260163003	Northwest Area (street-level	6/24/09	1800.3	Metals	6020	STL-SAC	6/26/09	4.3	246	< 0.67	< 0.67	< 6.7	86.0	12.0	41.0	12.4	122	No	No													
METALS-ST5-6/24/09	G9F260163004	Firehouse #10 (roof level)	6/24/09	1679.1	Metals	6020	STL-SAC	6/26/09	4.2	185	< 0.71	< 0.71	< 7.1	62.1	6.5	37.6	12.3	97.3	No	No													
METALS-ST10-6/24/09	G9F260163005	North Side Sidewalk Bridg	6/24/09	1808.3	Metals	6020	STL-SAC	6/26/09	3.9	311	< 0.66	< 0.66	< 6.6	56.8	7.0	54.7	14.6	132	No	No													
METALS-ST11-6/24/09	G9F260163006	90 Trinity Place (roof level)	6/24/09	1763.8	Metals	6020	STL-SAC	6/26/09	3.4	134	< 0.68	< 0.68	< 6.8	74.6	5.8	22.8	9.6	66.3	No	No													
METALS-ST12-6/24/09	G9F260163007	110 Greenwich Street (roof level)	6/24/09	1797.5	Metals	6020	STL-SAC	6/26/09	3.6	137	< 0.67	< 0.67	< 6.7	64.2	7.0	23.3	9.6	72.0	No	No													
METALS-ST13-6/24/09	G9F260163008	Marriott Hotel, 38th Floor (roof leve	6/24/09	1745.9	Metals	6020	STL-SAC	6/26/09	3.3	102	< 0.69	< 0.69	< 6.9	121	5.5	20.4	10.1	55.6	No	No													
METALS-ST1-6/25/09	G9F270175001	Southwest Area (sidewalk bridge leve	6/25/09	1782.4	Metals	6020	STL-SAC	6/27/09	4.7	126	< 0.67	< 0.67	< 6.7	92.7	26.0	50.0	15.6	146	No	No													
METALS-ST2-6/25/09	G9F270175002	Southwest Area (sidewalk bridge leve	6/25/09	1701.2	Metals	6020	STL-SAC	6/27/09	4.8	89.6	< 0.70	< 0.70	< 7.0	276	23.2	44.9	14.6	162	No	No													
METALS-ST4-6/25/09	G9F270175003	Northwest Area (street-level	6/25/09	1773.9	Metals	6020	STL-SAC	6/27/09	4.3	148	< 0.68	< 0.68	< 6.8	91.8	27.7	42.2	15.2	180	No	No													
METALS-ST5-6/25/09	G9F270175004	Firehouse #10 (roof level)	6/25/09	1747.7	Metals	6020	STL-SAC	6/27/09	4.2	209	< 0.69	< 0.69	< 6.9	82.3	19.4	46.0	17.4	140	No	No													
METALS-ST10-6/25/09	G9F270175005	North Side Sidewalk Bridg	6/25/09	1766.9	Metals	6020	STL-SAC	6/27/09	4.8	452	< 0.68	< 0.68	< 6.8	7.9	85.6	20.6	79.3	20.2	217	No	No												
METALS-ST11-6/25/09	G9F270175006	90 Trinity Place (roof level)	6/25/09	1756.3	Metals	6020	STL-SAC	6/27/09	4.4	95.9	< 0.68	< 0.68	< 6.8	63.3	16.0	21.1	13.5	86.3	No	No													
METALS-ST12-6/25/09	G9F270175007	110 Greenwich Street (roof level)	6/25/09	1765.9	Metals	6020	STL-SAC	6/27/09	4.4	83.4	< 0.68	< 0.68	< 6.8	105	19.3	20.7	13.6	94.3	No	No													
METALS-ST13-6/25/09	G9F270175008	Marriott Hotel, 38th Floor (roof leve	6/25/09	1766.3	Metals	6020	STL-SAC	6/27/09	4.3	< 67.9	< 0.68	< 0.68	< 6.8	168	16.0	16.3	14.9	59.9	No	No													
METALS-ST1-6/26/09	G9F290138001	Southwest Area (sidewalk bridge leve	6/26/09	1784.7	Metals	6020	STL-SAC	6/29/09	5.0	< 66.0	< 0.68	< 0.68	< 6.8	89.6	15.0	32.5	8.7	158	No	No													
METALS-ST2-6/26/09	G9F290138002	Southwest Area (sidewalk bridge leve	6/26/09	1749.5	Metals	6020	STL-SAC	6/29/09	5.6	76.2	< 0.68	< 0.68	< 6.8	7.4	218	16.7	42.6	10.6	224	No	No												
METALS-ST4-6/26/09	G9F290138003	Northwest Area (street-level	6/26/09	1760.2	Metals	6020	STL-SAC	6/29/09	5.6	79.6	< 0.68	< 0.68	< 6.8	120	17.0	31.4	10.3	163	No	No													
METALS-ST5-6/26/09	G9F290138004	Firehouse #10 (roof level)	6/26/09	1722.5	Metals	6020	STL-SAC	6/29/09	4.4	101	< 0.70	< 0.70	< 7.0	113	10.8	32.8	10.5	171	No	No													
METALS-ST10-6/26/09	G9F290138005	North Side Sidewalk Bridg	6/26/09	1754.4	Metals	6020	STL-SAC	6/29/09	4.6	393	< 0.68	< 0.68	< 6.8	163	11.3	61.8	40.4	281	No	No													
METALS-ST11-6/26/09	G9F290138006	90 Trinity Place (roof level)	6/26/09	1744.3	Metals	6020	STL-SAC	6/29/09	3.8	< 68.8	< 0.69	< 0.69	< 6.9	75.5	10.3	16.1	8.6	79.0	No	No													
METALS-ST12-6/26/09	G9F290138007	110 Greenwich Street (roof level)	6/26/09</																														