TRC Field Sample No. Sample No. Sampling Location	Collection Start Date	Sample Volume (m	3) Analyte	Analytical Metho	d Lab La	b Sample Receipt Date	Antimony Concentration (ng/m3)	Barium Concentration (ng/m3)	Beryllium Concentration (ng/m3)	Cadmium Concentration (ng/m3)	Chromium (Total) Concentration (ng/m	n3) Copper Concentration (ng/m3)	Lead Concentration (ng/m3)	Manganese Concentration (ng/m3)	Nickel Concentration (ng/m3)	Zinc Concentration (ng/m3)	Exceeds Target	Exceeds EPA
Target Air Quality Levels							5,000	5,000	20	40	600	10,000	1,500	500	200	16,000	Air Quality	Site Specific Comments
	EPA Site Specific Tr						14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000	Levels	Trigger Levels
METALS-ST5-8/21/07 G7H230124001 Firehouse #10 (roof level	8/21/07	1824.3	Metals	6020	STL-SAC	8/23/07	2.0	< 65.8	< 0.66	< 0.66	< 6.6	52.6	9.3	15.9	5.4	42.9	No	No
METALS-ST10-8/21/07 G7H230124002 North Side Sidewalk Bridge	8/21/07	1735.2	Metals	6020	STL-SAC	8/23/07	1.4	< 69.2	< 0.69	< 0.69	< 6.9	186	8.4	12.7	4.3	80.7	No	No
METALS-ST11-8/21/07 G7H230124003 90 Trinity Place (roof level	8/21/07	1810.5	Metals	6020	STL-SAC	8/23/07	1.4	< 66.3	< 0.66	< 0.66	< 6.6	140	4.5	8.6	3.7	26.4	No	No
METALS-ST12-8/21/07 G7H230124004 110 Greenwich Street (roof level	8/21/07	1987.7	Metals	6020	STL-SAC	8/23/07	1.6	< 60.4	< 0.60	< 0.60	< 6.0	40.6	7.5	10.3	4.0	73.9	No	No
METALS-ST13-8/21/07 G7H230124005 Marriott Hotel, 38th Floor (roof leve	8/21/07	1816.1	Metals	6020	STL-SAC	8/23/07	< 1.3	< 66.1	< 0.66	< 0.66	< 6.6	261	3.7	6.8	3.7	29.7	No	No
METALS-ST5-8/22/07 G7H240123001 Firehouse #10 (roof level	8/22/07	1839	Metals	6020	STL-SAC	8/24/07	2.8	< 65.2	< 0.65	< 0.65	< 6.5	68.1	15.2	28.9	12.9	82.4	No	No
METALS-ST10-8/22/07 G7H240123002 North Side Sidewalk Bridge	8/22/07	1852	Metals	6020	STL-SAC	8/24/07	3.2	< 64.8	< 0.65	< 0.65	< 6.5	209	17.7	22.6	8.4	76.9	No	No
METALS-ST11-8/22/07 G7H240123003 90 Trinity Place (roof level	8/22/07	1868.5	Metals	6020	STL-SAC	8/24/07	3.0	< 64.2	< 0.64	< 0.64	< 6.4	191	13.3	18.7	6.6	71.7	No	No
METALS-ST12-8/22/07 G7H240123004 110 Greenwich Street (roof level	8/22/07	1670.5	Metals	6020	STL-SAC	8/24/07	3.1	< 71.8	< 0.72	< 0.72	< 7.2	41.7	34.9	16.3	5.8	108	No	No
METALS-ST13-8/22/07 G7H240123005 Marriott Hotel, 38th Floor (roof leve	8/22/07	1845.9	Metals	6020	STL-SAC	8/24/07	2.6	< 65.0	< 0.65	< 0.65	< 6.5	374	11.1	12.7	5.5	53.0	No	No

Note:
1. Metals samples at Station 1 (Southwest Area [sidewalk bridge level]), Station 2 (Southeast Area [sidewalk bridge level]) and Station 4 (Northwest Area [street-level]) on August 21 and 22, 2007 were not collected. The stations were not accessible on account of a fire at 130 Liberty Street that caused unsafe conditions in the vicinity of the stations.
2. Metals samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 [South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]) and Station 17 (North Face - West end at corner [scaffolding level]) on August 21 and 22, 2007 were not collected. The stations were not accessible on account of a fire at 130 Liberty Street.

Page 1 of 1 130 Liberty Street Deconstruction Project