

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m³)	Barium Concentration (ng/m³)	Beryllium Concentration (ng/m³)	Cadmium Concentration (ng/m³)	Chromium (Total) Concentration (ng/m³)	Copper Concentration (ng/m³)	Lead Concentration (ng/m³)	Manganese Concentration (ng/m³)	Nickel Concentration (ng/m³)	Zinc Concentration (ng/m³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									5,000	5,000	200	40	600	10,000	1,500	500	200	160,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000			
METALS-ST11-11/8/05	GSK100212001	Southwest Area (street-level)	11/8/05	1672.6	Metals	6020	STL-SAC	11/10/05	5.3	< 71.7	< 0.72	< 0.72	< 7.2	177	56.4	30.9	15.9	181	No	No	
METALS-ST2-11/8/05	GSK100212002	Southwest Area (sidewalk bridge leve	11/8/05	1566	Metals	6020	STL-SAC	11/10/05	5.6	93.3	< 0.77	< 0.77	8.0	81.2	21.5	54.1	16.2	90.4	No	No	
METALS-ST4-11/8/05	GSK100212003	Northwest Area (street-level)	11/8/05	1615.4	Metals	6020	STL-SAC	11/10/05	22.3	< 74.3	< 0.74	1.5	14.7	120	57.4	61.4	17.2	789	No	No	
METALS-ST5-11/8/05	GSK100212004	Firehouse #10 (roof level)	11/8/05	1795.8	Metals	6020	STL-SAC	11/10/05	3.7	< 66.8	< 0.67	< 0.67	< 6.7	42.3	14.8	24.2	14.9	64.4	No	No	
METALS-ST10-11/8/05	GSK100212005	North Side Sidewalk Bridgr	11/8/05	1660.8	Metals	6020	STL-SAC	11/10/05	3.6	< 72.2	< 0.72	< 0.72	< 7.2	30.4	13.4	21.3	15.4	62.9	No	No	
METALS-ST11-11/8/05	GSK100212006	90 Trinity Place (roof level)	11/8/05	1788.3	Metals	6020	STL-SAC	11/10/05	3.3	< 67.1	< 0.67	< 0.67	< 6.7	70.9	15.3	21.0	13.6	64.0	No	No	
METALS-ST12-11/8/05	GSK100212007	110 Greenwich Street (roof level)	11/8/05	1761.2	Metals	6020	STL-SAC	11/10/05	3.4	< 68.1	< 0.68	< 0.68	< 6.8	102	15.5	20.4	13.3	62.6	No	No	
METALS-ST13-11/8/05	GSK100212008	Marrriott Hotel, 38th Floor (roof leve	11/8/05	1777.1	Metals	6020	STL-SAC	11/10/05	3.3	< 67.5	< 0.68	< 0.68	< 6.8	43.9	11.2	16.6	13.6	48.0	No	No	
METALS-ST1-11/9/05	GSK110226001	Southwest Area (street-level)	11/9/05	1659.6	Metals	6020	STL-SAC	11/11/05	2.0	< 72.3	< 0.72	< 0.72	< 7.2	193	22.8	18.8	6.8	88.6	No	No	
METALS-ST2-11/9/05	GSK110226002	Southwest Area (sidewalk bridge leve	11/9/05	1575.7	Metals	6020	STL-SAC	11/11/05	3.3	< 76.2	< 0.76	< 0.76	< 7.6	162	30.0	39.2	11.3	104	No	No	
METALS-ST4-11/9/05	GSK110226003	Northwest Area (street-level)	11/9/05	1626.5	Metals	6020	STL-SAC	11/11/05	2.0	< 73.8	< 0.74	< 0.74	< 7.4	261	17.3	17.9	7.2	58.1	No	No	
METALS-ST5-11/9/05	GSK110226004	Firehouse #10 (roof level)	11/9/05	1774.9	Metals	6020	STL-SAC	11/11/05	2.1	< 67.6	< 0.68	< 0.68	< 6.8	75.2	16.5	19.4	7.8	57.6	No	No	
METALS-ST10-11/9/05	GSK110226005	North Side Sidewalk Bridgr	11/9/05	1749.6	Metals	6020	STL-SAC	11/11/05	2.1	< 68.6	< 0.68	< 0.68	< 6.8	67.7	15.9	19.4	7.4	56.3	No	No	
METALS-ST100-11/9/05	GSK110226009	Station 10 Field Duplicat	11/9/05	1759.2	Metals	6020	STL-SAC	11/11/05	2.0	< 68.2	< 0.68	< 0.68	< 6.8	56.9	15.2	19.7	7.3	55.6	No	No	
METALS-ST11-11/9/05	GSK110226006	90 Trinity Place (roof level)	11/9/05	1778.2	Metals	6020	STL-SAC	11/11/05	3.0	< 67.5	< 0.67	< 0.67	< 6.7	66.7	19.8	15.8	7.5	94.5	No	No	
METALS-ST12-11/9/05	GSK110226007	110 Greenwich Street (roof level)	11/9/05	1743.4	Metals	6020	STL-SAC	11/11/05	2.4	< 68.8	< 0.69	< 0.69	< 6.9	124	17.5	15.9	7.4	70.0	No	No	
METALS-ST13-11/9/05	GSK110226008	Marrriott Hotel, 38th Floor (roof leve	11/9/05	1728.5	Metals	6020	STL-SAC	11/11/05	2.0	< 69.4	< 0.69	< 0.69	< 6.9	35.7	11.6	11.6	5.9	62.9	No	No	
METALS-ST1-11/10/05	GSK120217001	Southwest Area (street-level)	11/10/05	1652	Metals	6020	STL-SAC	11/12/05	< 1.4	< 72.6	< 0.73	< 0.73	< 7.3	79.4	26.9	10.8	< 3.6	51.1	No	No	
METALS-ST2-11/10/05	GSK120217002	Southwest Area (sidewalk bridge leve	11/10/05	1653.4	Metals	6020	STL-SAC	11/12/05	1.8	< 72.6	< 0.72	< 0.72	< 7.2	80.1	23.2	34.4	6.5	94.2	No	No	
METALS-ST4-11/10/05	GSK120217003	Northwest Area (street-level)	11/10/05	1604.3	Metals	6020	STL-SAC	11/12/05	< 1.5	< 74.8	< 0.75	< 0.75	< 7.5	165	14.7	10.6	< 3.7	63.3	No	No	
METALS-ST5-11/10/05	GSK120217004	Firehouse #10 (roof level)	11/10/05	1800.5	Metals	6020	STL-SAC	11/12/05	< 1.3	< 66.6	< 0.67	< 0.67	< 6.7	42.1	5.5	8.5	< 3.4	23.2	No	No	
METALS-ST10-11/10/05	GSK120217005	North Side Sidewalk Bridgr	11/10/05	1788.1	Metals	6020	STL-SAC	11/12/05	< 1.3	< 67.1	< 0.67	< 0.67	< 6.7	18.1	4.8	8.5	< 3.4	22.3	No	No	
METALS-ST11-11/10/05	GSK120217006	90 Trinity Place (roof level)	11/10/05	1843.4	Metals	6020	STL-SAC	11/12/05	< 1.3	< 65.1	< 0.65	< 0.65	< 6.5	47.3	8.0	10	5.2	23.3	No	No	
METALS-ST12-11/10/05	GSK120217007	110 Greenwich Street (roof level)	11/10/05	1715.4	Metals	6020	STL-SAC	11/12/05	< 1.4	< 70.0	< 0.70	< 0.70	< 7.0	70.5	5.7	7.6	4.2	19.7	No	No	
METALS-ST13-11/10/05	GSK120217008	Marrriott Hotel, 38th Floor (roof leve	11/10/05	1670.3	Metals	6020	STL-SAC	11/12/05	< 1.4	< 71.8	< 0.72	< 0.72	< 7.2	25.4	3.4	4.7	< 3.6	14.7	No	No	