

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000			
EPA Site Specific Trigger Levels									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000	Air Quality	Exceeds EPA Site Specific Trigger Levels	Comments
METALS-ST11-11/30/06	G6L020206001	Southwest Area (sidewalk bridge level)	11/30/2006	1726.8	Metals	6020	STL-SAC	12/02/2006	1.9	< 69.5	< 0.69	< 0.69	< 6.9	174	16.5	14.0	5.6	50.3	No	No	
<EPA> METALS-ST11-11/30/06	G6L020206002	Southwest Area (sidewalk bridge level)	11/30/2006	1754.3	Metals	6020	STL-SAC	12/02/2006	2.4	< 68.4	< 0.68	< 0.68	< 6.8	215	13.3	12.2	5.4	45.3	No	No	
METALS-ST4-11/30/06	G6L020206003	Northwest Area (street-level)	11/30/2006	1797.5	Metals	6020	STL-SAC	12/02/2006	2.2	< 66.8	< 0.67	< 0.67	< 6.7	43.2	53.1	14.2	5.1	65.0	No	No	
METALS-ST5-11/30/06	G6L020206004	Firehouse #10 (roof level)	11/30/2006	1809.9	Metals	6020	STL-SAC	12/02/2006	2.2	< 66.3	< 0.66	< 0.66	< 6.6	66.6	18.5	21.6	5.4	61.5	No	No	
METALS-ST10-11/30/06	G6L020206005	North Side Sidewalk Bridge	11/30/2006	1788.2	Metals	6020	STL-SAC	12/02/2006	2.4	< 67.1	< 0.67	< 0.67	< 6.7	44.7	17.0	24.3	6.0	49.7	No	No	
<EPA> METALS-ST11-11/30/06	G6L020206006	90 Trinity Place (roof level)	11/30/2006	1774.4	Metals	6020	STL-SAC	12/02/2006	1.4	< 67.6	< 0.68	< 0.68	< 6.8	107	11.7	8.7	3.9	34.2	No	No	
METALS-ST12-11/30/06	G6L020206007	110 Greenwich Street (roof level)	11/30/2006	1757.8	Metals	6020	STL-SAC	12/02/2006	1.5	< 68.3	< 0.68	< 0.68	< 6.8	60.7	12.6	9.2	4.0	35.3	No	No	
METALS-ST13-11/30/06	G6L020206008	Marriott Hotel, 38th Floor (roof level)	11/30/2006	1777.9	Metals	6020	STL-SAC	12/02/2006	< 1.3	< 67.5	< 0.67	< 0.67	< 6.7	81.1	5.2	8.6	4.6	33.0	No	No	
METALS-ST14-11/30/06	G6L020206009	West Face - South end at corner (scalloping level)	11/30/2006	1692.6	Metals	6020	STL-SAC	12/02/2006	< 1.4	< 70.9	< 0.71	< 0.71	< 7.1	72.3	3.2	4.4	< 3.5	21.1	No	No	
METALS-ST15-11/30/06	G6L020206010	South Face - East end at corner (scalloping level)	11/30/2006	1666.4	Metals	6020	STL-SAC	12/02/2006	< 1.4	< 72.0	< 0.72	< 0.72	< 7.2	31.4	4.2	4.2	< 3.6	20.1	No	No	
METALS-ST16-11/30/06	G6L020206011	East Face - North end at corner (scalloping level)	11/30/2006	1708.5	Metals	6020	STL-SAC	12/02/2006	< 1.4	< 70.2	< 0.70	< 0.70	< 7.0	92.6	4.3	5.6	< 3.5	40.6	No	No	
METALS-ST17-11/30/06	G6L020206012	North Face - West end at corner (scalloping level)	11/30/2006	1667.2	Metals	6020	STL-SAC	12/02/2006	< 1.4	< 72.0	< 0.72	< 0.72	< 7.2	146	5.2	9.8	3.6	26.7	No	No	
METALS-ST18-11/30/06	G6L020206013	Southwest Area (sidewalk bridge level)	12/01/2006	1707.2	Metals	6020	STL-SAC	12/05/2006	< 1.4	< 70.3	< 0.70	< 0.70	< 7.0	130	12.4	8.6	4.4	49.0	No	No	
METALS-ST2-12/01/06	G6L050134002	Southwest Area (sidewalk bridge level)	12/01/2006	1747.9	Metals	6020	STL-SAC	12/05/2006	< 1.4	< 65.9	< 0.69	< 0.69	< 6.9	154	9.8	4.8	4.8	44.4	No	No	
METALS-ST4-12/01/06	G6L050134003	Northwest Area (street-level)	12/01/2006	1745.6	Metals	6020	STL-SAC	12/05/2006	< 1.4	< 68.7	< 0.69	< 0.69	< 6.9	32.5	13.1	4.2	4.2	47.3	No	No	
METALS-ST5-12/01/06	G6L050134004	Firehouse #10 (roof level)	12/01/2006	1748.1	Metals	6020	STL-SAC	12/05/2006	1.4	< 68.6	< 0.69	< 0.69	< 6.9	61.8	9.4	7.9	5.3	77.1	No	No	
METALS-ST10-12/01/06	G6L050134005	North Side Sidewalk Bridge	12/01/2006	1797.0	Metals	6020	STL-SAC	12/05/2006	1.3	< 66.8	< 0.67	< 0.67	< 6.7	43.9	8.4	12.2	4.4	44.4	No	No	
METALS-ST11-12/01/06	G6L050134006	90 Trinity Place (roof level)	12/01/2006	1828.6	Metals	6020	STL-SAC	12/05/2006	1.5	< 65.6	< 0.66	< 0.66	< 6.6	75.7	11.2	9.4	4.3	35.0	No	No	
METALS-ST13-12/01/06	G6L050134007	Marriott Hotel, 38th Floor (roof level)	12/01/2006	1675.5	Metals	6020	STL-SAC	12/05/2006	< 1.4	< 71.6	< 0.72	< 0.72	< 7.2	102	7.4	8.0	5.6	57.4	No	No	
METALS-ST14-12/01/06	G6L050134008	West Face - South end at corner (scalloping level)	12/01/2006	1687.5	Metals	6020	STL-SAC	12/05/2006	< 1.4	< 71.1	< 0.71	< 0.71	< 7.1	40.5	4.2	5.1	< 3.6	26.9	No	No	
METALS-ST15-12/01/06	G6L050134009	South Face - East end at corner (scalloping level)	12/01/2006	1679.2	Metals	6020	STL-SAC	12/05/2006	< 1.4	< 71.5	< 0.71	< 0.71	< 7.1	58.9	4.5	3.6	4.5	42.2	No	No	
METALS-ST16-12/01/06	G6L050134010	East Face - North end at corner (scalloping level)	12/01/2006	1683.1	Metals	6020	STL-SAC	12/05/2006	< 1.4	< 71.3	< 0.71	< 0.71	< 7.1	92.3	4.8	7.1	5.2	38.9	No	No	
METALS-ST17-12/01/06	G6L050134011	North Face - West end at corner (scalloping level)	12/01/2006	1684.8	Metals	6020	STL-SAC	12/05/2006	< 1.4	< 71.2	< 0.71	< 0.71	< 7.1	81.8	5.6	4.0	34.5	No	No		
METALS-ST18-12/02/06	G6L050139001	Southwest Area (sidewalk bridge level)	12/02/2006	1742.1	Metals	6020	STL-SAC	12/05/2006	1.6	< 68.9	< 0.69	< 0.69	< 6.9	165	5.5	5.5	4.3	28.4	No	No	
METALS-ST19-12/02/06	G6L050139002	Southwest Area (sidewalk bridge level)	12/02/2006	1776.8	Metals	6020	STL-SAC	12/05/2006	1.9	< 67.5	< 0.68	< 0.68	< 6.8	166	5.0	11.5	6.2	26.9	No	No	
METALS-ST2-12/02/06	G6L050139003	Northwest Area (street-level)	12/02/2006	1771.7	Metals	6020	STL-SAC	12/05/2006	< 1.4	< 67.7	< 0.68	< 0.68	< 6.8	28.4	4.7	5.5	3.8	20.9	No	No	
METALS-ST5-12/02/06	G6L050139004	Firehouse #10 (roof level)	12/02/2006	1816.9	Metals	6020	STL-SAC	12/05/2006	1.7	< 66.6	< 0.66	< 0.66	< 6.6	70	6.6	19.0	5.8	63.2	No	No	
METALS-ST10-12/02/06	G6L050139005	North Side Sidewalk Bridge	12/02/2006	1773.4	Metals	6020	STL-SAC	12/05/2006	1.4	< 67.7	< 0.68	< 0.68	< 6.8	31.7	5.3	10.4	4.4	33.5	No	No	
METALS-ST11-12/02/06	G6L050139006	90 Trinity Place (roof level)	12/02/2006	1789.2	Metals	6020	STL-SAC	12/05/2006	1.5	< 67.1	< 0.67	< 0.67	< 6.7	88.0	3.8	7.4	7.4	24.1	No	No	
METALS-ST12-12/02/06	G6L050139007	110 Greenwich Street (roof level)	12/02/2006	1731.3	Metals	6020	STL-SAC	12/05/2006	1.5	< 69.3	< 0.69	< 0.69	< 6.9	52.3	4.5	7.1	7.1	22.3	No	No	
METALS-ST13-12/02/06	G6L050139008	Marriott Hotel, 38th Floor (roof level)	12/02/2006	1788.4	Metals	6020	STL-SAC	12/05/2006	< 1.3	< 67.1	< 0.67	< 0.67	< 6.7	68.6	3.2	4.5	5.7	17.8	No	No	
METALS-ST14-12/02/06	G6L050139009	West Face - South end at corner (scalloping level)	12/02/2006	1809.2	Metals	6020	STL-SAC	12/05/2006	< 1.3	< 66.3	< 0.66	< 0.66	< 6.6	35.3	2.8	3.6	< 3.3	< 13.3	No	No	
METALS-ST15-12/02/06	G6L050139010	South Face - East end at corner (scalloping level)	12/02/2006	1786.1	Metals	6020	STL-SAC	12/05/2006	< 1.3	< 67.2	< 0.67	< 0.67	< 6.7	79.9	3.1	4.7	4.7	15.1	No	No	
METALS-ST16-12/02/06	G6L050139011	East Face - North end at corner (scalloping level)	12/02/2006	1786.4	Metals	6020	STL-SAC	12/05/2006	< 1.3	< 67.2	< 0.67	< 0.67	< 6.7	67.5	3.5	6.6	4.8	23.2	No	No	
METALS-ST17-12/02/06	G6L050139012	North Face - West end at corner (scalloping level)	12/02/2006	1797.7	Metals	6020	STL-SAC	12/05/2006	< 1.3	< 66.8	< 0.67	< 0.67	< 6.7	46.9	4.0	4.0	< 3.3	20.2	No	No	
METALS-ST18-12/03/06	G6L050143001	Southwest Area (sidewalk bridge level)	12/03/2006	1788.8	Metals	6020	STL-SAC	12/05/2006	3.1	< 67.1	< 0.67	< 0.67	< 6.7	202	13.6	11.3	6.7	43.4	No	No	
METALS-ST19-12/03/06	G6L050143002	Southwest Area (sidewalk bridge level)	12/03/2006	1854.9	Metals	6020	STL-SAC	12/05/2006	2.9	< 64.7	< 0.65	< 0.65	< 6.5	242	8.8	15.2	7.5	36.9	No	No	
METALS-ST4-12/03/06	G6L050143003	Northwest Area (street-level)	12/03/2006	1860.7	Metals	6020	STL-SAC	12/05/2006	2.8	< 64.5	< 0.64	< 0.64	< 6.4	47.9	13.1	12.9	6.9	43.4	No	No	
METALS-ST5-12/03/06	G6L050143004	Firehouse #10 (roof level)	12/03/2006	1753.8	Metals	6020	STL-SAC	12/05/2006	2.5	< 68.4	< 0.68	< 0.68	< 6.8	69.6	10.8	20.6	8.6	49.5	No	No	
METALS-ST10-12/03/06	G6L050143005	North Side Sidewalk Bridge	12/03/2006	1778.9	Metals	6020	STL-SAC	12/05/2006	2.8	< 67.4	< 0.67	< 0.67	< 6.7	71.3	10.1	16.5	9.3	35.9	No	No	
METALS-ST11-12/03/06	G6L050143006	90 Trinity Place (roof level)	12/03/2006	1747.8	Metals	6020	STL-SAC	12/05/2006	2.1	< 68.6	< 0.69	< 0.69	< 6.9	103	7.6	10.6	7.8	29.4	No	No	
METALS-ST12-12/03/06	G6L050143007	110 Greenwich Street (roof level)	12/03/2006	1851.7	Metals	6020	STL-SAC	12/05/2006	2.2	< 64.8	< 0.65	< 0.65	< 6.5	49.5	9.6	10.4	7.2	42.7	No	No	
METALS-ST13-12/03/06	G6L050143008	Marriott Hotel, 38th Floor (roof level)	12/03/2006	1887.1	Metals	6020	STL-SAC	12/05/2006	2.0	< 63.6	< 0.64	< 0.64	< 6.4	102	6.8	9.4	8.6	29.5	No	No	
METALS-ST14-12/03/06	G6L050143009	West Face - South end at corner (scalloping level)	12/03/2006	2033.2	Metals	6020	STL-SAC	12/05/2006	1.6	< 59.0	< 0.59	< 0.59	< 5.9	39.6	7.0	8.3	5.6	23.0	No	No	
METALS-ST15-12/03/06	G6L050143010	South Face - East end at corner (scalloping level)	12/03/2006	1990.2	Metals	6020	STL-SAC	12/05/2006	1.7	< 60.3	< 0.60	< 0.60	< 6.0	80.5	8.4	6.5	30.9	No	No		
METALS-ST16-12/03/06	G6L050143011	East Face - North end at corner (scalloping level)	12/03/2006	1999.4	Metals	6020	STL-SAC	12/05/2006	1.7	< 60.0	&										