

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-1/9/09	030900903-0001	Southwest Area (sidewalk bridge level)	1/9/09	1	3.140	Asbestos	PCME	EMSL	1/12/09	< 0.00079	No	No	
ASBESTOS-ST2-1/9/09	030900903-0002	Southeast Area (sidewalk bridge level)	1/9/09	1	3.040	Asbestos	PCME	EMSL	1/12/09	< 0.00081	No	No	
ASBESTOS-ST4-1/9/09	030900903-0003	Northwest Area (street-level)	1/9/09	1	3.050	Asbestos	PCME	EMSL	1/12/09	< 0.00081	No	No	
ASBESTOS-ST5-1/9/09	030900903-0004	Firehouse #10 (roof level)	1/9/09	1	2.980	Asbestos	PCME	EMSL	1/12/09	< 0.00083	No	No	
ASBESTOS-ST10-1/9/09	030900903-0005	North Side Sidewalk Bridge	1/9/09	1	3.060	Asbestos	PCME	EMSL	1/12/09	< 0.00081	No	No	
ASBESTOS-ST11-1/9/09	030900903-0006	90 Trinity Place (roof level)	1/9/09	1	3.050	Asbestos	PCME	EMSL	1/12/09	< 0.00081	No	No	
ASBESTOS-ST12-1/9/09	030900903-0007	110 Greenwich Street (roof level)	1/9/09	1	3.020	Asbestos	PCME	EMSL	1/12/09	< 0.00082	No	No	
ASBESTOS-ST13-1/9/09	030900903-0008	Marriott Hotel, 38th Floor (roof level)	1/9/09	1	3.010	Asbestos	PCME	EMSL	1/12/09	< 0.00082	No	No	
ASBESTOS-ST14-1/9/09	030900903-0009	West Face - South end at corner (scaffolding level)	1/9/09	1	2.890	Asbestos	PCME	EMSL	1/12/09	< 0.00085	No	No	
ASBESTOS-ST15-1/9/09	030900903-0010	South Face - East end at corner (scaffolding level)	1/9/09	1	2.820	Asbestos	PCME	EMSL	1/12/09	< 0.00088	No	No	
ASBESTOS-ST16-1/9/09	030900903-0011	East Face - North end at corner (scaffolding level)	1/9/09	1	2.850	Asbestos	PCME	EMSL	1/12/09	< 0.00087	No	No	
ASBESTOS-ST17-1/9/09	030900903-0012	North Face - West end at corner (scaffolding level)	1/9/09	1	2.860	Asbestos	PCME	EMSL	1/12/09	< 0.00086	No	No	
ASBESTOS-ST1-1/10/09	030900953-0001	Southwest Area (sidewalk bridge level)	1/10/09	1	3.120	Asbestos	PCME	EMSL	1/12/09	< 0.00079	No	No	
ASBESTOS-ST2-1/10/09	030900953-0002	Southeast Area (sidewalk bridge level)	1/10/09	1	3.000	Asbestos	PCME	EMSL	1/12/09	< 0.00082	No	No	
ASBESTOS-ST4-1/10/09	030900953-0003	Northwest Area (street-level)	1/10/09	1	2.970	Asbestos	PCME	EMSL	1/12/09	< 0.00083	No	No	
ASBESTOS-ST5-1/10/09	030900953-0004	Firehouse #10 (roof level)	1/10/09	1	3.050	Asbestos	PCME	EMSL	1/12/09	< 0.00081	No	No	
ASBESTOS-ST10-1/10/09	030900953-0005	North Side Sidewalk Bridge	1/10/09	1	3.110	Asbestos	PCME	EMSL	1/12/09	< 0.00079	No	No	
ASBESTOS-ST11-1/10/09	030900953-0006	90 Trinity Place (roof level)	1/10/09	1	3.280	Asbestos	PCME	EMSL	1/12/09	< 0.00082	No	No	
ASBESTOS-ST12-1/10/09	030900953-0007	110 Greenwich Street (roof level)	1/10/09	1	3.000	Asbestos	PCME	EMSL	1/12/09	< 0.00082	No	No	
ASBESTOS-ST13-1/10/09	030900953-0008	Marriott Hotel, 38th Floor (roof level)	1/10/09	1	2.980	Asbestos	PCME	EMSL	1/12/09	< 0.00083	No	No	
ASBESTOS-ST14-1/10/09	030900953-0009	West Face - South end at corner (scaffolding level)	1/10/09	1	6.160	Asbestos	PCME	EMSL	1/12/09	< 0.00080	No	No	Note 1
ASBESTOS-ST15-1/10/09	030900953-0010	South Face - East end at corner (scaffolding level)	1/10/09	1	6.190	Asbestos	PCME	EMSL	1/12/09	< 0.00080	No	No	Note 1
ASBESTOS-ST16-1/10/09	030900953-0011	East Face - North end at corner (scaffolding level)	1/10/09	1	6.310	Asbestos	PCME	EMSL	1/12/09	< 0.00078	No	No	Note 1
ASBESTOS-ST17-1/10/09	030900953-0012	North Face - West end at corner (scaffolding level)	1/10/09	1	6.310	Asbestos	PCME	EMSL	1/12/09	< 0.00078	No	No	Note 1
ASBESTOS-ST1-1/11/09	030900954-0001	Southwest Area (sidewalk bridge level)	1/11/09	1	2.970	Asbestos	PCME	EMSL	1/12/09	< 0.00083	No	No	
ASBESTOS-ST2-1/11/09	030900954-0002	Southeast Area (sidewalk bridge level)	1/11/09	1	3.010	Asbestos	PCME	EMSL	1/12/09	< 0.00082	No	No	
ASBESTOS-ST4-1/11/09	030900954-0003	Northwest Area (street-level)	1/11/09	1	2.910	Asbestos	PCME	EMSL	1/12/09	< 0.00085	No	No	
ASBESTOS-ST5-1/11/09	030900954-0004	Firehouse #10 (roof level)	1/11/09	1	2.940	Asbestos	PCME	EMSL	1/12/09	< 0.00084	No	No	
ASBESTOS-ST10-1/11/09	030900954-0005	North Side Sidewalk Bridge	1/11/09	1	3.070	Asbestos	PCME	EMSL	1/12/09	< 0.00088	No	No	
ASBESTOS-ST11-1/11/09	030900954-0006	90 Trinity Place (roof level)	1/11/09	1	3.000	Asbestos	PCME	EMSL	1/12/09	< 0.00082	No	No	
ASBESTOS-ST12-1/11/09	030900954-0007	110 Greenwich Street (roof level)	1/11/09	1	3.000	Asbestos	PCME	EMSL	1/12/09	< 0.00082	No	No	
ASBESTOS-ST13-1/11/09	030900954-0008	Marriott Hotel, 38th Floor (roof level)	1/11/09	1	3.000	Asbestos	PCME	EMSL	1/12/09	< 0.00082	No	No	
ASBESTOS-ST1-1/12/09	030901076-0001	Southwest Area (sidewalk bridge level)	1/12/09	1	3.120	Asbestos	PCME	EMSL	1/13/09	< 0.00079	No	No	
ASBESTOS-ST2-1/12/09	030901076-0002	Southeast Area (sidewalk bridge level)	1/12/09	1	3.110	Asbestos	PCME	EMSL	1/13/09	< 0.00079	No	No	
ASBESTOS-ST4-1/12/09	030901076-0003	Northwest Area (street-level)	1/12/09	1	3.060	Asbestos	PCME	EMSL	1/13/09	< 0.00081	No	No	
ASBESTOS-ST5-1/12/09	030901076-0004	Firehouse #10 (roof level)	1/12/09	1	3.000	Asbestos	PCME	EMSL	1/13/09	< 0.00082	No	No	
ASBESTOS-ST10-1/12/09	030901076-0005	North Side Sidewalk Bridge	1/12/09	1	3.080	Asbestos	PCME	EMSL	1/13/09	< 0.00080	No	No	
ASBESTOS-ST11-1/12/09	030901076-0006	90 Trinity Place (roof level)	1/12/09	1	3.080	Asbestos	PCME	EMSL	1/13/09	< 0.00080	No	No	
ASBESTOS-ST12-1/12/09	030901076-0007	110 Greenwich Street (roof level)	1/12/09	1	3.070	Asbestos	PCME	EMSL	1/13/09	< 0.00080	No	No	
ASBESTOS-ST13-1/12/09	030901076-0008	Marriott Hotel, 38th Floor (roof level)	1/12/09	1	2.980	Asbestos	PCME	EMSL	1/13/09	< 0.00083	No	No	
ASBESTOS-ST14-1/12/09	030901076-0009	West Face - South end at corner (scaffolding level)	1/12/09	1	3.020	Asbestos	PCME	EMSL	1/13/09	< 0.00082	No	No	
ASBESTOS-ST15-1/12/09	030901076-0010	South Face - East end at corner (scaffolding level)	1/12/09	1	2.980	Asbestos	PCME	EMSL	1/13/09	< 0.00083	No	No	
ASBESTOS-ST16-1/12/09	030901076-0011	East Face - North end at corner (scaffolding level)	1/12/09	1	3.110	Asbestos	PCME	EMSL	1/13/09	< 0.00079	No	No	
ASBESTOS-ST17-1/12/09	030901076-0012	North Face - West end at corner (scaffolding level)	1/12/09	1	2.980	Asbestos	PCME	EMSL	1/13/09	< 0.00083	No	No	

Note:

- The asbestos sample volumes at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 [South Face - East end at corner [scaffolding level]], Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on January 10, 2009 represent 2 consecutive 24-hour periods as samples could not be retrieved on January 11, 2009 due to hazardous conditions posed by ice and snow on the scaffolding.
- Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level: 15th floor]), Station 15 [South Face - East end at corner [scaffolding level]], Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on January 11, 2009 were not accessible due to hazardous conditions posed by ice and snow on the scaffolding. Refer to samples collected on January 10, 2009 which reflect 2 consecutive 24-hour periods.