

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-1/11/08	030801080-0001	Southwest Area (sidewalk bridge level)	1/11/08	1	3.010	Asbestos	PCME	EMSL	1/14/08	< 0.00082	No	No	
ASBESTOS-ST2-1/11/08	030801080-0002	Southeast Area (sidewalk bridge level)	1/11/08	1	2.990	Asbestos	PCME	EMSL	1/14/08	< 0.00083	No	No	
ASBESTOS-ST4-1/11/08	030801080-0003	Northwest Area (street-level)	1/11/08	1	3.010	Asbestos	PCME	EMSL	1/14/08	< 0.00082	No	No	
ASBESTOS-ST5-1/11/08	030801080-0004	Firehouse #10 (roof level)	1/11/08	1	3.120	Asbestos	PCME	EMSL	1/14/08	< 0.00079	No	No	
ASBESTOS-ST10-1/11/08	030801080-0005	North Side Sidewalk Bridge	1/11/08	1	3.000	Asbestos	PCME	EMSL	1/14/08	< 0.00082	No	No	
ASBESTOS-ST11-1/11/08	030801080-0006	90 Trinity Place (roof level)	1/11/08	1	3.040	Asbestos	PCME	EMSL	1/14/08	< 0.00081	No	No	
ASBESTOS-ST12-1/11/08	030801080-0007	110 Greenwich Street (roof level)	1/11/08	1	3.010	Asbestos	PCME	EMSL	1/14/08	< 0.00082	No	No	
ASBESTOS-ST13-1/11/08	030801080-0008	Marriott Hotel, 38th Floor (roof level)	1/11/08	1	3.000	Asbestos	PCME	EMSL	1/14/08	< 0.00082	No	No	
ASBESTOS-ST14-1/11/08	030801080-0009	West Face - South end at corner (scaffolding level)	1/11/08	1	3.040	Asbestos	PCME	EMSL	1/14/08	< 0.00081	No	No	
ASBESTOS-ST15-1/11/08	030801080-0010	South Face - East end at corner (scaffolding level)	1/11/08	1	3.010	Asbestos	PCME	EMSL	1/14/08	< 0.00082	No	No	
ASBESTOS-ST16-1/11/08	030801080-0011	East Face - North end at corner (scaffolding level)	1/11/08	1	3.140	Asbestos	PCME	EMSL	1/14/08	< 0.00086	No	No	
ASBESTOS-ST17-1/11/08	030801080-0012	North Face - West end at corner (scaffolding level)	1/11/08	1	3.060	Asbestos	PCME	EMSL	1/14/08	< 0.00081	No	No	
ASBESTOS-ST1-1/12/08	030801069-0001	Southwest Area (sidewalk bridge level)	1/12/08	1	3.040	Asbestos	PCME	EMSL	1/14/08	< 0.00089	No	No	
ASBESTOS-ST2-1/12/08	030801069-0002	Southeast Area (sidewalk bridge level)	1/12/08	1	3.000	Asbestos	PCME	EMSL	1/14/08	0.00082	No	No	
ASBESTOS-ST4-1/12/08	030801069-0003	Northwest Area (street-level)	1/12/08	1	2.990	Asbestos	PCME	EMSL	1/14/08	< 0.00083	No	No	
ASBESTOS-ST5-1/12/08	030801069-0004	Firehouse #10 (roof level)	1/12/08	1	3.050	Asbestos	PCME	EMSL	1/14/08	< 0.00081	No	No	
ASBESTOS-ST10-1/12/08	030801069-0005	North Side Sidewalk Bridge	1/12/08	1	2.960	Asbestos	PCME	EMSL	1/14/08	< 0.00083	No	No	
ASBESTOS-ST11-1/12/08	030801069-0006	90 Trinity Place (roof level)	1/12/08	1	3.060	Asbestos	PCME	EMSL	1/14/08	< 0.00081	No	No	
ASBESTOS-ST12-1/12/08	030801069-0007	110 Greenwich Street (roof level)	1/12/08	1	3.040	Asbestos	PCME	EMSL	1/14/08	< 0.00081	No	No	
ASBESTOS-ST13-1/12/08	030801069-0008	Marriott Hotel, 38th Floor (roof level)	1/12/08	1	3.000	Asbestos	PCME	EMSL	1/14/08	< 0.00082	No	No	
ASBESTOS-ST14-1/12/08	030801069-0009	West Face - South end at corner (scaffolding level)	1/12/08	1	3.010	Asbestos	PCME	EMSL	1/14/08	< 0.00082	No	No	
ASBESTOS-ST15-1/12/08	030801069-0010	South Face - East end at corner (scaffolding level)	1/12/08	1	3.040	Asbestos	PCME	EMSL	1/14/08	< 0.00081	No	No	
ASBESTOS-ST16-1/12/08	030801069-0011	East Face - North end at corner (scaffolding level)	1/12/08	1	3.020	Asbestos	PCME	EMSL	1/14/08	< 0.00082	No	No	
ASBESTOS-ST17-1/12/08	030801069-0012	North Face - West end at corner (scaffolding level)	1/12/08	1	3.040	Asbestos	PCME	EMSL	1/14/08	< 0.00081	No	No	
ASBESTOS-ST1-1/13/08	030801067-0001	Southwest Area (sidewalk bridge level)	1/13/08	1	3.040	Asbestos	PCME	EMSL	1/14/08	< 0.00081	No	No	
ASBESTOS-ST2-1/13/08	030801067-0002	Southeast Area (sidewalk bridge level)	1/13/08	1	2.980	Asbestos	PCME	EMSL	1/14/08	< 0.00083	No	No	
ASBESTOS-ST4-1/13/08	030801067-0003	Northwest Area (street-level)	1/13/08	1	2.980	Asbestos	PCME	EMSL	1/14/08	< 0.00083	No	No	
ASBESTOS-ST5-1/13/08	030801067-0004	Firehouse #10 (roof level)	1/13/08	1	3.000	Asbestos	PCME	EMSL	1/14/08	< 0.00082	No	No	
ASBESTOS-ST10-1/13/08	030801067-0005	North Side Sidewalk Bridge	1/13/08	1	3.010	Asbestos	PCME	EMSL	1/14/08	< 0.00082	No	No	
ASBESTOS-ST11-1/13/08	030801067-0006	90 Trinity Place (roof level)	1/13/08	1	3.010	Asbestos	PCME	EMSL	1/14/08	< 0.00082	No	No	
ASBESTOS-ST12-1/13/08	030801067-0007	110 Greenwich Street (roof level)	1/13/08	1	3.040	Asbestos	PCME	EMSL	1/14/08	< 0.00081	No	No	
ASBESTOS-ST13-1/13/08	030801067-0008	Marriott Hotel, 38th Floor (roof level)	1/13/08	1	3.070	Asbestos	PCME	EMSL	1/14/08	< 0.00080	No	No	
ASBESTOS-ST14-1/13/08	030801067-0009	West Face - South end at corner (scaffolding level)	1/13/08	1	2.990	Asbestos	PCME	EMSL	1/14/08	< 0.00083	No	No	
ASBESTOS-ST15-1/13/08	030801067-0010	South Face - East end at corner (scaffolding level)	1/13/08	1	3.200	Asbestos	PCME	EMSL	1/14/08	< 0.00084	No	No	
ASBESTOS-ST16-1/13/08	030801067-0011	East Face - North end at corner (scaffolding level)	1/13/08	1	3.000	Asbestos	PCME	EMSL	1/14/08	< 0.00082	No	No	
ASBESTOS-ST17-1/13/08	030801067-0012	North Face - West end at corner (scaffolding level)	1/13/08	1	3.090	Asbestos	PCME	EMSL	1/14/08	< 0.00080	No	No	