

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-1/13/06	030601448-0001	Southwest Area (sidewalk bridge level)	1/13/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST2-1/13/06	030601448-0002	Southeast Area (sidewalk bridge level)	1/13/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST4-1/13/06	030601448-0003	Northwest Area (street-level)	1/13/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST5-1/13/06	030601448-0004	Firehouse #10 (roof level)	1/13/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST10-1/13/06	030601448-0005	North Side Sidewalk Bridge	1/13/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST11-1/13/06	030601448-0006	90 Trinity Place (roof level)	1/13/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST12-1/13/06	030601448-0007	110 Greenwich Street (roof level)	1/13/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST13-1/13/06	030601448-0008	Marriott Hotel, 38th Floor (roof level)	1/13/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST14-1/13/06	030601448-0009	West Face - South end at corner (scaffolding level)	1/13/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST15-1/13/06	030601448-0010	South Face - East end at corner (scaffolding level)	1/13/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST16-1/13/06	030601448-0011	East Face - North end at corner (scaffolding level)	1/13/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST17-1/13/06	030601448-0012	North Face - West end at corner (scaffolding level)	1/13/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST1-1/14/06	030601452-0001	Southwest Area (sidewalk bridge level)	1/14/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST2-1/14/06	030601452-0002	Southeast Area (sidewalk bridge level)	1/14/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST4-1/14/06	030601452-0003	Northwest Area (street-level)	1/14/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST5-1/14/06	030601452-0004	Firehouse #10 (roof level)	1/14/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST10-1/14/06	030601452-0005	North Side Sidewalk Bridge	1/14/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST11-1/14/06	030601452-0006	90 Trinity Place (roof level)	1/14/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST12-1/14/06	030601452-0007	110 Greenwich Street (roof level)	1/14/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST13-1/14/06	030601452-0009	Marriott Hotel, 38th Floor (roof level)	1/14/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST14-1/14/06	030601452-0009	West Face - South end at corner (scaffolding level)	1/14/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST15-1/14/06	030601452-0010	South Face - East end at corner (scaffolding level)	1/14/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST16-1/14/06	030601452-0011	East Face - North end at corner (scaffolding level)	1/14/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST17-1/14/06	030601452-0012	North Face - West end at corner (scaffolding level)	1/14/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST1-1/15/06	030601455-0001	Southwest Area (sidewalk bridge level)	1/15/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST2-1/15/06	030601455-0002	Southeast Area (sidewalk bridge level)	1/15/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST4-1/15/06	030601455-0003	Northwest Area (street-level)	1/15/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST5-1/15/06	030601455-0004	Firehouse #10 (roof level)	1/15/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST10-1/15/06	030601455-0005	North Side Sidewalk Bridge	1/15/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST11-1/15/06	030601455-0006	90 Trinity Place (roof level)	1/15/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST12-1/15/06	030601455-0007	110 Greenwich Street (roof level)	1/15/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST13-1/15/06	030601455-0008	Marriott Hotel, 38th Floor (roof level)	1/15/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST14-1/15/06	030601455-0009	West Face - South end at corner (scaffolding level)	1/15/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST15-1/15/06	030601455-0010	South Face - East end at corner (scaffolding level)	1/15/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST16-1/15/06	030601455-0011	East Face - North end at corner (scaffolding level)	1/15/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST17-1/15/06	030601455-0012	North Face - West end at corner (scaffolding level)	1/15/06	1	2.970	Asbestos	PCME	EMSL	1/16/06	< 0.00083	No	No	
ASBESTOS-ST1-1/16/06	030601528-0001	Southwest Area (sidewalk bridge level)	1/16/06	1	2.970	Asbestos	PCME	EMSL	1/17/06	< 0.00083	No	No	
ASBESTOS-ST2-1/16/06	030601528-0002	Southeast Area (sidewalk bridge level)	1/16/06	1	2.970	Asbestos	PCME	EMSL	1/17/06	< 0.00083	No	No	
ASBESTOS-ST4-1/16/06	030601528-0003	Northwest Area (street-level)	1/16/06	1	2.970	Asbestos	PCME	EMSL	1/17/06	< 0.00083	No	No	
ASBESTOS-ST5-1/16/06	030601528-0004	Firehouse #10 (roof level)	1/16/06	1	2.970	Asbestos	PCME	EMSL	1/17/06	< 0.00083	No	No	
ASBESTOS-ST10-1/16/06	030601528-0005	North Side Sidewalk Bridge	1/16/06	1	2.970	Asbestos	PCME	EMSL	1/17/06	< 0.00083	No	No	
ASBESTOS-ST100-1/16/06	030601528-0013	Station 10 Field Duplicate	1/16/06	1	2.970	Asbestos	PCME	EMSL	1/17/06	< 0.00083	No	No	
ASBESTOS-ST11-1/16/06	030601528-0006	90 Trinity Place (roof level)	1/16/06	1	2.970	Asbestos	PCME	EMSL	1/17/06	< 0.00083	No	No	
ASBESTOS-ST12-1/16/06	030601528-0007	110 Greenwich Street (roof level)	1/16/06	1	2.970	Asbestos	PCME	EMSL	1/17/06	< 0.00083	No	No	
ASBESTOS-ST13-1/16/06	030601528-0008	Marriott Hotel, 38th Floor (roof level)	1/16/06	1	2.970	Asbestos	PCME	EMSL	1/17/06	< 0.00083	No	No	
ASBESTOS-ST14-1/16/06	030601528-0009	West Face - South end at corner (scaffolding level)	1/16/06	1	2.970	Asbestos	PCME	EMSL	1/17/06	< 0.00083	No	No	
ASBESTOS-ST15-1/16/06	030601528-0010	South Face - East end at corner (scaffolding level)	1/16/06	1	2.970	Asbestos	PCME	EMSL	1/17/06	< 0.00083	No	No	
ASBESTOS-ST16-1/16/06	030601528-0011	East Face - North end at corner (scaffolding level)	1/16/06	1	2.970	Asbestos	PCME	EMSL	1/17/06	< 0.00083	No	No	
ASBESTOS-ST17-1/16/06	030601528-0012	North Face - West end at corner (scaffolding level)	1/16/06	1	2.970	Asbestos	PCME	EMSL	1/17/06	< 0.00083	No	No	