

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality	Site Specific	
										NA	Levels	Trigger Levels	
ASBESTOS-ST1-1/17/09	030901686-0001	Southwest Area (sidewalk bridge level)	1/17/09	1	3.080	Asbestos	PCME	EMSL	1/19/09	< 0.00080	No	No	
ASBESTOS-ST2-1/17/09	030901686-0002	Southeast Area (sidewalk bridge level)	1/17/09	1	3.040	Asbestos	PCME	EMSL	1/19/09	< 0.00081	No	No	
ASBESTOS-ST4-1/17/09	030901686-0003	Northwest Area (street-level)	1/17/09	1	2.980	Asbestos	PCME	EMSL	1/19/09	< 0.00083	No	No	
ASBESTOS-ST5-1/17/09	030901686-0004	Firehouse #10 (roof level)	1/17/09	1	3.000	Asbestos	PCME	EMSL	1/19/09	< 0.00082	No	No	
ASBESTOS-ST10-1/17/09	030901686-0005	North Side Sidewalk Bridge	1/17/09	1	3.020	Asbestos	PCME	EMSL	1/19/09	< 0.00082	No	No	
ASBESTOS-ST11-1/17/09	030901686-0006	90 Trinity Place (roof level)	1/17/09	1	3.060	Asbestos	PCME	EMSL	1/19/09	< 0.00081	No	No	
ASBESTOS-ST12-1/17/09	030901686-0007	110 Greenwich Street (roof level)	1/17/09	1	2.990	Asbestos	PCME	EMSL	1/19/09	< 0.00083	No	No	
ASBESTOS-ST13-1/17/09	030901686-0008	Marriott Hotel, 38th Floor (roof level)	1/17/09	1	3.110	Asbestos	PCME	EMSL	1/19/09	< 0.00079	No	No	
ASBESTOS-ST14-1/17/09	030901686-0009	West Face - South end at corner (scaffolding level)	1/17/09	1	2.960	Asbestos	PCME	EMSL	1/19/09	< 0.00083	No	No	
ASBESTOS-ST15-1/17/09	030901686-0010	South Face - East end at corner (scaffolding level)	1/17/09	1	2.960	Asbestos	PCME	EMSL	1/19/09	< 0.00083	No	No	
ASBESTOS-ST16-1/17/09	030901686-0011	East Face - North end at corner (scaffolding level)	1/17/09	1	2.980	Asbestos	PCME	EMSL	1/19/09	< 0.00083	No	No	
ASBESTOS-ST17-1/17/09	030901686-0012	North Face - West end at corner (scaffolding level)	1/17/09	1	2.940	Asbestos	PCME	EMSL	1/19/09	< 0.00084	No	No	
ASBESTOS-ST1-1/18/09	030901689-0001	Southwest Area (sidewalk bridge level)	1/18/09	1	3.180	Asbestos	PCME	EMSL	1/19/09	< 0.00085	No	No	
ASBESTOS-ST2-1/18/09	030901689-0002	Southeast Area (sidewalk bridge level)	1/18/09	1	3.120	Asbestos	PCME	EMSL	1/19/09	< 0.00086	No	No	
ASBESTOS-ST4-1/18/09	030901689-0003	Northwest Area (street-level)	1/18/09	1	3.200	Asbestos	PCME	EMSL	1/19/09	< 0.00084	No	No	
ASBESTOS-ST5-1/18/09	030901689-0004	Firehouse #10 (roof level)	1/18/09	1	2.970	Asbestos	PCME	EMSL	1/19/09	< 0.00083	No	No	
ASBESTOS-ST10-1/18/09	030901689-0005	North Side Sidewalk Bridge	1/18/09	1	3.070	Asbestos	PCME	EMSL	1/19/09	< 0.00088	No	No	
ASBESTOS-ST11-1/18/09	030901689-0006	90 Trinity Place (roof level)	1/18/09	1	2.990	Asbestos	PCME	EMSL	1/19/09	< 0.00083	No	No	
ASBESTOS-ST12-1/18/09	030901689-0007	110 Greenwich Street (roof level)	1/18/09	1	3.060	Asbestos	PCME	EMSL	1/19/09	< 0.00081	No	No	
ASBESTOS-ST13-1/18/09	030901689-0008	Marriott Hotel, 38th Floor (roof level)	1/18/09	1	3.080	Asbestos	PCME	EMSL	1/19/09	< 0.00087	No	No	
ASBESTOS-ST14-1/18/09	030901689-0009	West Face - South end at corner (scaffolding level)	1/18/09	1	3.250	Asbestos	PCME	EMSL	1/19/09	< 0.00083	No	No	
ASBESTOS-ST15-1/18/09	030901689-0010	South Face - East end at corner (scaffolding level)	1/18/09	1	3.240	Asbestos	PCME	EMSL	1/19/09	< 0.00083	No	No	
ASBESTOS-ST16-1/18/09	030901689-0011	East Face - North end at corner (scaffolding level)	1/18/09	1	3.250	Asbestos	PCME	EMSL	1/19/09	< 0.00083	No	No	
ASBESTOS-ST17-1/18/09	030901689-0012	North Face - West end at corner (scaffolding level)	1/18/09	1	3.190	Asbestos	PCME	EMSL	1/19/09	< 0.00084	No	No	
ASBESTOS-ST1-1/19/09	030901828-0001	Southwest Area (sidewalk bridge level)	1/19/09	1	3.040	Asbestos	PCME	EMSL	1/20/09	< 0.00081	No	No	
ASBESTOS-ST2-1/19/09	030901828-0002	Southeast Area (sidewalk bridge level)	1/19/09	1	3.060	Asbestos	PCME	EMSL	1/20/09	< 0.00081	No	No	
ASBESTOS-ST4-1/19/09	030901828-0003	Northwest Area (street-level)	1/19/09	1	3.060	Asbestos	PCME	EMSL	1/20/09	< 0.00081	No	No	
ASBESTOS-ST5-1/19/09	030901828-0004	Firehouse #10 (roof level)	1/19/09	1	3.010	Asbestos	PCME	EMSL	1/20/09	< 0.00082	No	No	
ASBESTOS-ST10-1/19/09	030901828-0005	North Side Sidewalk Bridge	1/19/09	1	2.860	Asbestos	PCME	EMSL	1/20/09	< 0.00086	No	No	
ASBESTOS-ST11-1/19/09	030901828-0006	90 Trinity Place (roof level)	1/19/09	1	2.970	Asbestos	PCME	EMSL	1/20/09	< 0.00083	No	No	
ASBESTOS-ST12-1/19/09	030901828-0007	110 Greenwich Street (roof level)	1/19/09	1	3.000	Asbestos	PCME	EMSL	1/20/09	< 0.00082	No	No	
ASBESTOS-ST13-1/19/09	030901828-0008	Marriott Hotel, 38th Floor (roof level)	1/19/09	1	2.950	Asbestos	PCME	EMSL	1/20/09	< 0.00084	No	No	
ASBESTOS-ST14-1/19/09	030901828-0009	West Face - South end at corner (scaffolding level)	1/19/09	1	3.050	Asbestos	PCME	EMSL	1/20/09	< 0.00081	No	No	
ASBESTOS-ST15-1/19/09	030901828-0010	South Face - East end at corner (scaffolding level)	1/19/09	1	2.990	Asbestos	PCME	EMSL	1/20/09	< 0.00083	No	No	
ASBESTOS-ST16-1/19/09	030901828-0011	East Face - North end at corner (scaffolding level)	1/19/09	1	2.970	Asbestos	PCME	EMSL	1/20/09	< 0.00083	No	No	
ASBESTOS-ST17-1/19/09	030901828-0012	North Face - West end at corner (scaffolding level)	1/19/09	1	3.020	Asbestos	PCME	EMSL	1/20/09	< 0.00082	No	No	
ASBESTOS-ST1-1/20/09	030902022-0001	Southwest Area (sidewalk bridge level)	1/20/09	1	3.110	Asbestos	PCME	EMSL	1/21/09	< 0.00079	No	No	
ASBESTOS-ST2-1/20/09	030902022-0002	Southeast Area (sidewalk bridge level)	1/20/09	1	3.080	Asbestos	PCME	EMSL	1/21/09	< 0.00080	No	No	
ASBESTOS-ST4-1/20/09	030902022-0003	Northwest Area (street-level)	1/20/09	1	3.010	Asbestos	PCME	EMSL	1/21/09	< 0.00082	No	No	
ASBESTOS-ST5-1/20/09	030902022-0004	Firehouse #10 (roof level)	1/20/09	1	3.020	Asbestos	PCME	EMSL	1/21/09	< 0.00082	No	No	
ASBESTOS-ST10-1/20/09	030902022-0005	North Side Sidewalk Bridge	1/20/09	1	2.970	Asbestos	PCME	EMSL	1/21/09	< 0.00083	No	No	
ASBESTOS-ST11-1/20/09	030902022-0006	90 Trinity Place (roof level)	1/20/09	1	3.050	Asbestos	PCME	EMSL	1/21/09	< 0.00081	No	No	
ASBESTOS-ST12-1/20/09	030902022-0007	110 Greenwich Street (roof level)	1/20/09	1	2.980	Asbestos	PCME	EMSL	1/21/09	< 0.00083	No	No	
ASBESTOS-ST13-1/20/09	030902022-0008	Marriott Hotel, 38th Floor (roof level)	1/20/09	1	3.120	Asbestos	PCME	EMSL	1/21/09	< 0.00079	No	No	
ASBESTOS-ST14-1/20/09	030902022-0009	West Face - South end at corner (scaffolding level)	1/20/09	1	2.980	Asbestos	PCME	EMSL	1/21/09	< 0.00083	No	No	
ASBESTOS-ST15-1/20/09	030902022-0010	South Face - East end at corner (scaffolding level)	1/20/09	1	3.030	Asbestos	PCME	EMSL	1/21/09	< 0.00081	No	No	
ASBESTOS-ST16-1/20/09	030902022-0011	East Face - North end at corner (scaffolding level)	1/20/09	1	3.090	Asbestos	PCME	EMSL	1/21/09	< 0.00080	No	No	
ASBESTOS-ST17-1/20/09	030902022-0012	North Face - West end at corner (scaffolding level)	1/20/09	1	2.960	Asbestos	PCME	EMSL	1/21/09	< 0.00083	No	No	