

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-1/24/09	030902454-0001	Southwest Area (sidewalk bridge level)	1/24/09	1	3.030	Asbestos	PCME	EMSL	1/26/09	< 0.00081	No	No	
ASBESTOS-ST2-1/24/09	030902454-0002	Southeast Area (sidewalk bridge level)	1/24/09	1	3.040	Asbestos	PCME	EMSL	1/26/09	< 0.00081	No	No	
ASBESTOS-ST4-1/24/09	030902454-0003	Northwest Area (street-level)	1/24/09	1	2.980	Asbestos	PCME	EMSL	1/26/09	< 0.00083	No	No	
ASBESTOS-ST5-1/24/09	030902454-0004	Firehouse #10 (roof level)	1/24/09	1	3.010	Asbestos	PCME	EMSL	1/26/09	< 0.00082	No	No	
ASBESTOS-ST10-1/24/09	030902454-0005	North Side Sidewalk Bridge	1/24/09	1	3.010	Asbestos	PCME	EMSL	1/26/09	< 0.00082	No	No	
ASBESTOS-ST11-1/24/09	030902454-0006	90 Trinity Place (roof level)	1/24/09	1	2.990	Asbestos	PCME	EMSL	1/26/09	< 0.00083	No	No	
ASBESTOS-ST12-1/24/09	030902454-0007	110 Greenwich Street (roof level)	1/24/09	1	3.050	Asbestos	PCME	EMSL	1/26/09	< 0.00081	No	No	
ASBESTOS-ST13-1/24/09	030902454-0008	Marriott Hotel, 38th Floor (roof level)	1/24/09	1	3.050	Asbestos	PCME	EMSL	1/26/09	< 0.00081	No	No	
ASBESTOS-ST14-1/24/09	030902454-0009	West Face - South end at corner (scaffolding level)	1/24/09	1	2.990	Asbestos	PCME	EMSL	1/26/09	< 0.00083	No	No	
ASBESTOS-ST15-1/24/09	030902454-0010	South Face - East end at corner (scaffolding level)	1/24/09	1	2.990	Asbestos	PCME	EMSL	1/26/09	< 0.00083	No	No	
ASBESTOS-ST16-1/24/09	030902454-0011	East Face - North end at corner (scaffolding level)	1/24/09	1	2.940	Asbestos	PCME	EMSL	1/26/09	< 0.00084	No	No	
ASBESTOS-ST17-1/24/09	030902454-0012	North Face - West end at corner (scaffolding level)	1/24/09	1	2.970	Asbestos	PCME	EMSL	1/26/09	< 0.00083	No	No	
ASBESTOS-ST1-1/25/09	030902450-0001	Southwest Area (sidewalk bridge level)	1/25/09	1	3.040	Asbestos	PCME	EMSL	1/26/09	< 0.00081	No	No	
ASBESTOS-ST2-1/25/09	030902450-0002	Southeast Area (sidewalk bridge level)	1/25/09	1	3.090	Asbestos	PCME	EMSL	1/26/09	< 0.00087	No	No	
ASBESTOS-ST4-1/25/09	030902450-0003	Northwest Area (street-level)	1/25/09	1	2.970	Asbestos	PCME	EMSL	1/26/09	< 0.00083	No	No	
ASBESTOS-ST5-1/25/09	030902450-0004	Firehouse #10 (roof level)	1/25/09	1	3.040	Asbestos	PCME	EMSL	1/26/09	< 0.00081	No	No	
ASBESTOS-ST10-1/25/09	030902450-0005	North Side Sidewalk Bridge	1/25/09	1	3.010	Asbestos	PCME	EMSL	1/26/09	< 0.00082	No	No	
ASBESTOS-ST11-1/25/09	030902450-0006	90 Trinity Place (roof level)	1/25/09	1	3.030	Asbestos	PCME	EMSL	1/26/09	< 0.00081	No	No	
ASBESTOS-ST12-1/25/09	030902450-0007	110 Greenwich Street (roof level)	1/25/09	1	3.040	Asbestos	PCME	EMSL	1/26/09	< 0.00081	No	No	
ASBESTOS-ST13-1/25/09	030902450-0008	Marriott Hotel, 38th Floor (roof level)	1/25/09	1	2.980	Asbestos	PCME	EMSL	1/26/09	< 0.00083	No	No	
ASBESTOS-ST14-1/25/09	030902450-0009	West Face - South end at corner (scaffolding level)	1/25/09	1	3.290	Asbestos	PCME	EMSL	1/26/09	< 0.00082	No	No	
ASBESTOS-ST15-1/25/09	030902450-0010	South Face - East end at corner (scaffolding level)	1/25/09	1	3.230	Asbestos	PCME	EMSL	1/26/09	< 0.00083	No	No	
ASBESTOS-ST16-1/25/09	030902450-0011	East Face - North end at corner (scaffolding level)	1/25/09	1	3.220	Asbestos	PCME	EMSL	1/26/09	< 0.00084	No	No	
ASBESTOS-ST17-1/25/09	030902450-0012	North Face - West end at corner (scaffolding level)	1/25/09	1	3.280	Asbestos	PCME	EMSL	1/26/09	< 0.00082	No	No	
ASBESTOS-ST1-1/26/09	030902578-0001	Southwest Area (sidewalk bridge level)	1/26/09	1	3.090	Asbestos	PCME	EMSL	1/27/09	< 0.00081	No	No	
ASBESTOS-ST2-1/26/09	030902578-0002	Southeast Area (sidewalk bridge level)	1/26/09	1	3.110	Asbestos	PCME	EMSL	1/27/09	< 0.00079	No	No	
ASBESTOS-ST4-1/26/09	030902578-0003	Northwest Area (street-level)	1/26/09	1	3.050	Asbestos	PCME	EMSL	1/27/09	< 0.00081	No	No	
ASBESTOS-ST5-1/26/09	030902578-0004	Firehouse #10 (roof level)	1/26/09	1	2.990	Asbestos	PCME	EMSL	1/27/09	< 0.00083	No	No	
ASBESTOS-ST10-1/26/09	030902578-0005	North Side Sidewalk Bridge	1/26/09	1	3.070	Asbestos	PCME	EMSL	1/27/09	< 0.00080	No	No	
ASBESTOS-ST11-1/26/09	030902578-0006	90 Trinity Place (roof level)	1/26/09	1	3.010	Asbestos	PCME	EMSL	1/27/09	< 0.00082	No	No	
ASBESTOS-ST12-1/26/09	030902578-0007	110 Greenwich Street (roof level)	1/26/09	1	2.890	Asbestos	PCME	EMSL	1/27/09	< 0.00085	No	No	Note 1
ASBESTOS-ST13-1/26/09	030902578-0008	Marriott Hotel, 38th Floor (roof level)	1/26/09	1	3.030	Asbestos	PCME	EMSL	1/27/09	< 0.00081	No	No	
ASBESTOS-ST14-1/26/09	030902578-0009	West Face - South end at corner (scaffolding level)	1/26/09	1	3.010	Asbestos	PCME	EMSL	1/27/09	< 0.00082	No	No	
ASBESTOS-ST15-1/26/09	030902578-0010	South Face - East end at corner (scaffolding level)	1/26/09	1	2.910	Asbestos	PCME	EMSL	1/27/09	< 0.00085	No	No	
ASBESTOS-ST16-1/26/09	030902578-0011	East Face - North end at corner (scaffolding level)	1/26/09	1	2.910	Asbestos	PCME	EMSL	1/27/09	< 0.00085	No	No	
ASBESTOS-ST17-1/26/09	030902578-0012	North Face - West end at corner (scaffolding level)	1/26/09	1	3.010	Asbestos	PCME	EMSL	1/27/09	< 0.00082	No	No	

Note:
1. Due to a final flow rate below 2 liters per minute (lpm) for the asbestos sample at Station 12 (110 Greenwich Street roof level) on January 26, 2009 the sample volume and subsequent sample result are estimated.