

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality	Site Specific	
										NA	Levels	Trigger Levels	
ASBESTOS-ST1-1/26/07	030702831-0001	Southwest Area (sidewalk bridge level)	1/26/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST2-1/26/07	030702831-0002	Southeast Area (sidewalk bridge level)	1/26/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST4-1/26/07	030702831-0003	Northwest Area (street-level)	1/26/07	1	3.160	Asbestos	PCME	EMSL	1/29/07	< 0.00078	No	No	
ASBESTOS-ST5-1/26/07	030702831-0004	Firehouse #10 (roof level)	1/26/07	1	3.040	Asbestos	PCME	EMSL	1/29/07	< 0.00081	No	No	
ASBESTOS-ST10-1/26/07	030702831-0005	North Side Sidewalk Bridge	1/26/07	1	3.040	Asbestos	PCME	EMSL	1/29/07	< 0.00081	No	No	
ASBESTOS-ST11-1/26/07	030702831-0006	90 Trinity Place (roof level)	1/26/07	1	3.040	Asbestos	PCME	EMSL	1/29/07	< 0.00081	No	No	
ASBESTOS-ST12-1/26/07	030702831-0007	110 Greenwich Street (roof level)	1/26/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST13-1/26/07	030702831-0008	Marriott Hotel, 38th Floor (roof level)	1/26/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST14-1/26/07	030702831-0009	West Face - South end at corner (scaffolding level)	1/26/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST15-1/26/07	030702831-0010	South Face - East end at corner (scaffolding level)	1/26/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST16-1/26/07	030702831-0011	East Face - North end at corner (scaffolding level)	1/26/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST17-1/26/07	030702831-0012	North Face - West end at corner (scaffolding level)	1/26/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST1-1/27/07	030702830-0001	Southwest Area (sidewalk bridge level)	1/27/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST2-1/27/07	030702830-0002	Southeast Area (sidewalk bridge level)	1/27/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST4-1/27/07	030702830-0003	Northwest Area (street-level)	1/27/07	1	2.970	Asbestos	PCME	EMSL	1/29/07	< 0.00083	No	No	
ASBESTOS-ST5-1/27/07	030702830-0004	Firehouse #10 (roof level)	1/27/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST10-1/27/07	030702830-0005	North Side Sidewalk Bridge	1/27/07	1	3.090	Asbestos	PCME	EMSL	1/29/07	< 0.00080	No	No	
ASBESTOS-ST11-1/27/07	030702830-0006	90 Trinity Place (roof level)	1/27/07	1	3.040	Asbestos	PCME	EMSL	1/29/07	< 0.00081	No	No	
ASBESTOS-ST12-1/27/07	030702830-0007	110 Greenwich Street (roof level)	1/27/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST13-1/27/07	030702830-0008	Marriott Hotel, 38th Floor (roof level)	1/27/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST14-1/27/07	030702830-0009	West Face - South end at corner (scaffolding level)	1/27/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST15-1/27/07	030702830-0010	South Face - East end at corner (scaffolding level)	1/27/07	1	3.040	Asbestos	PCME	EMSL	1/29/07	< 0.00081	No	No	
ASBESTOS-ST16-1/27/07	030702830-0011	East Face - North end at corner (scaffolding level)	1/27/07	1	3.040	Asbestos	PCME	EMSL	1/29/07	< 0.00081	No	No	
ASBESTOS-ST17-1/27/07	030702830-0012	North Face - West end at corner (scaffolding level)	1/27/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST1-1/28/07	030702829-0001	Southwest Area (sidewalk bridge level)	1/28/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST2-1/28/07	030702829-0002	Southeast Area (sidewalk bridge level)	1/28/07	1	2.990	Asbestos	PCME	EMSL	1/29/07	< 0.00083	No	No	
ASBESTOS-ST4-1/28/07	030702829-0003	Northwest Area (street-level)	1/28/07	1	3.030	Asbestos	PCME	EMSL	1/29/07	< 0.00081	No	No	
ASBESTOS-ST5-1/28/07	030702829-0004	Firehouse #10 (roof level)	1/28/07	1	2.850	Asbestos	PCME	EMSL	1/29/07	< 0.00087	No	No	
ASBESTOS-ST10-1/28/07	030702829-0005	North Side Sidewalk Bridge	1/28/07	1	2.940	Asbestos	PCME	EMSL	1/29/07	< 0.00084	No	No	
ASBESTOS-ST11-1/28/07	030702829-0006	90 Trinity Place (roof level)	1/28/07	1	2.880	Asbestos	PCME	EMSL	1/29/07	< 0.00079	No	No	
ASBESTOS-ST12-1/28/07	030702829-0007	110 Greenwich Street (roof level)	1/28/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST13-1/28/07	030702829-0008	Marriott Hotel, 38th Floor (roof level)	1/28/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST14-1/28/07	030702829-0009	West Face - South end at corner (scaffolding level)	1/28/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST15-1/28/07	030702829-0010	South Face - East end at corner (scaffolding level)	1/28/07	1	3.030	Asbestos	PCME	EMSL	1/29/07	< 0.00081	No	No	
ASBESTOS-ST16-1/28/07	030702829-0011	East Face - North end at corner (scaffolding level)	1/28/07	1	3.020	Asbestos	PCME	EMSL	1/29/07	< 0.00082	No	No	
ASBESTOS-ST17-1/28/07	030702829-0012	North Face - West end at corner (scaffolding level)	1/28/07	1	3.040	Asbestos	PCME	EMSL	1/29/07	< 0.00081	No	No	
ASBESTOS-ST1-1/29/07	030702947-0001	Southwest Area (sidewalk bridge level)	1/29/07	1	2.850	Asbestos	PCME	EMSL	1/30/07	< 0.00080	No	No	
ASBESTOS-ST2-1/29/07	030702947-0002	Southeast Area (sidewalk bridge level)	1/29/07	1	3.040	Asbestos	PCME	EMSL	1/30/07	< 0.00081	No	No	
ASBESTOS-ST4-1/29/07	030702947-0003	Northwest Area (street-level)	1/29/07	1	2.990	Asbestos	PCME	EMSL	1/30/07	< 0.00083	No	No	
ASBESTOS-ST5-1/29/07	030702947-0004	Firehouse #10 (roof level)	1/29/07	1	3.040	Asbestos	PCME	EMSL	1/30/07	< 0.00081	No	No	
ASBESTOS-ST10-1/29/07	030702947-0005	North Side Sidewalk Bridge	1/29/07	1	2.930	Asbestos	PCME	EMSL	1/30/07	< 0.00084	No	No	
ASBESTOS-ST11-1/29/07	030702947-0006	90 Trinity Place (roof level)	1/29/07	1	3.040	Asbestos	PCME	EMSL	1/30/07	< 0.00081	No	No	
ASBESTOS-ST12-1/29/07	030702947-0007	110 Greenwich Street (roof level)	1/29/07	1	3.020	Asbestos	PCME	EMSL	1/30/07	< 0.00082	No	No	
ASBESTOS-ST13-1/29/07	030702947-0008	Marriott Hotel, 38th Floor (roof level)	1/29/07	1	3.020	Asbestos	PCME	EMSL	1/30/07	< 0.00082	No	No	
ASBESTOS-ST14-1/29/07	030702947-0009	West Face - South end at corner (scaffolding level)	1/29/07	1	2.900	Asbestos	PCME	EMSL	1/30/07	< 0.00085	No	No	
ASBESTOS-ST15-1/29/07	030702947-0010	South Face - East end at corner (scaffolding level)	1/29/07	1	3.020	Asbestos	PCME	EMSL	1/30/07	< 0.00082	No	No	
ASBESTOS-ST16-1/29/07	030702947-0011	East Face - North end at corner (scaffolding level)	1/29/07	1	3.030	Asbestos	PCME	EMSL	1/30/07	< 0.00081	No	No	
ASBESTOS-ST17-1/29/07	030702947-0012	North Face - West end at corner (scaffolding level)	1/29/07	1	3.020	Asbestos	PCME	EMSL	1/30/07	< 0.00081	No	No	