

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments	
										0.0009	Air Quality Levels	Site Specific Trigger Levels		
										NA				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-1/30/07	030703074-0001	Southwest Area (sidewalk bridge level)	1/30/07	1	3.020	Asbestos	PCME	EMSL	1/31/07	< 0.00082	No	No		
ASBESTOS-ST2-1/30/07	030703074-0002	Southeast Area (sidewalk bridge level)	1/30/07	1	3.040	Asbestos	PCME	EMSL	1/31/07	< 0.00081	No	No		
ASBESTOS-ST4-1/30/07	030703074-0003	Northwest Area (street-level)	1/30/07	1	3.040	Asbestos	PCME	EMSL	1/31/07	< 0.00081	No	No		
ASBESTOS-ST5-1/30/07	030703074-0004	Firehouse #10 (roof level)	1/30/07	1	3.040	Asbestos	PCME	EMSL	1/31/07	< 0.00081	No	No		
ASBESTOS-ST10-1/30/07	030703074-0005	North Side Sidewalk Bridge	1/30/07	1	3.030	Asbestos	PCME	EMSL	1/31/07	< 0.00081	No	No		
ASBESTOS-ST11-1/30/07	030703074-0006	90 Trinity Place (roof level)	1/30/07	1	3.040	Asbestos	PCME	EMSL	1/31/07	< 0.00081	No	No		
ASBESTOS-ST12-1/30/07	030703074-0007	110 Greenwich Street (roof level)	1/30/07	1	3.020	Asbestos	PCME	EMSL	1/31/07	< 0.00082	No	No		
ASBESTOS-ST13-1/30/07	030703074-0008	Marriott Hotel, 38th Floor (roof level)	1/30/07	1	3.030	Asbestos	PCME	EMSL	1/31/07	< 0.00081	No	No		
ASBESTOS-ST14-1/30/07	030703074-0009	West Face - South end at corner (scaffolding level)	1/30/07	1	3.010	Asbestos	PCME	EMSL	1/31/07	< 0.00082	No	No		
ASBESTOS-ST15-1/30/07	030703074-0010	South Face - East end at corner (scaffolding level)	1/30/07	1	3.020	Asbestos	PCME	EMSL	1/31/07	< 0.00082	No	No		
ASBESTOS-ST16-1/30/07	030703074-0011	East Face - North end at corner (scaffolding level)	1/30/07	1	3.020	Asbestos	PCME	EMSL	1/31/07	< 0.00082	No	No		
ASBESTOS-ST17-1/30/07	030703074-0012	North Face - West end at corner (scaffolding level)	1/30/07	1	3.020	Asbestos	PCME	EMSL	1/31/07	< 0.00082	No	No		
ASBESTOS-ST1-1/31/07	030703221-0001	Southwest Area (sidewalk bridge level)	1/31/07	1	3.030	Asbestos	PCME	EMSL	2/1/07	< 0.00081	No	No		
ASBESTOS-ST2-1/31/07	030703221-0002	Southeast Area (sidewalk bridge level)	1/31/07	1	3.020	Asbestos	PCME	EMSL	2/1/07	< 0.00082	No	No		
ASBESTOS-ST4-1/31/07	030703221-0003	Northwest Area (street-level)	1/31/07	1	3.040	Asbestos	PCME	EMSL	2/1/07	< 0.00081	No	No		
ASBESTOS-ST5-1/31/07	030703221-0004	Firehouse #10 (roof level)	1/31/07	1	3.030	Asbestos	PCME	EMSL	2/1/07	< 0.00081	No	No		
ASBESTOS-ST10-1/31/07	030703221-0005	North Side Sidewalk Bridge	1/31/07	1	3.090	Asbestos	PCME	EMSL	2/1/07	< 0.00080	No	No		
ASBESTOS-ST100-1/31/07	030703221-0013	Station 10 Field Duplicate	1/31/07	1	3.070	Asbestos	PCME	EMSL	2/1/07	< 0.00083	No	No		
ASBESTOS-ST11-1/31/07	030703221-0006	90 Trinity Place (roof level)	1/31/07	1	3.040	Asbestos	PCME	EMSL	2/1/07	< 0.00081	No	No		
ASBESTOS-ST12-1/31/07	030703221-0007	110 Greenwich Street (roof level)	1/31/07	1	2.970	Asbestos	PCME	EMSL	2/1/07	< 0.00083	No	No		
ASBESTOS-ST13-1/31/07	030703221-0008	Marriott Hotel, 38th Floor (roof level)	1/31/07	1	2.920	Asbestos	PCME	EMSL	2/1/07	< 0.00085	No	No		
ASBESTOS-ST14-1/31/07	030703221-0009	West Face - South end at corner (scaffolding level)	1/31/07	1	3.040	Asbestos	PCME	EMSL	2/1/07	< 0.00081	No	No		
ASBESTOS-ST15-1/31/07	030703221-0010	South Face - East end at corner (scaffolding level)	1/31/07	1	3.010	Asbestos	PCME	EMSL	2/1/07	< 0.00082	No	No		
ASBESTOS-ST16-1/31/07	030703221-0011	East Face - North end at corner (scaffolding level)	1/31/07	1	3.020	Asbestos	PCME	EMSL	2/1/07	< 0.00082	No	No		
ASBESTOS-ST17-1/31/07	030703221-0012	North Face - West end at corner (scaffolding level)	1/31/07	1	3.020	Asbestos	PCME	EMSL	2/1/07	< 0.00082	No	No		