

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-2/2/09	030903164-0001	Southwest Area (sidewalk bridge level)	2/2/09	1	3.060	Asbestos	PCME	EMSL	2/3/09	< 0.00081	No	No	
ASBESTOS-ST2-2/2/09	030903164-0002	Southeast Area (sidewalk bridge level)	2/2/09	1	3.110	Asbestos	PCME	EMSL	2/3/09	< 0.00079	No	No	
ASBESTOS-ST4-2/2/09	030903164-0003	Northwest Area (street-level)	2/2/09	1	3.000	Asbestos	PCME	EMSL	2/3/09	< 0.00082	No	No	
ASBESTOS-ST5-2/2/09	030903164-0004	Firehouse #10 (roof level)	2/2/09	1	3.090	Asbestos	PCME	EMSL	2/3/09	< 0.00080	No	No	
ASBESTOS-ST10-2/2/09	030903164-0005	North Side Sidewalk Bridge	2/2/09	1	3.100	Asbestos	PCME	EMSL	2/3/09	< 0.00080	No	No	
ASBESTOS-ST11-2/2/09	030903164-0006	90 Trinity Place (roof level)	2/2/09	1	3.060	Asbestos	PCME	EMSL	2/3/09	< 0.00081	No	No	
ASBESTOS-ST12-2/2/09	030903164-0007	110 Greenwich Street (roof level)	2/2/09	1	3.050	Asbestos	PCME	EMSL	2/3/09	< 0.00081	No	No	
ASBESTOS-ST13-2/2/09	030903164-0008	Marriott Hotel, 38th Floor (roof level)	2/2/09	1	3.070	Asbestos	PCME	EMSL	2/3/09	< 0.00080	No	No	
ASBESTOS-ST14-2/2/09	030903164-0009	West Face - South end at corner (scaffolding level)	2/2/09	1	3.080	Asbestos	PCME	EMSL	2/3/09	< 0.00080	No	No	
ASBESTOS-ST15-2/2/09	030903164-0010	South Face - East end at corner (scaffolding level)	2/2/09	1	3.020	Asbestos	PCME	EMSL	2/3/09	< 0.00082	No	No	
ASBESTOS-ST16-2/2/09	030903164-0011	East Face - North end at corner (scaffolding level)	2/2/09	1	3.050	Asbestos	PCME	EMSL	2/3/09	< 0.00081	No	No	
ASBESTOS-ST17-2/2/09	030903164-0012	North Face - West end at corner (scaffolding level)	2/2/09	1	3.020	Asbestos	PCME	EMSL	2/3/09	< 0.00082	No	No	
ASBESTOS-ST1-2/3/09	030903263-0001	Southwest Area (sidewalk bridge level)	2/3/09	1	3.090	Asbestos	PCME	EMSL	2/4/09	< 0.00080	No	No	
ASBESTOS-ST2-2/3/09	030903263-0002	Southeast Area (sidewalk bridge level)	2/3/09	1	3.020	Asbestos	PCME	EMSL	2/4/09	< 0.00082	No	No	
ASBESTOS-ST4-2/3/09	030903263-0003	Northwest Area (street-level)	2/3/09	1	2.950	Asbestos	PCME	EMSL	2/4/09	< 0.00084	No	No	
ASBESTOS-ST5-2/3/09	030903263-0004	Firehouse #10 (roof level)	2/3/09	1	2.990	Asbestos	PCME	EMSL	2/4/09	< 0.00083	No	No	
ASBESTOS-ST10-2/3/09	030903263-0005	North Side Sidewalk Bridge	2/3/09	1	2.990	Asbestos	PCME	EMSL	2/4/09	< 0.00083	No	No	
ASBESTOS-ST11-2/3/09	030903263-0006	90 Trinity Place (roof level)	2/3/09	1	2.970	Asbestos	PCME	EMSL	2/4/09	< 0.00083	No	No	
ASBESTOS-ST12-2/3/09	030903263-0007	110 Greenwich Street (roof level)	2/3/09	1	2.960	Asbestos	PCME	EMSL	2/4/09	< 0.00083	No	No	
ASBESTOS-ST13-2/3/09	030903263-0008	Marriott Hotel, 38th Floor (roof level)	2/3/09	1	3.060	Asbestos	PCME	EMSL	2/4/09	< 0.00081	No	No	
ASBESTOS-ST14-2/3/09	030903263-0009	West Face - South end at corner (scaffolding level)	2/3/09	1	3.030	Asbestos	PCME	EMSL	2/4/09	< 0.00081	No	No	
ASBESTOS-ST15-2/3/09	030903263-0010	South Face - East end at corner (scaffolding level)	2/3/09	1	3.020	Asbestos	PCME	EMSL	2/4/09	< 0.00082	No	No	
ASBESTOS-ST16-2/3/09	030903263-0011	East Face - North end at corner (scaffolding level)	2/3/09	1	3.030	Asbestos	PCME	EMSL	2/4/09	< 0.00081	No	No	

Note:

1. The asbestos sample from Station 17 (North Face - West end at corner [scaffolding level]) on February 3, 2009 was not available for analysis on account of power failure.