

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-2/9/08	030803591-0001	Southwest Area (sidewalk bridge level)	2/9/08	1	3.000	Asbestos	PCME	EMSL	2/11/08	< 0.00082	No	No	
ASBESTOS-ST2-2/9/08	030803591-0002	Southeast Area (sidewalk bridge level)	2/9/08	1	3.110	Asbestos	PCME	EMSL	2/11/08	< 0.00087	No	No	
ASBESTOS-ST4-2/9/08	030803591-0003	Northwest Area (street-level)	2/9/08	1	2.980	Asbestos	PCME	EMSL	2/11/08	< 0.00083	No	No	
ASBESTOS-ST5-2/9/08	030803591-0004	Firehouse #10 (roof level)	2/9/08	1	3.070	Asbestos	PCME	EMSL	2/11/08	< 0.00080	No	No	
ASBESTOS-ST10-2/9/08	030803591-0005	North Side Sidewalk Bridge	2/9/08	1	3.090	Asbestos	PCME	EMSL	2/11/08	< 0.00080	No	No	
ASBESTOS-ST11-2/9/08	030803591-0006	90 Trinity Place (roof level)	2/9/08	1	3.010	Asbestos	PCME	EMSL	2/11/08	< 0.00082	No	No	
ASBESTOS-ST12-2/9/08	030803591-0007	110 Greenwich Street (roof level)	2/9/08	1	3.030	Asbestos	PCME	EMSL	2/11/08	< 0.00081	No	No	
ASBESTOS-ST13-2/9/08	030803591-0008	Marriott Hotel, 38th Floor (roof level)	2/9/08	1	3.010	Asbestos	PCME	EMSL	2/11/08	< 0.00082	No	No	
ASBESTOS-ST14-2/9/08	030803591-0009	West Face - South end at corner (scaffolding level)	2/9/08	1	3.010	Asbestos	PCME	EMSL	2/11/08	< 0.00082	No	No	
ASBESTOS-ST15-2/9/08	030803591-0010	South Face - East end at corner (scaffolding level)	2/9/08	1	3.070	Asbestos	PCME	EMSL	2/11/08	< 0.00080	No	No	
ASBESTOS-ST16-2/9/08	030803591-0011	East Face - North end at corner (scaffolding level)	2/9/08	1	3.040	Asbestos	PCME	EMSL	2/11/08	< 0.00081	No	No	
ASBESTOS-ST17-2/9/08	030803591-0012	North Face - West end at corner (scaffolding level)	2/9/08	1	3.050	Asbestos	PCME	EMSL	2/11/08	< 0.00081	No	No	
ASBESTOS-ST1-2/10/08	030803585-0001	Southwest Area (sidewalk bridge level)	2/10/08	1	3.050	Asbestos	PCME	EMSL	2/11/08	< 0.00081	No	No	
ASBESTOS-ST2-2/10/08	030803585-0002	Southeast Area (sidewalk bridge level)	2/10/08	1	3.010	Asbestos	PCME	EMSL	2/11/08	< 0.00082	No	No	
ASBESTOS-ST4-2/10/08	030803585-0003	Northwest Area (street-level)	2/10/08	1	3.010	Asbestos	PCME	EMSL	2/11/08	< 0.00082	No	No	
ASBESTOS-ST5-2/10/08	030803585-0004	Firehouse #10 (roof level)	2/10/08	1	3.120	Asbestos	PCME	EMSL	2/11/08	< 0.00086	No	No	
ASBESTOS-ST10-2/10/08	030803585-0005	North Side Sidewalk Bridge	2/10/08	1	3.000	Asbestos	PCME	EMSL	2/11/08	< 0.00082	No	No	
ASBESTOS-ST11-2/10/08	030803585-0006	90 Trinity Place (roof level)	2/10/08	1	3.040	Asbestos	PCME	EMSL	2/11/08	< 0.00081	No	No	
ASBESTOS-ST12-2/10/08	030803585-0007	110 Greenwich Street (roof level)	2/10/08	1	3.000	Asbestos	PCME	EMSL	2/11/08	< 0.00082	No	No	
ASBESTOS-ST13-2/10/08	030803585-0008	Marriott Hotel, 38th Floor (roof level)	2/10/08	1	3.010	Asbestos	PCME	EMSL	2/11/08	< 0.00082	No	No	
ASBESTOS-ST14-2/10/08	030803585-0009	West Face - South end at corner (scaffolding level)	2/10/08	1	3.010	Asbestos	PCME	EMSL	2/11/08	< 0.00082	No	No	
ASBESTOS-ST15-2/10/08	030803585-0010	South Face - East end at corner (scaffolding level)	2/10/08	1	2.970	Asbestos	PCME	EMSL	2/11/08	< 0.00083	No	No	
ASBESTOS-ST16-2/10/08	030803585-0011	East Face - North end at corner (scaffolding level)	2/10/08	1	3.090	Asbestos	PCME	EMSL	2/11/08	< 0.00080	No	No	
ASBESTOS-ST17-2/10/08	030803585-0012	North Face - West end at corner (scaffolding level)	2/10/08	1	3.180	Asbestos	PCME	EMSL	2/11/08	< 0.00078	No	No	
ASBESTOS-ST1-2/11/08	030803703-0001	Southwest Area (sidewalk bridge level)	2/11/08	1	2.970	Asbestos	PCME	EMSL	2/12/08	< 0.00083	No	No	
ASBESTOS-ST2-2/11/08	030803703-0002	Southeast Area (sidewalk bridge level)	2/11/08	1	2.980	Asbestos	PCME	EMSL	2/12/08	< 0.00083	No	No	
ASBESTOS-ST4-2/11/08	030803703-0003	Northwest Area (street-level)	2/11/08	1	2.900	Asbestos	PCME	EMSL	2/12/08	< 0.00085	No	No	
ASBESTOS-ST5-2/11/08	030803703-0004	Firehouse #10 (roof level)	2/11/08	1	3.020	Asbestos	PCME	EMSL	2/12/08	< 0.00082	No	No	
ASBESTOS-ST10-2/11/08	030803703-0005	North Side Sidewalk Bridge	2/11/08	1	2.990	Asbestos	PCME	EMSL	2/12/08	< 0.00083	No	No	
ASBESTOS-ST11-2/11/08	030803703-0006	90 Trinity Place (roof level)	2/11/08	1	2.990	Asbestos	PCME	EMSL	2/12/08	< 0.00083	No	No	
ASBESTOS-ST12-2/11/08	030803703-0007	110 Greenwich Street (roof level)	2/11/08	1	3.010	Asbestos	PCME	EMSL	2/12/08	< 0.00082	No	No	
ASBESTOS-ST13-2/11/08	030803703-0008	Marriott Hotel, 38th Floor (roof level)	2/11/08	1	3.060	Asbestos	PCME	EMSL	2/12/08	< 0.00081	No	No	
ASBESTOS-ST14-2/11/08	030803703-0009	West Face - South end at corner (scaffolding level)	2/11/08	1	3.020	Asbestos	PCME	EMSL	2/12/08	< 0.00082	No	No	
ASBESTOS-ST15-2-11/08	030803703-0010	South Face - East end at corner (scaffolding level)	2/11/08	1	3.010	Asbestos	PCME	EMSL	2/12/08	< 0.00082	No	No	
ASBESTOS-ST16-2/11/08	030803703-0011	East Face - North end at corner (scaffolding level)	2/11/08	1	2.990	Asbestos	PCME	EMSL	2/12/08	< 0.00083	No	No	
ASBESTOS-ST17-2/11/08	030803703-0012	North Face - West end at corner (scaffolding level)	2/11/08	1	2.970	Asbestos	PCME	EMSL	2/12/08	< 0.00083	No	No	