

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										0.0009	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels										NA	Levels	Trigger Levels	
ASBESTOS-ST1-2/13/08	030803983-0001	Southwest Area (sidewalk bridge level)	2/13/08	1	2.930	Asbestos	PCME	EMSL	2/15/08	< 0.00084	No	No	
ASBESTOS-ST2-2/13/08	030803983-0002	Southeast Area (sidewalk bridge level)	2/13/08	1	2.970	Asbestos	PCME	EMSL	2/15/08	< 0.00083	No	No	
ASBESTOS-ST4-2/13/08	030803983-0003	Northwest Area (street-level)	2/13/08	1	2.980	Asbestos	PCME	EMSL	2/15/08	< 0.00083	No	No	
ASBESTOS-ST5-2/13/08	030803983-0004	Firehouse #10 (roof level)	2/13/08	1	1.720	Asbestos	PCME	EMSL	2/15/08	< 0.00082	No	No	Note 1
ASBESTOS-ST10-2/13/08	030803983-0005	North Side Sidewalk Bridge	2/13/08	1	3.090	Asbestos	PCME	EMSL	2/15/08	< 0.00080	No	No	
ASBESTOS-ST11-2/13/08	030803983-0006	90 Trinity Place (roof level)	2/13/08	1	3.100	Asbestos	PCME	EMSL	2/15/08	< 0.00080	No	No	
ASBESTOS-ST12-2/13/08	030803983-0007	110 Greenwich Street (roof level)	2/13/08	1	3.140	Asbestos	PCME	EMSL	2/15/08	< 0.00079	No	No	
ASBESTOS-ST13-2/13/08	030803983-0008	Marriott Hotel, 38th Floor (roof level)	2/13/08	1	3.150	Asbestos	PCME	EMSL	2/15/08	< 0.00078	No	No	
ASBESTOS-ST14-2/13/08	030803982-0001	West Face - South end at corner (scaffolding level)	2/13/08	1	1.020	Asbestos	PCME	EMSL	2/15/08	< 0.00088	No	No	Note 2
ASBESTOS-ST15-2/13/08	030803982-0002	South Face - East end at corner (scaffolding level)	2/13/08	1	1.060	Asbestos	PCME	EMSL	2/15/08	< 0.00087	No	No	Note 2
ASBESTOS-ST16-2/13/08	030803982-0003	East Face - North end at corner (scaffolding level)	2/13/08	1	1.100	Asbestos	PCME	EMSL	2/15/08	< 0.00087	No	No	Note 2
ASBESTOS-ST17-2/13/08	030803982-0004	North Face - West end at corner (scaffolding level)	2/13/08	1	1.040	Asbestos	PCME	EMSL	2/15/08	< 0.00089	No	No	Note 2
ASBESTOS-ST1-2/14/08	030803979-0001	Southwest Area (sidewalk bridge level)	2/14/08	1	3.150	Asbestos	PCME	EMSL	2/15/08	< 0.00085	No	No	
ASBESTOS-ST2-2/14/08	030803979-0002	Southeast Area (sidewalk bridge level)	2/14/08	1	3.010	Asbestos	PCME	EMSL	2/15/08	< 0.00089	No	No	
ASBESTOS-ST4-2/14/08	030803979-0003	Northwest Area (street-level)	2/14/08	1	3.070	Asbestos	PCME	EMSL	2/15/08	< 0.00088	No	No	
ASBESTOS-ST5-2/14/08	030803979-0004	Firehouse #10 (roof level)	2/14/08	1	3.470	Asbestos	PCME	EMSL	2/15/08	< 0.00085	No	No	
ASBESTOS-ST10-2/14/08	030803979-0005	North Side Sidewalk Bridge	2/14/08	1	3.090	Asbestos	PCME	EMSL	2/15/08	< 0.00087	No	No	
ASBESTOS-ST11-2/14/08	030803979-0006	90 Trinity Place (roof level)	2/14/08	1	3.040	Asbestos	PCME	EMSL	2/15/08	< 0.00081	No	No	
ASBESTOS-ST12-2/14/08	030803979-0007	110 Greenwich Street (roof level)	2/14/08	1	3.000	Asbestos	PCME	EMSL	2/15/08	< 0.00082	No	No	
ASBESTOS-ST13-2/14/08	030803979-0008	Marriott Hotel, 38th Floor (roof level)	2/14/08	1	3.070	Asbestos	PCME	EMSL	2/15/08	< 0.00088	No	No	
ASBESTOS-ST14-2/14/08	030803979-0009	West Face - South end at corner (scaffolding level)	2/14/08	1	1.620	Asbestos	PCME	EMSL	2/15/08	< 0.00083	No	No	Note 2
ASBESTOS-ST15-2/14/08	030803979-0010	South Face - East end at corner (scaffolding level)	2/14/08	1	1.650	Asbestos	PCME	EMSL	2/15/08	< 0.00082	No	No	Note 2
ASBESTOS-ST16-2/14/08	030803979-0011	East Face - North end at corner (scaffolding level)	2/14/08	1	1.790	Asbestos	PCME	EMSL	2/15/08	< 0.00083	No	No	Note 2
ASBESTOS-ST17-2/14/08	030803979-0012	North Face - West end at corner (scaffolding level)	2/14/08	1	1.530	Asbestos	PCME	EMSL	2/15/08	< 0.00088	No	No	Note 2
ASBESTOS-ST1-2/15/08	030804051-0001	Southwest Area (sidewalk bridge level)	2/15/08	1	2.990	Asbestos	PCME	EMSL	2/16/08	< 0.00083	No	No	
ASBESTOS-ST2-2/15/08	030804051-0002	Southeast Area (sidewalk bridge level)	2/15/08	1	3.200	Asbestos	PCME	EMSL	2/16/08	< 0.00077	No	No	
ASBESTOS-ST4-2/15/08	030804051-0003	Northwest Area (street-level)	2/15/08	1	3.040	Asbestos	PCME	EMSL	2/16/08	< 0.00081	No	No	
ASBESTOS-ST5-2/15/08	030804051-0004	Firehouse #10 (roof level)	2/15/08	1	3.070	Asbestos	PCME	EMSL	2/16/08	< 0.00080	No	No	
ASBESTOS-ST10-2/15/08	030804051-0005	North Side Sidewalk Bridge	2/15/08	1	3.090	Asbestos	PCME	EMSL	2/16/08	< 0.00080	No	No	
ASBESTOS-ST100-2/15/08	030804051-0012	Station 10 Field Duplicate	2/15/08	1	3.070	Asbestos	PCME	EMSL	2/16/08	< 0.00080	No	No	
ASBESTOS-ST11-2/15/08	030804216-0001	90 Trinity Place (roof level)	2/15/08	1	3.170	Asbestos	PCME	EMSL	2/18/08	< 0.00085	No	No	
ASBESTOS-ST12-2/15/08	030804051-0006	110 Greenwich Street (roof level)	2/15/08	1	3.020	Asbestos	PCME	EMSL	2/16/08	< 0.00082	No	No	
ASBESTOS-ST13-2/15/08	030804051-0007	Marriott Hotel, 38th Floor (roof level)	2/15/08	1	3.000	Asbestos	PCME	EMSL	2/16/08	< 0.00082	No	No	
ASBESTOS-ST14-2/15/08	030804051-0008	West Face - South end at corner (scaffolding level)	2/15/08	1	3.010	Asbestos	PCME	EMSL	2/16/08	< 0.00082	No	No	
ASBESTOS-ST15-2/15/08	030804051-0009	South Face - East end at corner (scaffolding level)	2/15/08	1	2.990	Asbestos	PCME	EMSL	2/16/08	< 0.00083	No	No	
ASBESTOS-ST16-2/15/08	030804051-0010	East Face - North end at corner (scaffolding level)	2/15/08	1	2.960	Asbestos	PCME	EMSL	2/16/08	< 0.00083	No	No	
ASBESTOS-ST17-2/15/08	030804051-0011	North Face - West end at corner (scaffolding level)	2/15/08	1	3.040	Asbestos	PCME	EMSL	2/16/08	< 0.00081	No	No	
ASBESTOS-ST1-2/16/08	030804212-0001	Southwest Area (sidewalk bridge level)	2/16/08	1	3.060	Asbestos	PCME	EMSL	2/18/08	< 0.00081	No	No	
ASBESTOS-ST2-2/16/08	030804212-0002	Southeast Area (sidewalk bridge level)	2/16/08	1	3.090	Asbestos	PCME	EMSL	2/18/08	< 0.00080	No	No	
ASBESTOS-ST4-2/16/08	030804212-0003	Northwest Area (street-level)	2/16/08	1	3.090	Asbestos	PCME	EMSL	2/18/08	< 0.00080	No	No	
ASBESTOS-ST5-2/16/08	030804212-0004	Firehouse #10 (roof level)	2/16/08	1	2.990	Asbestos	PCME	EMSL	2/18/08	< 0.00083	No	No	
ASBESTOS-ST10-2/16/08	030804212-0005	North Side Sidewalk Bridge	2/16/08	1	3.060	Asbestos	PCME	EMSL	2/18/08	< 0.00081	No	No	
ASBESTOS-ST11-2/16/08	030804212-0006	90 Trinity Place (roof level)	2/16/08	1	3.320	Asbestos	PCME	EMSL	2/18/08	< 0.00081	No	No	
ASBESTOS-ST12-2/16/08	030804212-0007	110 Greenwich Street (roof level)	2/16/08	1	3.040	Asbestos	PCME	EMSL	2/18/08	< 0.00081	No	No	
ASBESTOS-ST13-2/16/08	030804212-0008	Marriott Hotel, 38th Floor (roof level)	2/16/08	1	3.040	Asbestos	PCME	EMSL	2/18/08	< 0.00081	No	No	
ASBESTOS-ST14-2/16/08	030804212-0009	West Face - South end at corner (scaffolding level)	2/16/08	1	3.020	Asbestos	PCME	EMSL	2/18/08	< 0.00082	No	No	
ASBESTOS-ST15-2/16/08	030804212-0010	South Face - East end at corner (scaffolding level)	2/16/08	1	3.050	Asbestos	PCME	EMSL	2/18/08	< 0.00081	No	No	
ASBESTOS-ST16-2/16/08	030804212-0011	East Face - North end at corner (scaffolding level)	2/16/08	1	3.140	Asbestos	PCME	EMSL	2/18/08	< 0.00086	No	No	
ASBESTOS-ST17-2/16/08	030804212-0012	North Face - West end at corner (scaffolding level)	2/16/08	1	3.000	Asbestos	PCME	EMSL	2/18/08	< 0.00082	No	No	
ASBESTOS-ST1-2/17/08	030804211-0001	Southwest Area (sidewalk bridge level)	2/17/08	1	3.530	Asbestos	PCME	EMSL	2/18/08	< 0.00084	No	No	Note 3
ASBESTOS-ST2-2/17/08	030804211-0002	Southeast Area (sidewalk bridge level)	2/17/08	1	3.360	Asbestos	PCME	EMSL	2/18/08	< 0.00080	No	No	
ASBESTOS-ST4-2/17/08	030804211-0003	Northwest Area (street-level)	2/17/08	1	3.530	Asbestos	PCME	EMSL	2/18/08	< 0.00084	No	No	Note 3
ASBESTOS-ST5-2/17/08	030804211-0004	Firehouse #10 (roof level)	2/17/08	1	3.080	Asbestos	PCME	EMSL	2/18/08	< 0.00080	No	No	
ASBESTOS-ST10-2/17/08	030804211-0005	North Side Sidewalk Bridge	2/17/08	1	3.170	Asbestos	PCME	EMSL	2/18/08	< 0.00078	No	No	
ASBESTOS-ST11-2/17/08	030804211-0006	90 Trinity Place (roof level)	2/17/08	1	2.750	Asbestos	PCME	EMSL	2/18/08	< 0.00083	No	No	
ASBESTOS-ST12-2/17/08	030804211-0007	110 Greenwich Street (roof level)	2/17/08	1	3.110	Asbestos	PCME	EMSL	2/18/08	< 0.00079	No	No	
ASBESTOS-ST13-2/17/08	030804211-0008	Marriott Hotel, 38th Floor (roof level)	2/17/08	1	2.940	Asbestos	PCME	EMSL	2/18/08	< 0.00084	No	No	
ASBESTOS-ST14-2/17/08	030804211-0009	West Face - South end at corner (scaffolding level)	2/17/08	1	3.330	Asbestos	PCME	EMSL	2/18/08	< 0.00081	No	No	
ASBESTOS-ST15-2/17/08	030804211-0010	South Face - East end at corner (scaffolding level)	2/17/08	1	3.070	Asbestos	PCME	EMSL	2/18/08	< 0.00080	No	No	
ASBESTOS-ST16-2/17/08	030804211-0011	East Face - North end at corner (scaffolding level)	2/17/08	1	3.000	Asbestos	PCME	EMSL	2/18/08	< 0.00082	No	No	
ASBESTOS-ST17-2/17/08	030804211-0012	North Face - West end at corner (scaffolding level)	2/17/08	1	3.330	Asbestos	PCME	EMSL	2/18/08	< 0.00081	No	No	
ASBESTOS-ST1-2/18/08	030804281-0001	Southwest Area (sidewalk bridge level)	2/18/08	1	2.930	Asbestos	PCME	EMSL	2/19/08	< 0.00084	No	No	
ASBESTOS-ST2-2/18/08	030804281-0002	Southeast Area (sidewalk bridge level)	2/18/08	1	3.020	Asbestos	PCME	EMSL	2/19/08	< 0.00082	No	No	
ASBESTOS-ST4-2/18/08	030804281-0003	Northwest Area (street-level)	2/18/08	1	2.950	Asbestos	PCME	EMSL	2/19/08	< 0.00084	No	No	
ASBESTOS-ST5-2/18/08	030804281-0004	Firehouse #10 (roof level)	2/18/08	1	3.070	Asbestos	PCME	EMSL	2/19/08	< 0.00080	No	No	
ASBESTOS-ST10-2/18/08	030804281-0005	North Side Sidewalk Bridge	2/18/08	1	3.040	Asbestos	PCME	EMSL	2/19/08	< 0.00081	No	No	
ASBESTOS-ST11-2/18/08	030804281-0006	90 Trinity Place (roof level)	2/18/08	1	3.010	Asbestos	PCME	EMSL	2/19/08	< 0.00082	No	No	
ASBESTOS-ST12-2/18/08	030804281-0007	110 Greenwich Street (roof level)	2/18/08	1	3.110	Asbestos	PCME	EMSL	2/19/08	< 0.00087	No	No	
ASBESTOS-ST13-2/18/08	030804281-0008	Marriott Hotel, 38th Floor (roof level)	2/18/08	1	2.940	Asbestos	PCME	EMSL	2/19/08	< 0.00084	No	No	
ASBESTOS-ST14-2/18/08	030804281-0009	West Face - South end at corner (scaffolding level)	2/18/08	1	3.240	Asbestos	PCME	EMSL	2/19/08	< 0.00083	No	No	
ASBESTOS-ST15-2/18/08	030804281-0010	South Face - East end at corner (scaffolding level)	2/18/08	1	3.110	Asbestos	PCME	EMSL	2/19/08	< 0.00087	No	No	
ASBESTOS-ST16-2/18/08	030804281-0011	East Face - North end at corner (scaffolding level)	2/18/08	1	3.090	Asbestos	PCME	EMSL	2/19/08	< 0.00080	No	No	
ASBESTOS-ST17-2/18/08	030804281-0012	North Face - West end at corner (scaffolding level)	2/18/08	1	3.010	Asbestos	PCME	EMSL	2/19/08	< 0.00082	No	No	

- Note:
- The reduced volume for asbestos at Station 5 (Firehouse #10 [roof level]) on February 13, 2008 is on account of power failure.
 - The reduced volumes for asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on February 13 and 14, 2008 are on account of power failure.
 - Due to flow rate RPD exceedances (28.6%) at Station 1 (Southwest Area [sidewalk bridge level]) and Station 4 (Northwest Area [street-level]) on February 17, 2008, the sample volumes and subsequent sample results are estimated.