

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-2/25/07	030705950-0001	Southwest Area (sidewalk bridge level)	2/25/07	1	3.040	Asbestos	PCME	EMSL	2/26/07	< 0.00081	No	No	
ASBESTOS-ST2-2/25/07	030705950-0002	Southeast Area (sidewalk bridge level)	2/25/07	1	3.060	Asbestos	PCME	EMSL	2/26/07	< 0.00081	No	No	
ASBESTOS-ST4-2/25/07	030705950-0003	Northwest Area (street-level)	2/25/07	1	3.070	Asbestos	PCME	EMSL	2/26/07	< 0.00080	No	No	
ASBESTOS-ST5-2/25/07	030705950-0004	Firehouse #10 (roof level)	2/25/07	1	3.020	Asbestos	PCME	EMSL	2/26/07	< 0.00082	No	No	
ASBESTOS-ST10-2/25/07	030705950-0005	North Side Sidewalk Bridge	2/25/07	1	2.960	Asbestos	PCME	EMSL	2/26/07	< 0.00083	No	No	
ASBESTOS-ST11-2/25/07	030705950-0006	90 Trinity Place (roof level)	2/25/07	1	3.020	Asbestos	PCME	EMSL	2/26/07	< 0.00082	No	No	
ASBESTOS-ST12-2/25/07	030705950-0007	110 Greenwich Street (roof level)	2/25/07	1	2.970	Asbestos	PCME	EMSL	2/26/07	< 0.00083	No	No	
ASBESTOS-ST13-2/25/07	030705950-0008	Marriott Hotel, 38th Floor (roof level)	2/25/07	1	2.970	Asbestos	PCME	EMSL	2/26/07	< 0.00083	No	No	
ASBESTOS-ST14-2/25/07	030705950-0009	West Face - South end at corner (scaffolding level)	2/25/07	1	3.080	Asbestos	PCME	EMSL	2/26/07	< 0.00080	No	No	
ASBESTOS-ST15-2/25/07	030705950-0010	South Face - East end at corner (scaffolding level)	2/25/07	1	3.010	Asbestos	PCME	EMSL	2/26/07	< 0.00082	No	No	
ASBESTOS-ST16-2/25/07	030705950-0011	East Face - North end at corner (scaffolding level)	2/25/07	1	3.020	Asbestos	PCME	EMSL	2/26/07	< 0.00082	No	No	
ASBESTOS-ST17-2/25/07	030705950-0012	North Face - West end at corner (scaffolding level)	2/25/07	1	3.020	Asbestos	PCME	EMSL	2/26/07	< 0.00082	No	No	
ASBESTOS-ST1-2/26/07	030706104-0001	Southwest Area (sidewalk bridge level)	2/26/07	1	3.060	Asbestos	PCME	EMSL	2/27/07	< 0.00081	No	No	
ASBESTOS-ST2-2/26/07	030706104-0002	Southeast Area (sidewalk bridge level)	2/26/07	1	3.020	Asbestos	PCME	EMSL	2/27/07	< 0.00082	No	No	
ASBESTOS-ST4-2/26/07	030706104-0003	Northwest Area (street-level)	2/26/07	1	3.120	Asbestos	PCME	EMSL	2/27/07	< 0.00079	No	No	
ASBESTOS-ST5-2/26/07	030706104-0004	Firehouse #10 (roof level)	2/26/07	1	3.040	Asbestos	PCME	EMSL	2/27/07	< 0.00081	No	No	
ASBESTOS-ST10-2/26/07	030706104-0005	North Side Sidewalk Bridge	2/26/07	1	2.960	Asbestos	PCME	EMSL	2/27/07	< 0.00083	No	No	
ASBESTOS-ST100-2/26/07	030706104-0013	Station 10 Field Duplicate	2/26/07	1	3.380	Asbestos	PCME	EMSL	2/27/07	< 0.00073	No	No	Note 1
ASBESTOS-ST11-2/26/07	030706104-0006	90 Trinity Place (roof level)	2/26/07	1	3.040	Asbestos	PCME	EMSL	2/27/07	< 0.00081	No	No	
ASBESTOS-ST12-2/26/07	030706104-0007	110 Greenwich Street (roof level)	2/26/07	1	2.950	Asbestos	PCME	EMSL	2/27/07	< 0.00084	No	No	
ASBESTOS-ST13-2/26/07	030706104-0008	Marriott Hotel, 38th Floor (roof level)	2/26/07	1	3.180	Asbestos	PCME	EMSL	2/27/07	< 0.00078	No	No	
ASBESTOS-ST14-2/26/07	030706104-0009	West Face - South end at corner (scaffolding level)	2/26/07	1	3.060	Asbestos	PCME	EMSL	2/27/07	< 0.00081	No	No	
ASBESTOS-ST15-2/26/07	030706104-0010	South Face - East end at corner (scaffolding level)	2/26/07	1	3.000	Asbestos	PCME	EMSL	2/27/07	< 0.00082	No	No	
ASBESTOS-ST16-2/26/07	030706104-0011	East Face - North end at corner (scaffolding level)	2/26/07	1	3.020	Asbestos	PCME	EMSL	2/27/07	< 0.00082	No	No	
ASBESTOS-ST17-2/26/07	030706104-0012	North Face - West end at corner (scaffolding level)	2/26/07	1	3.160	Asbestos	PCME	EMSL	2/27/07	< 0.00078	No	No	
ASBESTOS-ST1-2/27/07	030706253-0001	Southwest Area (sidewalk bridge level)	2/27/07	1	3.010	Asbestos	PCME	EMSL	2/28/07	< 0.00082	No	No	
ASBESTOS-ST2-2/27/07	030706253-0002	Southeast Area (sidewalk bridge level)	2/27/07	1	3.020	Asbestos	PCME	EMSL	2/28/07	< 0.00082	No	No	
ASBESTOS-ST4-2/27/07	030706253-0003	Northwest Area (street-level)	2/27/07	1	3.100	Asbestos	PCME	EMSL	2/28/07	< 0.00080	No	No	
ASBESTOS-ST5-2/27/07	030706253-0004	Firehouse #10 (roof level)	2/27/07	1	2.990	Asbestos	PCME	EMSL	2/28/07	< 0.00083	No	No	
ASBESTOS-ST10-2/27/07	030706253-0005	North Side Sidewalk Bridge	2/27/07	1	3.040	Asbestos	PCME	EMSL	2/28/07	< 0.00081	No	No	
ASBESTOS-ST11-2/27/07	030706253-0006	90 Trinity Place (roof level)	2/27/07	1	3.060	Asbestos	PCME	EMSL	2/28/07	< 0.00081	No	No	
ASBESTOS-ST12-2/27/07	030706253-0007	110 Greenwich Street (roof level)	2/27/07	1	3.020	Asbestos	PCME	EMSL	2/28/07	< 0.00082	No	No	
ASBESTOS-ST13-2/27/07	030706253-0008	Marriott Hotel, 38th Floor (roof level)	2/27/07	1	3.010	Asbestos	PCME	EMSL	2/28/07	< 0.00082	No	No	
ASBESTOS-ST14-2/27/07	030706253-0009	West Face - South end at corner (scaffolding level)	2/27/07	1	3.060	Asbestos	PCME	EMSL	2/28/07	< 0.00081	No	No	
ASBESTOS-ST15-2/27/07	030706253-0010	South Face - East end at corner (scaffolding level)	2/27/07	1	3.040	Asbestos	PCME	EMSL	2/28/07	< 0.00081	No	No	
ASBESTOS-ST16-2/27/07	030706253-0011	East Face - North end at corner (scaffolding level)	2/27/07	1	3.040	Asbestos	PCME	EMSL	2/28/07	< 0.00081	No	No	
ASBESTOS-ST17-2/27/07	030706253-0012	North Face - West end at corner (scaffolding level)	2/27/07	1	3.060	Asbestos	PCME	EMSL	2/28/07	< 0.00081	No	No	

Note:

1. Due to flow rate RPD exceedance (20.9%) for asbestos at Station 100 (Station 10 Field Duplicate) on February 26, 2007, the sample volume and subsequent sample result are estimated.