

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-2/25/09	030905412-0001	Southwest Area (sidewalk bridge level)	2/25/09	1	3.470	Asbestos	PCME	EMSL	2/26/09	< 0.00078	No	No	Note 1
ASBESTOS-ST2-2/25/09	030905412-0002	Southeast Area (sidewalk bridge level)	2/25/09	1	3.460	Asbestos	PCME	EMSL	2/26/09	< 0.00078	No	No	Note 1
ASBESTOS-ST4-2/25/09	030905412-0003	Northwest Area (street-level)	2/25/09	1	3.010	Asbestos	PCME	EMSL	2/26/09	< 0.00082	No	No	
ASBESTOS-ST5-2/25/09	030905412-0004	Firehouse #10 (roof level)	2/25/09	1	3.000	Asbestos	PCME	EMSL	2/26/09	< 0.00082	No	No	
ASBESTOS-ST10-2/25/09	030905412-0005	North Side Sidewalk Bridge	2/25/09	1	3.030	Asbestos	PCME	EMSL	2/26/09	< 0.00081	No	No	
ASBESTOS-ST100-2/25/09	030905412-0013	Station 10 Field Duplicate	2/25/09	1	3.050	Asbestos	PCME	EMSL	2/26/09	< 0.00081	No	No	
ASBESTOS-ST11-2/25/09	030905412-0006	90 Trinity Place (roof level)	2/25/09	1	3.050	Asbestos	PCME	EMSL	2/26/09	< 0.00081	No	No	
ASBESTOS-ST12-2/25/09	030905412-0007	110 Greenwich Street (roof level)	2/25/09	1	3.070	Asbestos	PCME	EMSL	2/26/09	< 0.00080	No	No	
ASBESTOS-ST13-2/25/09	030905412-0008	Marriott Hotel, 38th Floor (roof level)	2/25/09	1	3.050	Asbestos	PCME	EMSL	2/26/09	< 0.00081	No	No	
ASBESTOS-ST14-2/25/09	030905412-0009	West Face - South end at corner (scaffolding level)	2/25/09	1	3.010	Asbestos	PCME	EMSL	2/26/09	< 0.00082	No	No	
ASBESTOS-ST15-2/25/09	030905412-0010	South Face - East end at corner (scaffolding level)	2/25/09	1	2.980	Asbestos	PCME	EMSL	2/26/09	< 0.00083	No	No	
ASBESTOS-ST16-2/25/09	030905412-0011	East Face - North end at corner (scaffolding level)	2/25/09	1	2.920	Asbestos	PCME	EMSL	2/26/09	< 0.00085	No	No	
ASBESTOS-ST17-2/25/09	030905412-0012	North Face - West end at corner (scaffolding level)	2/25/09	1	2.940	Asbestos	PCME	EMSL	2/26/09	< 0.00084	No	No	
ASBESTOS-ST1-2/26/09	030905510-0001	Southwest Area (sidewalk bridge level)	2/26/09	1	2.710	Asbestos	PCME	EMSL	2/27/09	< 0.00084	No	No	
ASBESTOS-ST2-2/26/09	030905510-0002	Southeast Area (sidewalk bridge level)	2/26/09	1	2.800	Asbestos	PCME	EMSL	2/27/09	< 0.00088	No	No	
ASBESTOS-ST4-2/26/09	030905510-0003	Northwest Area (street-level)	2/26/09	1	2.940	Asbestos	PCME	EMSL	2/27/09	< 0.00084	No	No	
ASBESTOS-ST5-2/26/09	030905510-0004	Firehouse #10 (roof level)	2/26/09	1	3.110	Asbestos	PCME	EMSL	2/27/09	< 0.00087	No	No	
ASBESTOS-ST10-2/26/09	030905510-0005	North Side Sidewalk Bridge	2/26/09	1	3.070	Asbestos	PCME	EMSL	2/27/09	< 0.00088	No	No	
ASBESTOS-ST11-2/26/09	030905510-0006	90 Trinity Place (roof level)	2/26/09	1	3.070	Asbestos	PCME	EMSL	2/27/09	< 0.00088	No	No	
ASBESTOS-ST12-2/26/09	030905510-0007	110 Greenwich Street (roof level)	2/26/09	1	2.980	Asbestos	PCME	EMSL	2/27/09	< 0.00083	No	No	
ASBESTOS-ST13-2/26/09	030905510-0008	Marriott Hotel, 38th Floor (roof level)	2/26/09	1	3.030	Asbestos	PCME	EMSL	2/27/09	< 0.00081	No	No	
ASBESTOS-ST14-2/26/09	030905510-0009	West Face - South end at corner (scaffolding level)	2/26/09	1	3.140	Asbestos	PCME	EMSL	2/27/09	< 0.00086	No	No	
ASBESTOS-ST15-2/26/09	030905510-0010	South Face - East end at corner (scaffolding level)	2/26/09	1	3.100	Asbestos	PCME	EMSL	2/27/09	< 0.00080	No	No	
ASBESTOS-ST16-2/26/09	030905510-0011	East Face - North end at corner (scaffolding level)	2/26/09	1	3.190	Asbestos	PCME	EMSL	2/27/09	< 0.00077	No	No	
ASBESTOS-ST17-2/26/09	030905510-0012	North Face - West end at corner (scaffolding level)	2/26/09	1	3.140	Asbestos	PCME	EMSL	2/27/09	< 0.00079	No	No	
ASBESTOS-ST1-2/27/09	030905581-0001	Southwest Area (sidewalk bridge level)	2/27/09	1	3.060	Asbestos	PCME	EMSL	2/28/09	< 0.00081	No	No	
ASBESTOS-ST2-2/27/09	030905581-0002	Southeast Area (sidewalk bridge level)	2/27/09	1	3.000	Asbestos	PCME	EMSL	2/28/09	< 0.00082	No	No	
ASBESTOS-ST4-2/27/09	030905581-0003	Northwest Area (street-level)	2/27/09	1	3.090	Asbestos	PCME	EMSL	2/28/09	< 0.00087	No	No	
ASBESTOS-ST5-2/27/09	030905581-0004	Firehouse #10 (roof level)	2/27/09	1	3.070	Asbestos	PCME	EMSL	2/28/09	< 0.00088	No	No	
ASBESTOS-ST10-2/27/09	030905581-0005	North Side Sidewalk Bridge	2/27/09	1	3.080	Asbestos	PCME	EMSL	2/28/09	< 0.00087	No	No	
ASBESTOS-ST11-2/27/09	030905581-0006	90 Trinity Place (roof level)	2/27/09	1	3.030	Asbestos	PCME	EMSL	2/28/09	< 0.00081	No	No	
ASBESTOS-ST12-2/27/09	030905581-0007	110 Greenwich Street (roof level)	2/27/09	1	2.980	Asbestos	PCME	EMSL	2/28/09	< 0.00083	No	No	
ASBESTOS-ST13-2/27/09	030905581-0008	Marriott Hotel, 38th Floor (roof level)	2/27/09	1	3.050	Asbestos	PCME	EMSL	2/28/09	< 0.00081	No	No	
ASBESTOS-ST14-2/27/09	030905581-0009	West Face - South end at corner (scaffolding level)	2/27/09	1	2.880	Asbestos	PCME	EMSL	2/28/09	< 0.00086	No	No	
ASBESTOS-ST15-2/27/09	030905581-0010	South Face - East end at corner (scaffolding level)	2/27/09	1	2.780	Asbestos	PCME	EMSL	2/28/09	< 0.00089	No	No	
ASBESTOS-ST16-2/27/09	030905581-0011	East Face - North end at corner (scaffolding level)	2/27/09	1	2.900	Asbestos	PCME	EMSL	2/28/09	< 0.00085	No	No	
ASBESTOS-ST17-2/27/09	030905581-0012	North Face - West end at corner (scaffolding level)	2/27/09	1	2.820	Asbestos	PCME	EMSL	2/28/09	< 0.00088	No	No	

Note:

- The asbestos sample volumes at Station 1 (Southwest Area [sidewalk bridge level]) and Station 2 (Southeast Area [sidewalk bridge level]) on February 25, 2009 were slightly elevated because the stations were recovered late due to access issues.