

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-3/7/06	030607126-0001	Southwest Area (sidewalk bridge level)	3/7/06	1	2.970	Asbestos	PCME	EMSL	3/8/06	< 0.00083	No	No	
ASBESTOS-ST2-3/7/06	030607126-0002	Southeast Area (sidewalk bridge level)	3/7/06	1	2.970	Asbestos	PCME	EMSL	3/8/06	< 0.00083	No	No	
ASBESTOS-ST4-3/7/06	030607126-0003	Northwest Area (street-level)	3/7/06	1	2.970	Asbestos	PCME	EMSL	3/8/06	< 0.00083	No	No	
ASBESTOS-ST5-3/7/06	030607126-0004	Firehouse #10 (roof level)	3/7/06	1	2.970	Asbestos	PCME	EMSL	3/8/06	< 0.00083	No	No	
ASBESTOS-ST10-3/7/06	030607126-0005	North Side Sidewalk Bridge	3/7/06	1	2.970	Asbestos	PCME	EMSL	3/8/06	< 0.00083	No	No	
ASBESTOS-ST100-3-7/06	030607126-0013	Station 10 Field Duplicate	3/7/06	1	2.970	Asbestos	PCME	EMSL	3/8/06	< 0.00083	No	No	
ASBESTOS-ST11-3/7/06	030607126-0006	90 Trinity Place (roof level)	3/7/06	1	2.970	Asbestos	PCME	EMSL	3/8/06	< 0.00083	No	No	
ASBESTOS-ST12-3/7/06	030607126-0007	110 Greenwich Street (roof level)	3/7/06	1	2.970	Asbestos	PCME	EMSL	3/8/06	< 0.00083	No	No	
ASBESTOS-ST13-3/7/06	030607126-0008	Marriott Hotel, 38th Floor (roof level)	3/7/06	1	2.970	Asbestos	PCME	EMSL	3/8/06	< 0.00083	No	No	
ASBESTOS-ST14-3/7/06	030607126-0009	West Face - South end at corner (scaffolding level)	3/7/06	1	2.970	Asbestos	PCME	EMSL	3/8/06	< 0.00083	No	No	
ASBESTOS-ST15-3/7/06	030607126-0010	South Face - East end at corner (scaffolding level)	3/7/06	1	2.970	Asbestos	PCME	EMSL	3/8/06	< 0.00083	No	No	
ASBESTOS-ST16-3/7/06	030607126-0011	East Face - North end at corner (scaffolding level)	3/7/06	1	2.970	Asbestos	PCME	EMSL	3/8/06	< 0.00083	No	No	
ASBESTOS-ST17-3/7/06	030607126-0012	North Face - West end at corner (scaffolding level)	3/7/06	1	2.970	Asbestos	PCME	EMSL	3/8/06	< 0.00083	No	No	
ASBESTOS-ST1-3/8/06	030607270-0001	Southwest Area (sidewalk bridge level)	3/8/06	1	2.970	Asbestos	PCME	EMSL	3/9/06	< 0.00083	No	No	
ASBESTOS-ST2-3/8/06	030607270-0002	Southeast Area (sidewalk bridge level)	3/8/06	1	2.970	Asbestos	PCME	EMSL	3/9/06	< 0.00083	No	No	
ASBESTOS-ST4-3/8/06	030607270-0003	Northwest Area (street-level)	3/8/06	1	2.970	Asbestos	PCME	EMSL	3/9/06	< 0.00083	No	No	
ASBESTOS-ST5-3/8/06	030607270-0004	Firehouse #10 (roof level)	3/8/06	1	2.970	Asbestos	PCME	EMSL	3/9/06	< 0.00083	No	No	
ASBESTOS-ST10-3/8/06	030607270-0005	North Side Sidewalk Bridge	3/8/06	1	2.970	Asbestos	PCME	EMSL	3/9/06	< 0.00083	No	No	
ASBESTOS-ST11-3/8/06	030607270-0006	90 Trinity Place (roof level)	3/8/06	1	2.970	Asbestos	PCME	EMSL	3/9/06	< 0.00083	No	No	
ASBESTOS-ST12-3/8/06	030607270-0007	110 Greenwich Street (roof level)	3/8/06	1	2.970	Asbestos	PCME	EMSL	3/9/06	< 0.00083	No	No	
ASBESTOS-ST13-3/8/06	030607270-0008	Marriott Hotel, 38th Floor (roof level)	3/8/06	1	2.970	Asbestos	PCME	EMSL	3/9/06	< 0.00083	No	No	
ASBESTOS-ST14-3/8/06	030607270-0009	West Face - South end at corner (scaffolding level)	3/8/06	1	2.970	Asbestos	PCME	EMSL	3/9/06	< 0.00083	No	No	
ASBESTOS-ST15-3/8/06	030607270-0010	South Face - East end at corner (scaffolding level)	3/8/06	1	2.970	Asbestos	PCME	EMSL	3/9/06	< 0.00083	No	No	
ASBESTOS-ST16-3/8/06	030607270-0011	East Face - North end at corner (scaffolding level)	3/8/06	1	2.970	Asbestos	PCME	EMSL	3/9/06	< 0.00083	No	No	
ASBESTOS-ST17-3/8/06	030607270-0012	North Face - West end at corner (scaffolding level)	3/8/06	1	2.970	Asbestos	PCME	EMSL	3/9/06	< 0.00083	No	No	