

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-3/9/07	030707548-0001	Southwest Area (sidewalk bridge level)	3/9/07	1	2.940	Asbestos	PCME	EMSL	3/12/07	< 0.00084	No	No	
ASBESTOS-ST2-3/9/07	030707548-0002	Southeast Area (sidewalk bridge level)	3/9/07	1	3.040	Asbestos	PCME	EMSL	3/12/07	< 0.00081	No	No	
ASBESTOS-ST4-3/9/07	030707548-0003	Northwest Area (street-level)	3/9/07	1	3.010	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST5-3/9/07	030707548-0004	Firehouse #10 (roof level)	3/9/07	1	3.040	Asbestos	PCME	EMSL	3/12/07	< 0.00081	No	No	
ASBESTOS-ST10-3/9/07	030707548-0005	North Side Sidewalk Bridge	3/9/07	1	3.010	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST11-3/9/07	030707548-0006	90 Trinity Place (roof level)	3/9/07	1	3.020	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST12-3/9/07	030707548-0007	110 Greenwich Street (roof level)	3/9/07	1	2.990	Asbestos	PCME	EMSL	3/12/07	< 0.00083	No	No	
ASBESTOS-ST13-3/9/07	030707548-0008	Marriott Hotel, 38th Floor (roof level)	3/9/07	1	2.880	Asbestos	PCME	EMSL	3/12/07	< 0.00079	No	No	
ASBESTOS-ST14-3/9/07	030707548-0009	West Face - South end at corner (scaffolding level)	3/9/07	1	3.050	Asbestos	PCME	EMSL	3/12/07	< 0.00081	No	No	
ASBESTOS-ST15-3/9/07	030707548-0010	South Face - East end at corner (scaffolding level)	3/9/07	1	2.900	Asbestos	PCME	EMSL	3/12/07	< 0.00079	No	No	
ASBESTOS-ST16-3/9/07	030707548-0011	East Face - North end at corner (scaffolding level)	3/9/07	1	2.970	Asbestos	PCME	EMSL	3/12/07	< 0.00083	No	No	
ASBESTOS-ST17-3/9/07	030707548-0012	North Face - West end at corner (scaffolding level)	3/9/07	1	3.020	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST2-3/10/07	030707549-0001	Southeast Area (sidewalk bridge level)	3/10/07	1	3.020	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST4-3/10/07	030707549-0002	Northwest Area (street-level)	3/10/07	1	3.010	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST5-3/10/07	030707549-0003	Firehouse #10 (roof level)	3/10/07	1	2.930	Asbestos	PCME	EMSL	3/12/07	< 0.00084	No	No	
ASBESTOS-ST10-3/10/07	030707549-0004	North Side Sidewalk Bridge	3/10/07	1	3.010	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST11-3/10/07	030707549-0005	90 Trinity Place (roof level)	3/10/07	1	3.010	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST12-3/10/07	030707549-0006	110 Greenwich Street (roof level)	3/10/07	1	3.020	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST13-3/10/07	030707549-0007	Marriott Hotel, 38th Floor (roof level)	3/10/07	1	3.020	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST14-3/10/07	030707549-0008	West Face - South end at corner (scaffolding level)	3/10/07	1	3.040	Asbestos	PCME	EMSL	3/12/07	< 0.00081	No	No	
ASBESTOS-ST15-3/10/07	030707549-0009	South Face - East end at corner (scaffolding level)	3/10/07	1	2.970	Asbestos	PCME	EMSL	3/12/07	< 0.00083	No	No	
ASBESTOS-ST16-3/10/07	030707549-0010	East Face - North end at corner (scaffolding level)	3/10/07	1	3.040	Asbestos	PCME	EMSL	3/12/07	< 0.00081	No	No	
ASBESTOS-ST17-3/10/07	030707549-0011	North Face - West end at corner (scaffolding level)	3/10/07	1	3.020	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST1-3/11/07	030707547-0001	Southwest Area (sidewalk bridge level)	3/11/07	1	2.970	Asbestos	PCME	EMSL	3/12/07	< 0.00083	No	No	
ASBESTOS-ST2-3/11/07	030707547-0002	Southeast Area (sidewalk bridge level)	3/11/07	1	2.850	Asbestos	PCME	EMSL	3/12/07	< 0.00087	No	No	
ASBESTOS-ST5-3/11/07	030707547-0003	Firehouse #10 (roof level)	3/11/07	1	3.010	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST10-3/11/07	030707547-0004	North Side Sidewalk Bridge	3/11/07	1	3.020	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST11-3/11/07	030707547-0005	90 Trinity Place (roof level)	3/11/07	1	2.850	Asbestos	PCME	EMSL	3/12/07	< 0.00087	No	No	
ASBESTOS-ST12-3/11/07	030707547-0006	110 Greenwich Street (roof level)	3/11/07	1	3.010	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	
ASBESTOS-ST13-3/11/07	030707547-0007	Marriott Hotel, 38th Floor (roof level)	3/11/07	1	3.020	Asbestos	PCME	EMSL	3/12/07	< 0.00082	No	No	

Note:

1. Asbestos sample at Station 1 (Southwest Area [sidewalk bridge level]) on March 10, 2007 was not available for analysis on account of pump failure.
2. Asbestos sample at Station 4 (Northwest Area [street-level]) on March 11, 2007 was not available for analysis on account of pump failure.
3. Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on March 11, 2007 were not available for analysis. These stations were offline for relocation to the 20th floor scaffolding from the 30th floor scaffolding. Electrical service for these relocated stations was made available at 1100 hrs on 3/12/2007.