

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-3/14/07	030707980-0001	Southwest Area (sidewalk bridge level)	3/14/07	1	3.010	Asbestos	PCME	EMSL	3/15/07	< 0.00082	No	No	
ASBESTOS-ST2-3/14/07	030707980-0002	Southeast Area (sidewalk bridge level)	3/14/07	1	3.040	Asbestos	PCME	EMSL	3/15/07	< 0.00081	No	No	
ASBESTOS-ST4-3/14/07	030707980-0003	Northwest Area (street-level)	3/14/07	1	3.020	Asbestos	PCME	EMSL	3/15/07	< 0.00082	No	No	
ASBESTOS-ST5-3/14/07	030707980-0004	Firehouse #10 (roof level)	3/14/07	1	3.020	Asbestos	PCME	EMSL	3/15/07	< 0.00082	No	No	
ASBESTOS-ST10-3/14/07	030707980-0005	North Side Sidewalk Bridge	3/14/07	1	3.190	Asbestos	PCME	EMSL	3/15/07	< 0.00077	No	No	
ASBESTOS-ST100-3/14/07	030707980-0013	Station 10 Field Duplicate	3/14/07	1	3.280	Asbestos	PCME	EMSL	3/15/07	< 0.00075	No	No	
ASBESTOS-ST11-3/14/07	030707980-0006	90 Trinity Place (roof level)	3/14/07	1	3.030	Asbestos	PCME	EMSL	3/15/07	< 0.00081	No	No	
ASBESTOS-ST12-3/14/07	030707980-0007	110 Greenwich Street (roof level)	3/14/07	1	3.010	Asbestos	PCME	EMSL	3/15/07	< 0.00082	No	No	
ASBESTOS-ST13-3/14/07	030707980-0008	Marriott Hotel, 38th Floor (roof level)	3/14/07	1	3.020	Asbestos	PCME	EMSL	3/15/07	< 0.00082	No	No	
ASBESTOS-ST14-3/14/07	030707980-0009	West Face - South end at corner (scaffolding level)	3/14/07	1	3.000	Asbestos	PCME	EMSL	3/15/07	< 0.00082	No	No	
ASBESTOS-ST15-3/14/07	030707980-0010	South Face - East end at corner (scaffolding level)	3/14/07	1	3.010	Asbestos	PCME	EMSL	3/15/07	< 0.00082	No	No	
ASBESTOS-ST16-3/14/07	030707980-0011	East Face - North end at corner (scaffolding level)	3/14/07	1	3.020	Asbestos	PCME	EMSL	3/15/07	< 0.00082	No	No	
ASBESTOS-ST17-3/14/07	030707980-0012	North Face - West end at corner (scaffolding level)	3/14/07	1	3.010	Asbestos	PCME	EMSL	3/15/07	< 0.00082	No	No	
ASBESTOS-ST1-3/15/07	030708108-0001	Southwest Area (sidewalk bridge level)	3/15/07	1	3.060	Asbestos	PCME	EMSL	3/16/07	< 0.00081	No	No	
ASBESTOS-ST2-3/15/07	030708108-0002	Southeast Area (sidewalk bridge level)	3/15/07	1	3.060	Asbestos	PCME	EMSL	3/16/07	< 0.00081	No	No	
ASBESTOS-ST4-3/15/07	030708108-0003	Northwest Area (street-level)	3/15/07	1	2.940	Asbestos	PCME	EMSL	3/16/07	< 0.00084	No	No	
ASBESTOS-ST5-3/15/07	030708108-0004	Firehouse #10 (roof level)	3/15/07	1	3.020	Asbestos	PCME	EMSL	3/16/07	< 0.00082	No	No	
ASBESTOS-ST10-3/15/07	030708108-0005	North Side Sidewalk Bridge	3/15/07	1	2.920	Asbestos	PCME	EMSL	3/16/07	< 0.00085	No	No	
ASBESTOS-ST100-3/15/07	030708108-0013	Station 10 Field Duplicate	3/15/07	1	3.090	Asbestos	PCME	EMSL	3/16/07	< 0.00080	No	No	
ASBESTOS-ST11-3/15/07	030708108-0006	90 Trinity Place (roof level)	3/15/07	1	3.120	Asbestos	PCME	EMSL	3/16/07	< 0.00079	No	No	
ASBESTOS-ST12-3/15/07	030708108-0007	110 Greenwich Street (roof level)	3/15/07	1	2.890	Asbestos	PCME	EMSL	3/16/07	0.00085	No	No	
ASBESTOS-ST13-3/15/07	030708108-0008	Marriott Hotel, 38th Floor (roof level)	3/15/07	1	3.020	Asbestos	PCME	EMSL	3/16/07	< 0.00082	No	No	
ASBESTOS-ST14-3/15/07	030708108-0009	West Face - South end at corner (scaffolding level)	3/15/07	1	3.010	Asbestos	PCME	EMSL	3/16/07	< 0.00082	No	No	
ASBESTOS-ST15-3/15/07	030708108-0010	South Face - East end at corner (scaffolding level)	3/15/07	1	3.020	Asbestos	PCME	EMSL	3/16/07	< 0.00082	No	No	
ASBESTOS-ST16-3/15/07	030708108-0011	East Face - North end at corner (scaffolding level)	3/15/07	1	3.010	Asbestos	PCME	EMSL	3/16/07	< 0.00082	No	No	
ASBESTOS-ST17-3/15/07	030708108-0012	North Face - West end at corner (scaffolding level)	3/15/07	1	3.020	Asbestos	PCME	EMSL	3/16/07	< 0.00082	No	No	