

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-3/17/06	030608497-0001	Southwest Area (sidewalk bridge level)	3/17/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST2-3/17/06	030608497-0002	Southeast Area (sidewalk bridge level)	3/17/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST4-3/17/06	030608497-0003	Northwest Area (street-level)	3/17/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST5-3/17/06	030608497-0004	Firehouse #10 (roof level)	3/17/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST10-3/17/06	030608497-0005	North Side Sidewalk Bridge	3/17/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST100-3/17/06	030608497-0013	Station 10 Field Duplicate	3/17/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST11-3/17/06	030608497-0006	90 Trinity Place (roof level)	3/17/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST12-3/17/06	030608497-0007	110 Greenwich Street (roof level)	3/17/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST13-3/17/06	030608497-0008	Marriott Hotel, 38th Floor (roof level)	3/17/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST14-3/17/06	030608497-0009	West Face - South end at corner (scaffolding level)	3/17/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST15-3/17/06	030608497-0010	South Face - East end at corner (scaffolding level)	3/17/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST16-3/17/06	030608497-0011	East Face - North end at corner (scaffolding level)	3/17/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST17-3/17/06	030608497-0012	North Face - West end at corner (scaffolding level)	3/17/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST1-3/18/06	030608494-0001	Southwest Area (sidewalk bridge level)	3/18/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST2-3/18/06	030608494-0002	Southeast Area (sidewalk bridge level)	3/18/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST4-3/18/06	030608494-0003	Northwest Area (street-level)	3/18/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST5-3/18/06	030608494-0004	Firehouse #10 (roof level)	3/18/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST10-3/18/06	030608494-0005	North Side Sidewalk Bridge	3/18/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST11-3/18/06	030608494-0006	90 Trinity Place (roof level)	3/18/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST12-3/18/06	030608494-0007	110 Greenwich Street (roof level)	3/18/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST13-3/18/06	030608494-0008	Marriott Hotel, 38th Floor (roof level)	3/18/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST14-3/18/06	030608494-0009	West Face - South end at corner (scaffolding level)	3/18/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST15-3/18/06	030608494-0010	South Face - East end at corner (scaffolding level)	3/18/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST16-3/18/06	030608494-0011	East Face - North end at corner (scaffolding level)	3/18/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST17-3/18/06	030608494-0012	North Face - West end at corner (scaffolding level)	3/18/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST1-3/19/06	030608495-0001	Southwest Area (sidewalk bridge level)	3/19/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST2-3/19/06	030608495-0002	Southeast Area (sidewalk bridge level)	3/19/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST4-3/19/06	030608495-0003	Northwest Area (street-level)	3/19/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST5-3/19/06	030608495-0004	Firehouse #10 (roof level)	3/19/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST10-3/19/06	030608495-0005	North Side Sidewalk Bridge	3/19/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST11-3/19/06	030608495-0006	90 Trinity Place (roof level)	3/19/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST12-3/19/06	030608495-0007	110 Greenwich Street (roof level)	3/19/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST13-3/19/06	030608495-0008	Marriott Hotel, 38th Floor (roof level)	3/19/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST14-3/19/06	030608495-0009	West Face - South end at corner (scaffolding level)	3/19/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST15-3/19/06	030608495-0010	South Face - East end at corner (scaffolding level)	3/19/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST16-3/19/06	030608495-0011	East Face - North end at corner (scaffolding level)	3/19/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	
ASBESTOS-ST17-3/19/06	030608495-0012	North Face - West end at corner (scaffolding level)	3/19/06	1	3.000	Asbestos	PCME	EMSL	3/20/06	< 0.00082	No	No	