

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-3/17/08	030807386-0001	Southwest Area (sidewalk bridge level)	3/17/08	1	3.060	Asbestos	PCME	EMSL	3/18/08	< 0.00081	No	No	
ASBESTOS-ST2-3/17/08	030807386-0002	Southeast Area (sidewalk bridge level)	3/17/08	1	3.040	Asbestos	PCME	EMSL	3/18/08	< 0.00081	No	No	
ASBESTOS-ST4-3/17/08	030807386-0003	Northwest Area (street-level)	3/17/08	1	3.180	Asbestos	PCME	EMSL	3/18/08	< 0.00078	No	No	
ASBESTOS-ST5-3/17/08	030807386-0004	Firehouse #10 (roof level)	3/17/08	1	3.070	Asbestos	PCME	EMSL	3/18/08	< 0.00080	No	No	
ASBESTOS-ST10-3/17/08	030807386-0005	North Side Sidewalk Bridge	3/17/08	1	3.170	Asbestos	PCME	EMSL	3/18/08	< 0.00078	No	No	
ASBESTOS-ST11-3/17/08	030807386-0006	90 Trinity Place (roof level)	3/17/08	1	3.000	Asbestos	PCME	EMSL	3/18/08	< 0.00082	No	No	
ASBESTOS-ST12-3/17/08	030807386-0007	110 Greenwich Street (roof level)	3/17/08	1	3.070	Asbestos	PCME	EMSL	3/18/08	< 0.00080	No	No	
ASBESTOS-ST13-3/17/08	030807386-0008	Marriott Hotel, 38th Floor (roof level)	3/17/08	1	2.960	Asbestos	PCME	EMSL	3/18/08	< 0.00083	No	No	
ASBESTOS-ST14-3/17/08	030807386-0009	West Face - South end at corner (scaffolding level)	3/17/08	1	2.990	Asbestos	PCME	EMSL	3/18/08	< 0.00083	No	No	
ASBESTOS-ST15-3/17/08	030807386-0010	South Face - East end at corner (scaffolding level)	3/17/08	1	3.140	Asbestos	PCME	EMSL	3/18/08	< 0.00079	No	No	
ASBESTOS-ST16-3/17/08	030807386-0011	East Face - North end at corner (scaffolding level)	3/17/08	1	3.100	Asbestos	PCME	EMSL	3/18/08	< 0.00080	No	No	
ASBESTOS-ST17-3/17/08	030807386-0012	North Face - West end at corner (scaffolding level)	3/17/08	1	3.040	Asbestos	PCME	EMSL	3/18/08	< 0.00081	No	No	
ASBESTOS-ST1-3/18/08	030807496-0001	Southwest Area (sidewalk bridge level)	3/18/08	1	2.930	Asbestos	PCME	EMSL	3/19/08	< 0.00084	No	No	
ASBESTOS-ST2-3/18/08	030807496-0002	Southeast Area (sidewalk bridge level)	3/18/08	1	3.040	Asbestos	PCME	EMSL	3/19/08	< 0.00081	No	No	
ASBESTOS-ST4-3/18/08	030807496-0003	Northwest Area (street-level)	3/18/08	1	3.250	Asbestos	PCME	EMSL	3/19/08	< 0.00083	No	No	
ASBESTOS-ST5-3/18/08	030807496-0004	Firehouse #10 (roof level)	3/18/08	1	3.140	Asbestos	PCME	EMSL	3/19/08	< 0.00086	No	No	
ASBESTOS-ST10-3/18/08	030807496-0005	North Side Sidewalk Bridge	3/18/08	1	2.960	Asbestos	PCME	EMSL	3/19/08	< 0.00083	No	No	
ASBESTOS-ST11-3/18/08	030807496-0006	90 Trinity Place (roof level)	3/18/08	1	3.040	Asbestos	PCME	EMSL	3/19/08	< 0.00089	No	No	
ASBESTOS-ST12-3/18/08	030807496-0007	110 Greenwich Street (roof level)	3/18/08	1	3.050	Asbestos	PCME	EMSL	3/19/08	< 0.00088	No	No	
ASBESTOS-ST13-3/18/08	030807496-0008	Marriott Hotel, 38th Floor (roof level)	3/18/08	1	3.010	Asbestos	PCME	EMSL	3/19/08	< 0.00082	No	No	
ASBESTOS-ST14-3/18/08	030807496-0009	West Face - South end at corner (scaffolding level)	3/18/08	1	2.980	Asbestos	PCME	EMSL	3/19/08	< 0.00083	No	No	
ASBESTOS-ST15-3/18/08	030807496-0010	South Face - East end at corner (scaffolding level)	3/18/08	1	3.020	Asbestos	PCME	EMSL	3/19/08	< 0.00082	No	No	
ASBESTOS-ST16-3/18/08	030807496-0011	East Face - North end at corner (scaffolding level)	3/18/08	1	3.040	Asbestos	PCME	EMSL	3/19/08	< 0.00089	No	No	
ASBESTOS-ST17-3/18/08	030807496-0012	North Face - West end at corner (scaffolding level)	3/18/08	1	3.070	Asbestos	PCME	EMSL	3/19/08	< 0.00088	No	No	
ASBESTOS-ST1-3/19/08	030807653-0001	Southwest Area (sidewalk bridge level)	3/19/08	1	3.090	Asbestos	PCME	EMSL	3/20/08	< 0.00080	No	No	
ASBESTOS-ST2-3/19/08	030807653-0002	Southeast Area (sidewalk bridge level)	3/19/08	1	3.110	Asbestos	PCME	EMSL	3/20/08	< 0.00079	No	No	
ASBESTOS-ST4-3/19/08	030807653-0003	Northwest Area (street-level)	3/19/08	1	3.300	Asbestos	PCME	EMSL	3/20/08	< 0.00075	No	No	
ASBESTOS-ST5-3/19/08	030807653-0004	Firehouse #10 (roof level)	3/19/08	1	3.190	Asbestos	PCME	EMSL	3/20/08	< 0.00077	No	No	
ASBESTOS-ST10-3/19/08	030807653-0005	North Side Sidewalk Bridge	3/19/08	1	3.340	Asbestos	PCME	EMSL	3/20/08	< 0.00074	No	No	
ASBESTOS-ST11-3/19/08	030807653-0006	90 Trinity Place (roof level)	3/19/08	1	3.040	Asbestos	PCME	EMSL	3/20/08	< 0.00089	No	No	
ASBESTOS-ST12-3/19/08	030807653-0007	110 Greenwich Street (roof level)	3/19/08	1	3.080	Asbestos	PCME	EMSL	3/20/08	< 0.00087	No	No	
ASBESTOS-ST13-3/19/08	030807653-0008	Marriott Hotel, 38th Floor (roof level)	3/19/08	1	2.990	Asbestos	PCME	EMSL	3/20/08	< 0.00083	No	No	
ASBESTOS-ST14-3/19/08	030807653-0009	West Face - South end at corner (scaffolding level)	3/19/08	1	2.990	Asbestos	PCME	EMSL	3/20/08	< 0.00083	No	No	
ASBESTOS-ST15-3/19/08	030807653-0010	South Face - East end at corner (scaffolding level)	3/19/08	1	3.070	Asbestos	PCME	EMSL	3/20/08	< 0.00088	No	No	
ASBESTOS-ST16-3/19/08	030807653-0011	East Face - North end at corner (scaffolding level)	3/19/08	1	3.090	Asbestos	PCME	EMSL	3/20/08	< 0.00087	No	No	
ASBESTOS-ST17-3/19/08	030807653-0012	North Face - West end at corner (scaffolding level)	3/19/08	1	3.070	Asbestos	PCME	EMSL	3/20/08	< 0.00088	No	No	