

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-3/20/08	030807872-0001	Southwest Area (sidewalk bridge level)	3/20/08	1	3.060	Asbestos	PCME	EMSL	3/21/08	< 0.00081	No	No	
ASBESTOS-ST2-3/20/08	030807872-0002	Southeast Area (sidewalk bridge level)	3/20/08	1	3.020	Asbestos	PCME	EMSL	3/21/08	< 0.00082	No	No	
ASBESTOS-ST4-3/20/08	030807872-0003	Northwest Area (street-level)	3/20/08	1	3.190	Asbestos	PCME	EMSL	3/21/08	< 0.00077	No	No	
ASBESTOS-ST5-3/20/08	030807872-0004	Firehouse #10 (roof level)	3/20/08	1	3.040	Asbestos	PCME	EMSL	3/21/08	< 0.00081	No	No	
ASBESTOS-ST10-3/20/08	030807872-0005	North Side Sidewalk Bridge	3/20/08	1	3.110	Asbestos	PCME	EMSL	3/21/08	< 0.00079	No	No	
ASBESTOS-ST100-3/20/08	030807872-0013	Station 10 Field Duplicate	3/20/08	1	3.060	Asbestos	PCME	EMSL	3/21/08	< 0.00081	No	No	
ASBESTOS-ST11-3/20/08	030807872-0006	90 Trinity Place (roof level)	3/20/08	1	3.070	Asbestos	PCME	EMSL	3/21/08	< 0.00080	No	No	
ASBESTOS-ST12-3/20/08	030807872-0007	110 Greenwich Street (roof level)	3/20/08	1	3.090	Asbestos	PCME	EMSL	3/21/08	< 0.00080	No	No	
ASBESTOS-ST13-3/20/08	030807872-0008	Marriott Hotel, 38th Floor (roof level)	3/20/08	1	3.030	Asbestos	PCME	EMSL	3/21/08	< 0.00081	No	No	
ASBESTOS-ST14-3/20/08	030807872-0009	West Face - South end at corner (scaffolding level)	3/20/08	1	3.040	Asbestos	PCME	EMSL	3/21/08	< 0.00081	No	No	
ASBESTOS-ST15-3/20/08	030807872-0010	South Face - East end at corner (scaffolding level)	3/20/08	1	2.980	Asbestos	PCME	EMSL	3/21/08	< 0.00083	No	No	
ASBESTOS-ST16-3/20/08	030807872-0011	East Face - North end at corner (scaffolding level)	3/20/08	1	3.070	Asbestos	PCME	EMSL	3/21/08	< 0.00080	No	No	
ASBESTOS-ST17-3/20/08	030807872-0012	North Face - West end at corner (scaffolding level)	3/20/08	1	3.060	Asbestos	PCME	EMSL	3/21/08	< 0.00081	No	No	
ASBESTOS-ST1-3/21/08	030807989-0001	Southwest Area (sidewalk bridge level)	3/21/08	1	3.410	Asbestos	PCME	EMSL	3/22/08	< 0.00079	No	No	Note 1
ASBESTOS-ST2-3/21/08	030807989-0002	Southeast Area (sidewalk bridge level)	3/21/08	1	3.130	Asbestos	PCME	EMSL	3/22/08	< 0.00086	No	No	
ASBESTOS-ST4-3/21/08	030807989-0003	Northwest Area (street-level)	3/21/08	1	3.010	Asbestos	PCME	EMSL	3/22/08	< 0.00082	No	No	
ASBESTOS-ST5-3/21/08	030807989-0004	Firehouse #10 (roof level)	3/21/08	1	3.140	Asbestos	PCME	EMSL	3/22/08	< 0.00086	No	No	
ASBESTOS-ST10-3/21/08	030807989-0005	North Side Sidewalk Bridge	3/21/08	1	3.070	Asbestos	PCME	EMSL	3/22/08	< 0.00080	No	No	
ASBESTOS-ST11-3/21/08	030807989-0006	90 Trinity Place (roof level)	3/21/08	1	3.070	Asbestos	PCME	EMSL	3/22/08	< 0.00080	No	No	
ASBESTOS-ST12-3/21/08	030807989-0007	110 Greenwich Street (roof level)	3/21/08	1	3.070	Asbestos	PCME	EMSL	3/22/08	< 0.00080	No	No	
ASBESTOS-ST13-3/21/08	030807989-0008	Marriott Hotel, 38th Floor (roof level)	3/21/08	1	3.000	Asbestos	PCME	EMSL	3/22/08	< 0.00082	No	No	
ASBESTOS-ST14-3/21/08	030807989-0009	West Face - South end at corner (scaffolding level)	3/21/08	1	3.050	Asbestos	PCME	EMSL	3/22/08	< 0.00081	No	No	
ASBESTOS-ST15-3/21/08	030807989-0010	South Face - East end at corner (scaffolding level)	3/21/08	1	3.060	Asbestos	PCME	EMSL	3/22/08	< 0.00081	No	No	
ASBESTOS-ST16-3/21/08	030807989-0011	East Face - North end at corner (scaffolding level)	3/21/08	1	3.010	Asbestos	PCME	EMSL	3/22/08	< 0.00082	No	No	
ASBESTOS-ST17-3/21/08	030807989-0012	North Face - West end at corner (scaffolding level)	3/21/08	1	2.990	Asbestos	PCME	EMSL	3/22/08	< 0.00083	No	No	
ASBESTOS-ST1-3/22/08	030808134-0001	Southwest Area (sidewalk bridge level)	3/22/08	1	2.870	Asbestos	PCME	EMSL	3/24/08	< 0.00086	No	No	
ASBESTOS-ST2-3/22/08	030808134-0002	Southeast Area (sidewalk bridge level)	3/22/08	1	3.040	Asbestos	PCME	EMSL	3/24/08	< 0.00081	No	No	
ASBESTOS-ST4-3/22/08	030808134-0003	Northwest Area (street-level)	3/22/08	1	3.090	Asbestos	PCME	EMSL	3/24/08	< 0.00080	No	No	
ASBESTOS-ST5-3/22/08	030808134-0004	Firehouse #10 (roof level)	3/22/08	1	3.100	Asbestos	PCME	EMSL	3/24/08	< 0.00080	No	No	
ASBESTOS-ST10-3/22/08	030808134-0005	North Side Sidewalk Bridge	3/22/08	1	3.180	Asbestos	PCME	EMSL	3/24/08	< 0.00078	No	No	
ASBESTOS-ST11-3/22/08	030808134-0006	90 Trinity Place (roof level)	3/22/08	1	3.010	Asbestos	PCME	EMSL	3/24/08	< 0.00082	No	No	
ASBESTOS-ST12-3/22/08	030808134-0007	110 Greenwich Street (roof level)	3/22/08	1	3.050	Asbestos	PCME	EMSL	3/24/08	< 0.00081	No	No	
ASBESTOS-ST13-3/22/08	030808134-0008	Marriott Hotel, 38th Floor (roof level)	3/22/08	1	3.020	Asbestos	PCME	EMSL	3/24/08	< 0.00082	No	No	
ASBESTOS-ST14-3/22/08	030808134-0009	West Face - South end at corner (scaffolding level)	3/22/08	1	3.060	Asbestos	PCME	EMSL	3/24/08	< 0.00081	No	No	
ASBESTOS-ST15-3/22/08	030808134-0010	South Face - East end at corner (scaffolding level)	3/22/08	1	3.090	Asbestos	PCME	EMSL	3/24/08	< 0.00080	No	No	
ASBESTOS-ST16-3/22/08	030808134-0011	East Face - North end at corner (scaffolding level)	3/22/08	1	3.010	Asbestos	PCME	EMSL	3/24/08	< 0.00082	No	No	
ASBESTOS-ST17-3/22/08	030808134-0012	North Face - West end at corner (scaffolding level)	3/22/08	1	2.950	Asbestos	PCME	EMSL	3/24/08	< 0.00084	No	No	

Note:

1. Due to a flow rate RPD exceedance (22.3%) for asbestos at Station 1 (Southwest Area [sidewalk bridge level]) on March 21, 2008, the sample volume and subsequent sample result are estimated.