

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality	Site Specific	
										NA	Levels	Trigger Levels	
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-3/25/09	030907821-0001	Southwest Area (sidewalk bridge level)	3/25/09	1	3.130	Asbestos	PCME	EMSL	3/26/09	< 0.00086	No	No	
ASBESTOS-ST2-3/25/09	030907821-0002	Southeast Area (sidewalk bridge level)	3/25/09	1	3.070	Asbestos	PCME	EMSL	3/26/09	< 0.00080	No	No	
ASBESTOS-ST4-3/25/09	030907821-0003	Northwest Area (street-level)	3/25/09	1	2.990	Asbestos	PCME	EMSL	3/26/09	< 0.00083	No	No	
ASBESTOS-ST5-3/25/09	030907821-0004	Firehouse #10 (roof level)	3/25/09	1	3.050	Asbestos	PCME	EMSL	3/26/09	< 0.00081	No	No	
ASBESTOS-ST10-3/25/09	030907821-0005	North Side Sidewalk Bridge	3/25/09	1	3.150	Asbestos	PCME	EMSL	3/26/09	< 0.00078	No	No	
ASBESTOS-ST11-3/25/09	030907821-0006	90 Trinity Place (roof level)	3/25/09	1	3.040	Asbestos	PCME	EMSL	3/26/09	< 0.00081	No	No	
ASBESTOS-ST12-3/25/09	030907821-0007	110 Greenwich Street (roof level)	3/25/09	1	3.040	Asbestos	PCME	EMSL	3/26/09	< 0.00081	No	No	
ASBESTOS-ST13-3/25/09	030907821-0008	Marriott Hotel, 38th Floor (roof level)	3/25/09	1	2.980	Asbestos	PCME	EMSL	3/26/09	< 0.00083	No	No	
ASBESTOS-ST14-3/25/09	030907821-0009	West Face - South end at corner (scaffolding level)	3/25/09	1	3.110	Asbestos	PCME	EMSL	3/26/09	< 0.00079	No	No	
ASBESTOS-ST15-3/25/09	030907821-0010	South Face - East end at corner (scaffolding level)	3/25/09	1	2.990	Asbestos	PCME	EMSL	3/26/09	< 0.00083	No	No	
ASBESTOS-ST16-3/25/09	030907821-0011	East Face - North end at corner (scaffolding level)	3/25/09	1	3.060	Asbestos	PCME	EMSL	3/26/09	< 0.00081	No	No	
ASBESTOS-ST17-3/25/09	030907821-0012	North Face - West end at corner (scaffolding level)	3/25/09	1	2.960	Asbestos	PCME	EMSL	3/26/09	< 0.00083	No	No	
ASBESTOS-ST1-3/26/09	030907896-0001	Southwest Area (sidewalk bridge level)	3/26/09	1	3.070	Asbestos	PCME	EMSL	3/27/09	< 0.00088	No	No	
ASBESTOS-ST2-3/26/09	030907896-0002	Southeast Area (sidewalk bridge level)	3/26/09	1	3.070	Asbestos	PCME	EMSL	3/27/09	< 0.00088	No	No	
ASBESTOS-ST4-3/26/09	030907896-0003	Northwest Area (street-level)	3/26/09	1	3.050	Asbestos	PCME	EMSL	3/27/09	< 0.00081	No	No	
ASBESTOS-ST5-3/26/09	030907896-0004	Firehouse #10 (roof level)	3/26/09	1	2.950	Asbestos	PCME	EMSL	3/27/09	< 0.00084	No	No	
ASBESTOS-ST10-3/26/09	030907896-0005	North Side Sidewalk Bridge	3/26/09	1	2.940	Asbestos	PCME	EMSL	3/27/09	< 0.00084	No	No	
ASBESTOS-ST11-3/26/09	030907896-0006	90 Trinity Place (roof level)	3/26/09	1	2.980	Asbestos	PCME	EMSL	3/27/09	< 0.00083	No	No	
ASBESTOS-ST12-3/26/09	030907896-0007	110 Greenwich Street (roof level)	3/26/09	1	3.010	Asbestos	PCME	EMSL	3/27/09	< 0.00082	No	No	
ASBESTOS-ST13-3/26/09	030907896-0008	Marriott Hotel, 38th Floor (roof level)	3/26/09	1	3.000	Asbestos	PCME	EMSL	3/27/09	< 0.00082	No	No	
ASBESTOS-ST14-3/26/09	030907896-0009	West Face - South end at corner (scaffolding level)	3/26/09	1	3.080	Asbestos	PCME	EMSL	3/27/09	< 0.00087	No	No	
ASBESTOS-ST15-3/26/09	030907896-0010	South Face - East end at corner (scaffolding level)	3/26/09	1	3.060	Asbestos	PCME	EMSL	3/27/09	< 0.00081	No	No	
ASBESTOS-ST16-3/26/09	030907896-0011	East Face - North end at corner (scaffolding level)	3/26/09	1	2.980	Asbestos	PCME	EMSL	3/27/09	< 0.00083	No	No	
ASBESTOS-ST17-3/26/09	030907896-0012	North Face - West end at corner (scaffolding level)	3/26/09	1	3.130	Asbestos	PCME	EMSL	3/27/09	< 0.00086	No	No	
ASBESTOS-ST1-3/27/09	030907962-0001	Southwest Area (sidewalk bridge level)	3/27/09	1	3.060	Asbestos	PCME	EMSL	3/28/09	< 0.00081	No	No	
ASBESTOS-ST2-3/27/09	030907962-0002	Southeast Area (sidewalk bridge level)	3/27/09	1	3.080	Asbestos	PCME	EMSL	3/28/09	< 0.00087	No	No	
ASBESTOS-ST4-3/27/09	030907962-0003	Northwest Area (street-level)	3/27/09	1	3.010	Asbestos	PCME	EMSL	3/28/09	< 0.00082	No	No	
ASBESTOS-ST5-3/27/09	030907962-0004	Firehouse #10 (roof level)	3/27/09	1	3.070	Asbestos	PCME	EMSL	3/28/09	< 0.00088	No	No	
ASBESTOS-ST10-3/27/09	030907962-0005	North Side Sidewalk Bridge	3/27/09	1	3.120	Asbestos	PCME	EMSL	3/28/09	< 0.00086	No	No	
ASBESTOS-ST11-3/27/09	030907962-0006	90 Trinity Place (roof level)	3/27/09	1	2.980	Asbestos	PCME	EMSL	3/28/09	< 0.00083	No	No	
ASBESTOS-ST12-3/27/09	030907962-0007	110 Greenwich Street (roof level)	3/27/09	1	3.070	Asbestos	PCME	EMSL	3/28/09	< 0.00088	No	No	
ASBESTOS-ST13-3/27/09	030907962-0008	Marriott Hotel, 38th Floor (roof level)	3/27/09	1	3.090	Asbestos	PCME	EMSL	3/28/09	< 0.00087	No	No	
ASBESTOS-ST14-3/27/09	030907962-0009	West Face - South end at corner (scaffolding level)	3/27/09	1	2.900	Asbestos	PCME	EMSL	3/28/09	< 0.00085	No	No	
ASBESTOS-ST15-3/27/09	030907962-0010	South Face - East end at corner (scaffolding level)	3/27/09	1	2.950	Asbestos	PCME	EMSL	3/28/09	< 0.00084	No	No	
ASBESTOS-ST16-3/27/09	030907962-0011	East Face - North end at corner (scaffolding level)	3/27/09	1	3.000	Asbestos	PCME	EMSL	3/28/09	< 0.00082	No	No	
ASBESTOS-ST17-3/27/09	030907962-0012	North Face - West end at corner (scaffolding level)	3/27/09	1	2.890	Asbestos	PCME	EMSL	3/28/09	< 0.00085	No	No	